



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/05/2026

Incharge(s): M Kailash

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	reported red. OLR acted	Reset done	14:30:00	14:40:00	
2	OHP	BRC on CO-8A	Reported B/W not running.	Found oil leaking. Informed to Mechanical	14:45:00	15:00:00	
3	OHP	CO-26	Reported red. OLR acted	Reset done	18:05:00 21:00:00	18:10:00 21:15:00	
4	CHP	CC-31	UNHEALTHY	found MPR tripped. Reset done	14:55:00	15:00:00	
5	CHP	CC-58 TT	position bit missing in PLC.	Bypassed in I/O rack and checked. Cable to be checked for any damage.	19:35:00	20:00:00	Kept in Bypass
6	CHP	CC-52	unhealthy. MPR tripped on overload	Reset done	17:50:00	17:55:00	
7	CHP	CC-28	Unhealthy. OLR acted	Reset done	15:05:00	15:10:00	
8	CHP	CC-8	ZSS acted	Found ZSS cage stuck due to stone. Cage made free	15:25:00	15:35:00	
9	IOSA	OC-14A	Unhealthy. Found in Alarms, Pullcord Right -Rear acted.	Bypassed hardware contact and software contact. After Rake completion, bypass removed. Found loose contact in one pullcord.	14:05:00 15:20:00	15:05:00 15:35:00	