वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 16/10/2026

Shift: B

Incharge(s): G Eswara Rao

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | CO 24 | BRS WAS IN BYPASSED | KEPT IN CKT | 17:00:00 | 17:10:00 | |
| 2 | OHP | TBS ON CO 21 | BC NOT RUNNING/OLR ACTED DUE TO JAMMING | RESET DONE | 17:25:00 | 17:40:00 | |
| 3 | OHP | CO 25 | TRIPPED ON OLR | RESET DONE | 17:20:00<br>19:00:00 | 17:35:00<br>19:10:00 | |
| 4 | OHP | BRC ON CO 31 | BC NOT RUNNING/OLR ACTED | RESET DONE | 20:05:00 | 20:20:00 | |
| 5 | OHP | CO 29 | TRIPPED ON OLR | RESET DONE | 20:25:00 | 20:30:00 | |
| 6 | CHP | scr on cc40 | bc not running/mpd tripped on e207 fault | reset done | 16:25:00 | 16:35:00 | |
| 7 | CHP | SCR 1 ON CC31 | LUFFING NOT TAKING PLACE/DOWN LIMIT ACTED | BYPASSED FOR OPERATION REQUIREMENT AGAIN KEPT IN CKT | 17:40:00<br>17:40:00 | 17:50:00<br>21:00:00 | |
| 8 | CHP | CC 107 | BSS RF ACTED/NOT GETTING RESET | BYPASSED AT PLC | 19:10:00 | 19:20:00 | |
| 9 | CHP | CC 131 | TRIPPED ON OLR | RESET DONE | 20:05:00 | 20:10:00 | |