



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/07/2026

Shift: B

Incharge(s): Amit Roy,Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT-3 on BPC-1	Reported indication not coming	Fuse burnt.Replaced and tested okay	16:20:00	16:30:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	19:35:00	19:45:00	
3	OHP	TBS on CO-22	Reported right luff not taking place	Checked and found mechanical brake tight.Adjusted and tested okay	19:35:00	19:50:00	
4	OHP	CO-9A,12A, 3A	Reported not healthy	IC-2 tripped on under voltage fault in 1-28HVMCC-4. Bus coupler made on and given clearance	20:35:00	20:45:00	I/C-2 charged in 1-2LBDS-8
5	OHP	Cc-58	Reported tripped	OLR acted.Reset done	17:40:00	17:55:00	
6	CHP	CC-38 SCR-6	BC not running	OLR acted.Reset done	20:45:00	21:00:00	
7	WT	OT-1	Reported not rotating in reverse	Joystick kept in neutral and again command given and tested okay	19:00:00	19:15:00	
8	WT	OP-5	Reported not moving	Checked and found emergency acted at dead end.Released and tested okay	15:40:00	15:50:00	