



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 24/04/2026

Incharge(s): Amit Roy

Shift: C

| Sl No | Area | Equipment    | Problem             | Action                                                                                      | From     | To       | Remarks |
|-------|------|--------------|---------------------|---------------------------------------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | CO-3A        | ZSS acted           | Cage struck up.Made free and tested okay                                                    | 23:15:00 | 23:35:00 |         |
| 2     | OHP  | BRC on CO-28 | B/W-2 tripped       | OLR acted.Reset done                                                                        | 05:40:00 | 05:55:00 |         |
| 3     | OHP  | VF-19        | Reported tripped    | MPCB tripped.CHP side motor base bolts sheared.Replaced with new base bolts and tested okay | 04:30:00 | 05:00:00 |         |
| 4     | CHP  | CC-40 S2     | Lt not taking place | Wrong complaint                                                                             | 04:00:00 | 04:10:00 |         |
| 5     | CHP  | CC-51        | MPD tripped         | Reset done                                                                                  | 02:50:00 | 02:55:00 |         |
| 6     | WT   | OP-7         | Reported not moving | LS-1 sensor contact not coming.Bypassed and tested okay                                     | 04:10:00 | 04:20:00 |         |