वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/10/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 68	in 1-2LBDS6 I/C1 has no power due to PNl no8 circuit Breaker flash over	flash over IN circuit breaker due to RAT, individual feeder PNL back side open megger done all found ok,cable looping from ckt breaker to i/c r phase zeroIR	22:00:00	01:35:00	
2	OHP	WOBR on co 29	b/w not running,due to ol,stone stucked	informed mechanical	23:45:00	00:00:00	
3	OHP	BRC on co 8A	b/c not running,Cs acted due to sensor	sensor cleaned	00:57:00	01:15:00	
4	OHP	CO 25	olr acted	reset	05:35:00	05:45:00	
5	CHP	CC 51	mpd tripped	reset	01:45:00	01:50:00	
6	CHP	CC 104 SCR9	slew and b/w not working,jamming	informed operation	23:40:00	23:47:00	
7	CHP	CC 35 STK2	LT not working,drive tripped	reset	04:10:00	04:20:00	
8	CHP	CC 31 scr1	b/w not working,MPd acted due to overload	erset	04:20:00	04:32:00	
9	CHP	CC 38	mpr tripped in curt sp fault	reset	04:40:00	04:45:00	