



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 31/08/2026

Incharge(s): Lal Singh

Shift: C

| Sl No | Area | Equipment    | Problem                                    | Action           | From     | To       | Remarks |
|-------|------|--------------|--------------------------------------------|------------------|----------|----------|---------|
| 1     | OHP  | CO-25        | TRIPPED ON OLR                             | RESET DONE       | 23:50:00 | 00:00:00 |         |
| 2     | OHP  | CO-26        | TRIPPED ON OLR FOUR TIMES                  | RESET DONE       | 23:52:00 | 04:05:00 |         |
| 3     | OHP  | BRC ON CO-28 | BC TRIPPED ON OLR                          | RESET DONE       | 05:30:00 | 05:45:00 |         |
| 4     | CHP  | scr-8 CC-112 | SLEW NOT WORKING ... OIL LEVEL LOW         | INFORMED MECH    | 22:25:00 | 22:30:00 |         |
| 5     | CHP  | CC-35 S2     | BC TRIPPED ON UBC FAULT                    | RESET AND TESTED | 23:15:00 | 23:25:00 |         |
| 6     | CHP  | SCR-2 CC-33  | LT NOT WORKING ... PCRD FAST ACTED         | RESET DONE       | 00:30:00 | 00:40:00 |         |
| 7     | CHP  | SCR-7 CC-40  | BC TRIPPED ON OLR                          | RESET DONE       | 03:30:00 | 03:40:00 |         |
| 8     | CHP  | BRC ON CO-28 | BW 2 NOT RUNNING .. FLUID COUPLING PROBLEM | INFORMED MECH    | 02:20:00 | 02:30:00 |         |