वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 16/10/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO 6A	olr acted	reset	13:00:00	13:10:00	
2	OHP	co 20	BRS not resetting	checked and found all ok,brs acted yard side,belt piece hanging,informed operation	07:40:00	07:55:00	
3	OHP	CO 25	olr acted	reset	09:10:00	09:15:00	
4	OHP	BRC on CO 32	LT not working,OT acted	OT released	08:00:00	08:15:00	
5	OHP	co 33M	ZSS acted	wrong complain,checked and found OK	10:05:00	10:20:00	
6	OHP	WOBR on CO 26	LUff not working,OLr acted	reset	08:15:00	08:25:00	
7	CHP	CC 40 SCR7	b/c not working,slew 30 deg acted	released	06:30:00	06:40:00	
8	CHP	cc 40 scr7	slew not working,oil level low	informed mechanical	07:00:00	07:10:00	
9	CHP	CC 40 SCR7	BC not running,signal problem	LT done and modem and PLC power recycle done	08:50:00	09:00:00	