



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 02/10/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-32	Reported PC acted	PC cable found cut while cleaning.Bypassed at JB and clearance given	13:30:00	13:35:00	To be rectified
2	OHP	CO-32	BRS problem	Rectified at joint and kept in line	06:00:00	06:40:00	
3	OHP	BF-1A	Reported healthy not starting	Chute sensor acted	06:45:00	06:50:00	
4	OHP	WOBR on CO-25	Luffing not taking place	UP limit stuck.Made free	07:20:00	07:30:00	
5	OHP	CO-26	Reported tripped	OLR acted.Reset done	10:25:00 10:55:00 12:30:00	10:35:00 11:00:00 12:35:00	
6	OHP	WOBR on CO-24	Luffing not taking place	MPCB tripped.Made on	08:00:00	08:10:00	
7	OHP	CO-15	Reported healthy stopping	Checked and found position missing.Plate not placed properly	08:30:00	09:00:00	
8	CHP	CC-51	MPD tripped	Reset done(4 times)	09:10:00	13:20:00	
9	CHP	CC-131	Reported tripped	OLR acted.Reset done	09:30:00	09:35:00	
10	CHP	CC-32 SCR-5	LT not taking place	PCRD tension acted.Released	07:05:00	07:20:00	
11	CHP	SCR-7 on CC-40	B/c not running	Signal missing.CCR and machine modem power recycled	10:35:00	10:50:00	
12	CHP	SCR-4 on CC-111	B/c not running	CCR and machine modem power recycled and LT done towards gallery side	10:50:00	11:10:00	