



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 29/09/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR-1	Reported tripped	OLR acted.Reset done	14:30:00 18:30:00	14:40:00 18:40:00	
2	OHP	CC-125	Reported tripped	OLR acted.Reset done	20:00:00	20:10:00	
3	OHP	BRC on CO-8A	CT not taking place	Drive tripped.Reset done	15:15:00	15:20:00	
4	OHP	CO-26	Reported tripped	OLR acted.Reset done(2 times)	17:50:00 19:00:00	18:00:00 19:15:00	
5	OHP	CO-15	Reported ZSS acted	Belt loose while starting.	20:05:00	20:20:00	Informed to operation
6	OHP	WOBR on CO-25	LT not taking place	PCRD motor tripping.Loop given and power kept off.Drum arrested.	18:40:00	19:00:00	PCRD motor to be checked
7	OHP	BRC on CO-8A	LT not taking place	Drive tripped.Reset done	19:20:00	19:30:00	
8	OHP	CO-20	Reported BRS-2 acted	Sensors cleaned and tested okay	15:40:00	15:50:00	
9	CHP	SCR-10 on CC-105	B/C not running	Due to communication problem.ZSS was in line.Communication bit bypassed and tested okay	17:20:00	17:40:00	
10	CHP	S-2 on CC=35	LT not taking place	Wrong complaint	18:00:00	18:10:00	
11	CHP	SCR-3 on CC-37	Slewing not taking place	Left limit not healthy due to jamming	19:30:00	19:40:00	Informed to operation



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/09/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	SCR-2 on CC-33	LT not taking place	Drive tripped on over temperature.Reset done and tested okay	19:30:00	19:40:00	
13	CHP	CC-51A	Reported tripped	OLR acted.Reset done	20:35:00	20:40:00	
14	CHP	Cc-131	Reported tripped	OLR acted.Reset done	21:10:00	21:15:00	