



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 18/05/2026

Incharge(s): Saurabh Kumar Yadav

Shift: B

| Sl No | Area | Equipment   | Problem                                       | Action               | From     | To       | Remarks |
|-------|------|-------------|-----------------------------------------------|----------------------|----------|----------|---------|
| 1     | CHP  | cc 33 scr 2 | b/c not running,zss acted due to coal stucked | cage made free       | 14:45:00 | 14:55:00 |         |
| 2     | CHP  | CC 36 S1    | Lt not working ,M1 mpcb tripped               | made it on           | 16:30:00 | 16:40:00 |         |
| 3     | CHP  | CC 107      | motor tripped in olr                          | reset                | 21:04:00 | 21:10:00 | 2 times |
| 4     | CHP  | CC 115      | BRS acted,sensor covered with dust            | sensor cleaning done | 17:40:00 | 17:50:00 |         |
| 5     | WT   | CP 2        | no movement,no power,acb tripped in LC        | acb made on          | 17:00:00 | 17:10:00 |         |