

USHPA RISK ASSESSMENT WORKSHEET

Hang Gliding / Paragliding Site

The United States Hang Gliding & Paragliding Association • www.ushpa.aero • info@ushpa.aero

Flying Site Name	Copper Mountain		
Site Location: (Closest City, State)	Copper Mountain, CO	Annual/ Last Assessment Revision Date:	4 Jan 2019
Primary Launch GPS Coords: (DD.DDDD, -DD.DDDD)	39.4720, -106.1572	Primary LZ GPS Coords: (DD.DDDD, -DD.DDDD)	Summer: 39.5022, -106.1411 Winter:
			39.5000, -106.1500
			39.4990, -106.1480
Site Requirements: examples: H3, P3, H3 w/ CL	P4 and H4		
Site Type: examples: Coastal Cliff, High Alt, Mt Thermal, Eastern Ramp	Foot Launch (FL), High Altitude (HA), Ridge Soaring (RS), Turbulance (TUB), Mountain Thermal, Convergence Zone		
Site Guide Link: https://www.link.com	http://www.rmhpa.org/copper-site-guide	e/	
Site Guide Review Login: (if protected)	NA	Site Guide Review Password: (if protected)	NA
Chapter #:	21		
Chapter/Club Name:	Rocky Mountain Hang Gliding and Paragliding Association		
Name of Safety Coordinator:	Ed Williams, Tavo Gutierrez, Ben DeVo	oti	

Chp021-RiskAssessment-Copper.docx	Page 1 of 23
Copyright © 1974 - 2017 United States Hang Gliding and Paragliding Association, Inc. All rights reserved.	

Name of Site Coordinator:	Jason Rice
(for chapter)	

For Risk Management Information & Process Instructions see: START HERE: USHPA RISK MANAGEMENT PROGRAM


Quick Risk Management Plan Steps outline:

- 1. Review the Chapter Risk Management Training Videos & Training Materials on http://ushpa.vizigy.com
- 2. Create / Update Chapter Managed Sites and Site Locations List Table
 - a. Update Chapter Managed Site Additional Insured Landowner Table and associate to Site Locations
- 3. **Create Site Maps** to be used in this assessment and Site Guides. Site Maps to include the setup, launch, teardown and landing areas, including use zones & measurements (to compare to guidelines) and include in Risk Assessment & Site Guide document.
- 4. **Risk Assessment and Mitigation** sections of Worksheet: Identify all possible risks. Evaluate from the perspective of spectators, visiting pilots, inexperienced and experienced pilots. Analyze all risks and determine the vulnerabilities.
 - a. Note significant risks under Risk Detail and Risk Assessment.
 - b. For each risk noted, determine steps, actions, signs if necessary to mitigate the risk and document under "Risk Mitigation."
- 5. **Create Risk Mitigation Plans** in section of this worksheet for actions to be implemented if not in place and follow-through on any actions or other mitigation activities identified in your Risk Assessments and Action Plan, such as signage or preventative measures.
- 6. Create / Update Site Guide and update rules/regulations/protocols /site guides to be reflective of risks.
- 7. Communication
 - a. Publish your Site Guide and any rules/regulations/protocol guides, so all users of the flying site are aware of them
 - b. Publish your Risk Management Plan to be available to Chapter Members
- 8. Accident Investigations and feedback findings to your Risk Assessment Worksheet & Site Guide if actions are required
- 9. Submission Upload during Chapter Application/ Renewal (Annually) or send directly to USHPA or RRRG contact for updates after upload

Site Maps and Use Zones:


Launch

Located on Hallelujah Ridge by Storm King lift above Upper Enchanted Forest Summer drive-up access stops at Patrol Headquarters (PHQ) and requires short hike Winter access via lift with valid pass and proper ski/snowboard equipment




Summer Landing Zone

Located in main Alpine Lot




Winter Landing Zone 1

Located below Pitch Fork lift between Center and East Village



Winter Landing Zone 2

Located south of East Village and west of Super "B" lift



(000 - Flying Site Name) Copper	Review/ Revision Date 4 Ja	an 19	
Risk Identification (Examples – Feel free to identify your own!)	Risk Detail & Risk Assessment	Risk Mitigation	Sign Off
 Road or Trail Access What type of road access is there (4WD, paved, public, etc.)? What type of trails are used to access site features? Are roads and trails used to access the site secured using gates or locks? Should they be? Does access to roads/trails need to be restricted or monitored? Are there potential conflicts between pedestrians and vehicles (pilots or spectators)? How do emergency vehicles access site areas? Is signage needed? Have there been any incidents or accidents involving vehicles at this site? 	Summer drive-up access for 3 approved licensed/insured vehicles coordinated with mountain operation access. Only approved licensed drivers allowed to drive. Gate and pass code required to access road. Road is restricted and monitored. Drivers must yield right of way to pedestrians, workers, bicycles, vehicles, etc. Emergency vehicles can access the road. No incidents or accidents have been recorded.	Copper Mountain Resort Risk Management has insurance liability form. Mountain Operations requires a copy of vehicle registration, insurance and driver license. Approved vehicles must display the Drive Up Access permit when accessing the mountain. Road has posted speed limit of 20 mph. Ski/Bike Patrol provides first aid during daily winter/summer hours. Copper Mountain has a fire department located near Landing Zone.	
 Vehicle Parking Area Is there a designated parking area for vehicles? What is the clearance between vehicles and: Setup? Are gliders in setup area secured? Launch? Landing area? Teardown area? Are gliders in teardown secured? If any clearance is less than 50 feet, mitigation should be described Are tie-downs needed? Is signage needed? Have there been any incidents or accidents involving vehicles in the parking area at this site? 	Alpine Lot is the main parking lot located at the summer landing zone. Patrol Headquarters (PHQ) or top of Excelerator life is the parking location to access launch. Vehicle must not be parked to disrupt mountain operations or events. There are no tie downs for hang gliders. There is no signage except for Copper Resort signs. No incidents or accidents have been recorded.	Mountain Operations monitors vehicles including road and parking. Any violation can result in loss of drive up access.	

Chp021-RiskAssessment-C	Cop	per.	docx
-------------------------	-----	------	------

Spectator Areas

- What is the clearance between spectators and:
 - o Setup? Are gliders in setup area secured?
 - o Launch?
 - o Landing area?
- Teardown area? Are gliders in teardown secured?
- → If any clearance is less than 50 feet, mitigation should be described
- Are tie-downs needed?
- Are spectators allowed in areas with gliders without an escort? Should they be?
- How are spectator limitations communicated and enforced?
- Are barriers needed?
- Is signage needed?
- Have there been any incidents or accidents involving spectators at this site?

For spectators, mainly public trail users, spectators are kept away from use areas. Clearance >50 is easily achievable and pilots are encouraged to allow spectators, but to explain to them where to view from and the importance of staying clear of use areas.

Ski Patrol provides ropes in winter and designates launch is out-of-bounds for the general public.

There are no tie downs and hang gliders cannot fly in winter due to logistics of access mountain via lifts.

There is a snow fence at launch to help keep spectators out of the launch area,

There is no signage except for Copper Resort signs.

No incidents or accidents have been recorded.

Respectful and thoughtful communication between pilots and spectators.

Potential Obstacles

- Which potential obstacles are present at the site:
 - o wires
 - towers
 - lake or river
 - o ocean
 - o forest or trees
 - large rocky areas
 - o other
- What is the clearance between potential obstacles and:
 - o launch? (50 feet)
 - o landing area? (100 feet)
 - o planned flight path? (75 feet)
 - → If any clearance is less than noted distance, collision avoidance mitigation should be described
- Is the clearance sufficient?
- Are potential obstacles marked?
- Is signage needed?
- Have there been any incidents or accidents involving overhead obstacles at this site?

Launch area obstacles:

Scree (rocks), scrub, and trees below launch

Landing area obstacles:

There is roping around summer Landing Zone.

There are trees located around/near the winter Landing Zone.

Clearances:

Launch:

rocks and oak brush:> 30 feet

trees: > 100 feet

In flight:

trees: > 200 feet

LZ:

roping: > 10 feet trees: > 50 feet

Clearances are sufficient, obstacles are obvious, no flight path obstacles.

Pilots are not allowed to land within Ski Resort boundary.

Sufficient clearance must be maintained to make the appropriate landing zone.

Lifts, buildings, structures, trees, people are potential obstacles. These must be avoided at all times.

There is no signage except for Copper Resort signs.

No incidents or accidents have been recorded.

All pilots must fly with site director.

A walk-through must be completed with new pilots.

Ski Patrol controls flight clearance during winter operations.

Site director must check-in with Ski Patrol to obtain flight clearance any time pilots are going to fly.

During winter, pilots must access the launch area using approved ski/snowboard equipment.

If launch is not flyable, pilots must download the mountain using ski/snow equipment.

For returning pilots, walk full LZ and launch areas.

Before every flight, conduct a flight-plan review taking into account obstacles.

Steer clear of obstacles and be aware of the danger of object fixation.

Understand density altitude and how it affects launch and landing characteristics (HA endorsement required).

Launch Areas

- What is the clearance around the take-off area:
 - o in front (for solo pilots)? (50 feet)
 - o in front (for tandem pilots)? (75 feet)
 - o behind? (30 feet)
- o to the sides? (30 degrees)
- → If any clearance is less than noted, collision avoidance mitigation (for obstacles or spectators) should be described
- Are there ground obstructions (trip/fall hazards)?
- Is the launch area clearly marked? Does it need to be?
- Are there appropriate/adequate tie-downs?
- Are the site regulations and launch requirements clearly communicated to all pilots and spectators? How?
- Are there launch assistant qualifications and equipment guidelines communicated? How?
- Are spectator areas delineated and communicated? How?
- Is signage needed?
- Are there First Aid First Responder resources?
- Have there been any incidents or accidents involving obstacles, obstructions, vehicles or people on launch at this site?

Clearance for take-off obstacles is > 150 feet and > 180 degrees

Snow fence can be obstacle.

Scree and mountain debris are ground obstacles.

Slip/trip/fall hazards are present due to native environment.

Site regulations and launch requirements are clearly communicated to all pilots and spectators.

First responders are available.

There is no signage except for Copper Resort signs.

No incidents or accidents have been recorded.

Cellular coverage is available.

Emergency medical response is available from Copper, CO.

Ski Patrol is the primary first responder. 1-970-958-3311

Copper Fire Department is the second responder.

911

Landing Zones

- What is the clearance around the landing area and:
 - ground personnel
 - o vehicles
 - structures
 - o active roads/trails
 - spectators
 - → If any clearance is less than 50 feet, collision avoidance mitigation should be described
- Are there ground obstructions (trip/fall hazards)?
- Is the landing area clearly marked? Does it need to be?
- Are there appropriate/adequate tie-downs?
- Are the site regulations and landing requirements clearly communicated to all pilots and spectators? How?
- Are spectator areas delineated and communicated? How?
- Are there guidelines regarding ground handling (kiting) in the LZ area?
- Are there appropriate wind indicators?
- Is signage needed?
- Are there First Aid First Responder resources?
- Have there been any incidents or accidents involving obstacles, obstructions, vehicles or people in the landing area at this site?

Landing zone is located near I-70 Copper Mountain exit 195 and Highway 91 to Leadville.

Landing zone is located in a convergence zone where the Ten Mile canyon, Vail pass and Fremont pass air flows combine.

There are building structures located near the landing zones.

Alpine lot is a dirt parking lot that can generate poppy thermals.

There are burms, hills, potholes, streets, creeks, interstate, highways that pilot recognise as potential dangers.

Upon landing, pilots need to move their equipment and pack away from landing zone.

Wind socks are placed in the landing zones.

Copper main check-in has tall flag poles to indicate wind direction and speed.

Copper Fire Department is the first responder for the landing zone.

There is no signage except for Copper Resort signs.

No incidents or accidents have been recorded.

Cellular coverage is available.

Emergency medical response is available from Copper, CO.

Ski Patrol is the primary first responder. 1-970-958-3311

Copper Fire Department is the second responder.

911

Understand density altitude and HA endorsement required.

		
Other Activities in Area	General public can access the launch area, but there is plenty of space for pilots to keep clearance from	Pilots will communicate with spectators to keep them clear of launch area.
Is the site open to the general public?Do other activities occur in the same area? Such	spectators.	neep them stear of launen area.
as:	There is no signess event for Conner Descrit signs	Club must report any pilot that is not a
radio controlled (RC) aircraftmodel rocketry	There is no signage except for Copper Resort signs.	member attempting to access or fly the site.
 skeet shooting 	No incidents or accidents have been recorded.	Unauthorized access may result in legal
 o kite flying → If any other activity occurs, mid-air mishap 		actions in accordance Ski Resort policies.
mitigation should be described		This can be tresspassing, out-of-bounds misdemeanor designated by state
Is signage needed?Have there been any incidents or accidents		guildelines.
involving other activities at this site?		
		All pilots must have valid USPHA and RMHPA membership due to liability.
FAA Recognition and Communication		Automated Weather Observation System
Are there other flight operations in the area?	With the proximity to 170 there is possibility for VFR general aviation traffic. Sled rides should be low	(AWOS) 1-970-968-1715
general aviationcommercial aviation	enough to avoid conflicts. Thermal flights above	1-970-900-1715
agricultural aviation	launch altitude could encounter general aviation	
→ If any other flight operations occur in the	traffic.	
area, interference mitigation should be described		
Has the local FAA office been advised in writing		
of glider flight activities?		
 Are NOTAMs published for this site? Are there conflicts with Terminal Controlled 		
Flight areas (TCA)?		
 Are there potential conflicts with general aviation airports and landing patterns (non-controlled)? 		
 Are all tandem and towing operations in 		
compliance with FAA rules and regulations?		
 Have there been any incidents or accidents involving FAA non-compliance or other flight 		
operations in the area of this site?		

	<u> </u>		
Organized Events	Club has not had any organized events at this site.	Organized events have not occurred nor, at	
 Does your Chapter have any organized events at this site? Such as: club meetings, picnics or parties fly-ins or demo days ACE events or sanctioned competitions public demonstrations Is there a Flight Safety Coordinator designated for all flying events? Are spectator areas and vehicle parking areas clearly defined, designated and enforced? Are recommended clearances between flight operations and spectator areas marked, maintained and enforced? Are tie-down systems available and in-use for organized events? Are flight simulators or other demonstration 	Site director works with club to establish consistent safety guildelines.	this time of this submittal, are known to occur in the future at this Site.	
equipment under direct supervision at all times until disassembled?Are First Aid – First Responder resources on site			
and available?			

• Have there been any incidents or accidents during organized Chapter-sponsored events?

Safety Officer (Annual Review)

- Do your Bylaws clearly define the responsibilities of the Safety officer (can be a Director, Coordinator, or other titles)? Such as:
 - o Risk Assessment and Risk Mitigation Plan
 - o Incident Reporting process and follow-up
 - o Oversight of Site-Event Management Plans
 - Access to historical data for informing site guidelines and rules
 - Authority to close a site due to hazardous conditions or situations
 - Authority to restrict flight operations of a single pilot if necessary to avoid potential accidents
- Does your Chapter have a copy of USHPA's Risk Management Plan Program with Appendix A, Recommended Operating Guidelines?
- Does your Chapter have appropriate documentation in place for:
 - o Risk Mitigation Plan
 - Incident Reporting
 - policy/procedure to close a site due to hazardous conditions or situations
 - policy/procedure to restrict flight operations of a single pilot if necessary to avoid potential accidents

Yes, chapter bylaws included Safety Officer and Flight Director responsibilities, including reviewing and updating risk management plans, incident reporting, open access from pilots, site regulation changes and authority, and imposing flight restrictions.

Yes.

Documentation is maintained.

The Chapter Secretary is planning to visit all Chapter managed sites this year to review and update Google Earth Pro LZ obstacle photos with inputs from the local site experts/coordinators.

Information Communication

- Are flying site rules and guidelines clearly and appropriately communicated? This could be through one or more of the following:
 - website
 - o video
 - o signage on site
 - o paper hand-outs
 - designated members (site administrator, sponsor, guide)
 - o other
- Are flying site parameters and protocol clearly and appropriately communicated (to spectators and pilots) through signage, physical markings, barriers, etc.?
- Is contact information for the chapter site coordinator available at the site?
- How can members and spectators provide input and suggestions to the site management team?
- How is the Emergency Action Plan communicated?
- Have efforts been made to claim ownership of internet information with pointers back to your Chapter as the primary information source that takes precedence if on Google Maps, Paragliding Map, Paragliding Earth, or other online site guides?

Yes, site guidelines and process are communicated to the RMHPA membership via email, social media, and an updated website Site Guide.

In the chance spectators are present, pilots are encouraged to communicate with them on spectator safety hazards, where to view, and where to keep away from.

Site coordinator information will be included on the updated Site Guide.

Members and spectators are encouraged to contact any RMHPA officer with input or questions. Officer information is included in the RMHPA website.

Ownership claim has not been initiated.

Paraglide earth has old information and old site contact.

Experience & Skills required to fly the site safely

- List the pilot skill sets required to fly the site safely.
- Does the site require a specific pilot proficiency rating / special skills? Cliff, ramp launch, thermal, turbulence, . . .
- Is USHPA membership & ratings required to fly at this site?
- Each site should have recommended or required USHPA ratings
- Do the site ratings reflect the launch and landing zone requirements?
- Why did Site receive the rating? (Is the site a Green Circle run or a triple Black Diamond and why it was rated that)
- How are pilot rating/special skill requirements verified? Some possible methods:
 - o sticker
 - o text message (719-387-4571)
 - website (ushpa.org/m/#####)
 - o PDF USHPA or Chapter Member card
 - o designated members (site admin, sponsor)
- How is site access limited to only those pilots with a verified appropriate rating/special skills?
 - o all members
 - designated members (site administrator, sponsor, guide)
 - o other
- How does the chapter encourage and enable appropriate pilot experience for flying at this site?
- Does training take place at the site? If so, are USHPA training guidelines followed?

H4/P4 required w/ High Altitude (HA) and Turbulence (TUR) special skill endorsements.

Mini-wing (MW) are not allowed since landing zone is not located below launch.

The Site is insured, therefore USHPA membership and appropriate ratings are required.

Site ratings do reflect the pilot requirements during morning and evening flights and/or when thermic conditions and environmental hazards are not present. For mid-day conditions, H4/P4 or higher, is recommended.

USHPA membership/rating is verified by email, in-person cards, and/or txt message verification to USHPA.

Training does not occur since there is no on-site instructor.

Mentoring do occur at the Site since the site is more complex than other sites.

	<u>_</u>	
Emergency Action Plan	An EAP will be published on the website and briefed	An EAP is published on the website and
 Is the site Emergency Action Plan documented and communicated? Example methods: 	annually at a Chapter Meeting.	briefed annually at a Chapter Meeting.
websitesignage on site (launch and LZ)		A generic EAP, developed with reference to USHPA's online training material, is
paper hand-outsdesignated members		included on the Chapter website and briefed at a Chapter meeting annually. Specifics
Is there a documented protocol for filing incident		for individual sites are included in the
reports? • Have local emergency responders been notified		individual site guides.
of flying site location and methods of access?What first responder resources are available		Our Chapter conducted first responder
on-site? Some possible options: o first aid kit		training in 2018.and will sponsor additional First Responder and CPR classes if pilots
 direct phone numbers of emergency services landline telephone (e.g., pay phone) 		are interested.
o no-fly tarp/flag		
 Does the chapter sponsor First Aid and CPR training for members? How often? 		
 Have there been any incidents or accidents at this site using your Emergency Action Plan? 		
Tandem Flying	Currently, commercial operations for tandem flying is not allowed.	
 How is compliance with the USHPA FAA Tandem Exemption monitored and enforced? 	not anowed.	
Are all participants issued a 30-day student		
membership, or confirmed to possess a current USHPA membership?		
 What is the clearance around the take-off area: in front (for tandem pilots)? (75 feet) 		
behind? (30 feet)to the sides? (30 degrees)		
→ If any clearance is less than noted, collision avoidance mitigation (for obstacles or		
spectators) should be described		
 Have there been any incidents or accidents involving tandems at this site? 		

Towing	Towing is not allowed.	
Towing If towing operations occur at the site, indicate all types: aircraft boat scooter static line truck winch other List each towing vehicle used (Year, Manufacturer, Make, Model, Owner) Does every tow operator have the relevant USHPA towing appointments? Is there a written schedule for maintenance of all towing equipment and associated line and hardware? Does the Chapter verify that the towing equipment maintenance is up-to-date? Are there towing-specific risks at this site? For example: fuel storage equipment maintenance licensing of operation site access	Towing is not allowed.	
 Is the clearance around the towing area sufficient: in front? behind? 		
to the sides?overhead?For aero-towing operations:		
How is compliance with the USHPA FAA Towing Exemption monitored and enforced at the site? • Have there been any incidents or accidents involving towing at this site?		

Chp021-RiskAssessi	ment-Copper.docx
--------------------	------------------

Glider Tie Down Systems	No tie downs are available.	Given the need for tie downs, RMHPA
 Are glider tie-down systems needed at this site (in either the setup or teardown areas)? Possible reasons to require: dust devils gusty winds insufficient clearance from vehicles insufficient clearance from spectators If tie-downs are available, how are they communicated to pilots? If tie-downs are available, how are pilots encouraged to make use of them? Have there been any incidents or accidents 		would need to work with Copper Resort to determine how/where tie downs can be installed.
 Have there been any incidents or accidents involving loose gliders at this site? 		

Environment & Other Risk Considerations

- What are the Minimum & Maximum allowed winds and maximum gust factor for the site?
 Explanations should be included if these numbers are high for the industry.
- Are there any other risks or hazards associated with this site or XC from this site? For example:
 - o man-made risks
 - o natural hazards
 - o environmental risks
 - external events/forces
 - weather conditions
 - known venturi & rotor zones
 - o potential risks of impact
 - o vulnerability
 - o Time of year and time of day hazards
 - Other risks typically included in site briefings
- Are there any possible risks due to local response?
- Are there preventative measures that can be implemented immediately?
- Have there been any incidents or accidents in the past at this site? If so, what actions, systems, communications, etc. could have mitigated those outcomes?
- Have there been any incidents or accidents in the past Year that warrant hazard updates to the Site Guide?
- List any facilities owned by the chapter at this site (such as clubhouse, storage shed, wind sock tower, launch ramp, towing equipment)

There is no minimum wind speed and forward launches are common.

Pilots should not fly when there is any gust factors in the forecast.

Maximum winds are 15 mph mid-day conditions.

Mountainous weather is the primary flight-related hazard associated with this Site, and includes:

Wind velocity

Turbulence

Compression and venturi effects

Thermic conditions

Thunderstorm development

Gust fronts

Quickly changing conditions

H4/P4 rating implemented to reduce accidents and require only experienced pilots.

No incidents or accidents have been recorded in the past year.

No facility is owned by the club.


Weather-related risk mitigation tactics include:

Operating with rating limitations
Site mentorships and site walkthroughs

Understanding, reviewing, or beina trained/mentored in wind judgement and compression effects, topographic and terrain-induced amplification of weather, thermal knowledge and skills to deal with high altitude thermic conditions and how to recognize ramping, wind shear knowledge and forecast review, knowing where nearby wind talkers are located, understanding thunderstorm life cycle and recognizing hazardous conditions, having the flight skills to manage your aircraft including turbulence techniques and how to descend and land quickly when conditions build, recognizing changing conditions and landing quickly.

Mini / Speed Wing Provisions & Associated risks	No mini wing access.		
 Are Mini/ Speed Wings flown at your site? Do you have Mini/ Speed Wing provisions in your site protocols? Provisions or Restrictions to consider: Required Glide Ratio from each Launch to each LZ Quantifiable terrain clearance limits to experience level. Acceptable flying conditions in conjunction with terrain clearance protocols including acceptable times of day to the season. Restrictions on Low Acrobatic Flying / Low Barrel Rolls / Swooping Distances from other pilots, observers, vehicles, structures, and other obstacles or areas Are there any other Mini/ Speed Wing risks or hazards associated with this site? Have there been any Mini / Speed Wing incidents or accidents in the past Year that warrant hazard updates to the Site Guide? 	Launch is located away from landing zone, and mini wings do not enough glide to safely make the landing zone.		
Annual Insidents 9 Assidents Deview	Not applicable	We are constantly reviewing cofety	
Annual Incidents & Accidents Review	Not applicable 0 incidents in 2017	We are constantly reviewing safety protocols and procedures and how best to	
0 of Incidents this past Year 2018	0 accidents in 2017	communicate all of that to our member	
0 of Accidents this past Year 2018		pilots. Accidents and incidents are briefed at	
Has your Chapter Reviewed Accidents in this past year and prior years to determine if actions are required?		Chapter Meetings (when possible by the pilots involved). Lessons learned and takeaways for the future are discussed. Summaries of these accident and incident debriefs are included in Meeting Minutes on the Forum. It is our constant effort to keep the mentorship environment high for new pilots.	

Chp021-RiskAssessment-Copper.doc



Risk Mitigation Plan Activities - to be implemented/ work in process

Risk Mitigation Plan Activities	Responsible Coordinators	Project Start	Est. Completion
Update RAW and Site Guide Photos with Google Earth Pro (LZ obstacle survey to add to existing photos)	Scott Drinkard	Jan 2019	Aug 2019

Site Locations:

Attach & upload Chapter Managed Sites and Site Locations Table

Chp021-RiskAssessment-Copper.docx	Page 23 of 23
Copyright © 1974 - 2017 United States Hang Gliding and Paragliding Association, Inc. All rights reserved.	