Quintic Spline Math

Rajin Nagpal

The purpose of this is to demonstrate the math behind computing the splines used in the Motion Profiling project. The purpose of these splines is to create smooth paths between waypoints for a robot to efficiently traverse. To accomplish this, each spline will be a quintic polynomial defined in parametric form. The following guidelines will be used when computing the splines:

- Each spline will consist of a starting point, P_0 , and an ending point, P_1
 - Each point P_i will consist of an x_i , y_i , thet a_i representing its location and heading on a Cartesian coordinate plane
- Each spline will be modeled parametrically with the following two components:

$$-x(t) = a_x t^5 + b_x t^4 + c_x t^3 + d_x t^2 + e_x t + f_x$$

$$-y(t) = a_y t^5 + b_y t^4 + c_y t^3 + d_y t^2 + e_y t + f_y$$

- For every spline, P_0 will be defined when t = 0 and P_1 when t = 1 such that for every spline, the domain of t that encompasses the spline is $0 \le t \le 1$
- In order to maintain smooth curvature between splines, the second derivative of x(t) and y(t) at the endpoints of the spline will be 0 such that $\frac{d^2x}{dt^2}(0) = 0$, $\frac{d^2x}{dt^2}(1) = 0$, $\frac{d^2y}{dt^2}(0) = 0$, and $\frac{d^2y}{dt^2}(1) = 0$

The goal of the work shown below is to compute expressions for calculating the 12 coefficients that make up the quintic spline, $a_x, b_x, c_x, d_x, e_x, f_x, a_y, b_y, c_y, d_y, e_y, f_y$ all in terms of the points given $x_0, y_0, \theta_0, x_1, y_1, \theta_1$ so that given two waypoints, a quintic spline modeling the path between the waypoints can be computed in O(1) time.

First, we can use the starting and ending points of the spline to determine equations for when t = 0 and t = 1. We know the starting point, when t = 0, is (x_0, y_0) and the ending point, when t = 1, is (x_1, y_1) .

From this, we get the following equations

$$x(0) = x_0$$

$$a_x(0)^5 + b_x(0)^4 + c_x(0)^3 + d_x(0)^2 + e_x(0) + f_x = x_0$$

$$\Rightarrow f_x = x_0$$
(1)

$$x(1) = x_1$$

$$a_x(1)^5 + b_x(1)^4 + c_x(1)^3 + d_x(1)^2 + e_x(1) + f_x = x_1$$

$$\Rightarrow a_x + b_x + c_x + d_x + e_x + f_x = x_1$$
(2)

$$y(0) = y_0$$

$$a_y(0)^5 + b_y(0)^4 + c_y(0)^3 + d_y(0)^2 + e_y(0) + f_y = y_0$$

$$\Rightarrow f_y = y_0$$
(3)

$$y(1) = y_1$$

$$a_y(1)^5 + b_y(1)^4 + c_y(1)^3 + d_y(1)^2 + e_y(1) + f_y = y_1$$

$$\Rightarrow a_y + b_y + c_y + d_y + e_y + f_y = y_1$$
(4)

We can now incorporate the first derivatives using the θ_0 and θ_1 , the heading at the endpoints. The headings can be thought of as representative of the derivative of the quintic spline at the endpoints such that if f(x) is the function definition of the quintic spline, then

$$\frac{dy}{dx}(P_i) = \tan(\theta_i) = \frac{\sin(\theta_i)}{\cos(\theta_i)}$$

Using

$$\frac{dy}{dx} = \frac{y'(t)}{x'(t)}$$

we get

$$\frac{y'(t)}{x'(t)} = \frac{\sin(\theta_i)}{\cos(\theta_i)}$$

Here we can see that we could significantly simplify our equations if we could simply equate the numerator and denominator, but that is not allowed since the numerator/denominator on one side may be scaled to a different magnitude than the other. However, we can work around this by introducing a constant, s, which represents scaling one fraction by some scalar amount. This both obeys the laws of mathematics and allows flexibility in the magnitudes of the fractions, so long as the ratios match. For simplicity, we'll scale the $\frac{\sin(\theta)}{\cos(\theta)}$ side as such

$$\frac{y'(t)}{x'(t)} = \frac{s \cdot \sin(\theta_i)}{s \cdot \cos(\theta_i)}$$

which now gives

$$y'(t) = s \cdot \sin(\theta_i)$$

$$x'(t) = s \cdot \cos(\theta_i)$$

To use these, we should define the first derivative for x(t) and y(t) from the polynomial definition

$$x'(t) = 5a_x t^4 + 4b_x t^3 + 3c_x t^2 + 2d_x t + e_x$$

$$y'(t) = 5a_y t^4 + 4b_y t^3 + 3c_y t^2 + 2d_y t + e_y$$

We can now apply this to our endpoints when t = 0 and t = 1

$$x'(0) = s \cdot \cos(\theta_0)$$

$$5a_x(0)^4 + 4b_x(0)^3 + 3c_x(0)^2 + 2d_x(0) + e_x = s \cdot \cos(\theta_0)$$

$$\Rightarrow e_x = s \cdot \cos(\theta_0)$$
(5)

$$x'(1) = s \cdot \cos(\theta_1)$$

$$5a_x(1)^4 + 4b_x(1)^3 + 3c_x(1)^2 + 2d_x(1) + e_x = s \cdot \cos(\theta_1)$$

$$\Rightarrow 5a_x + 4b_x + 3c_x + 2d_x + e_x = s \cdot \cos(\theta_1)$$
(6)

$$y'(0) = s \cdot \sin(\theta_0)$$

$$5a_y(0)^4 + 4b_y(0)^3 + 3c_y(0)^2 + 2d_y(0) + e_y = s \cdot \sin(\theta_0)$$

$$\Rightarrow e_y = s \cdot \sin(\theta_0)$$
(7)

$$y'(1) = s \cdot \sin(\theta_1)$$

$$5a_y(1)^4 + 4b_y(1)^3 + 3c_y(1)^2 + 2d_y(1) + e_y = s \cdot \sin(\theta_1)$$

$$\Rightarrow 5a_y + 4b_y + 3c_y + 2d_y + e_y = s \cdot \sin(\theta_1)$$
(8)

Now, we know the second derivative must be 0 at the endpoints for x(t) and y(t) so we get x''(0) = 0, x''(1) = 0, y''(0) = 0, y''(1) = 0. Again, let's start by first defining the second derivative of x(t) and y(t) from the polynomial definition

$$x''(t) = 20a_x t^3 + 12b_x t^2 + 6c_x t + 2d_x$$

$$y''(t) = 20a_y t^3 + 12b_y t^2 + 6c_y t + 2d_y$$

Now we can apply this to the endpoints

$$x''(0) = 0$$

$$20a_x(0)^3 + 12b_x(0)^2 + 6c_x(0) + 2d_x = 0$$

$$2d_x = 0$$

$$\Rightarrow d_x = 0$$
(9)

$$x''(1) = 0$$

$$20a_x(1)^3 + 12b_x(1)^2 + 6c_x(1) + 2d_x = 0$$

$$\Rightarrow 20a_x + 12b_x + 6c_x + 2d_x = 0$$
(10)

$$y''(0) = 0$$

$$20a_y(0)^3 + 12b_y(0)^2 + 6c_y(0) + 2d_y = 0$$

$$2d_y = 0$$

$$\Rightarrow d_y = 0$$
(11)

$$y''(1) = 0$$

$$20a_y(1)^3 + 12b_y(1)^2 + 6c_y(1) + 2d_y = 0$$

$$\Rightarrow 20a_y + 12b_y + 6c_y + 2d_y = 0$$
(12)

Using the initial constraints, we have been able to solve for 6 of the 12 coefficients as shown in equations (1), (3), (5), (7), (9), (11). We can now substitute those values into the rest of the equations to solve for the remaining 6 coefficients.

Substituting in we get the following equations

$$(2) \Rightarrow a_x + b_x + c_x + d_x + e_x + f_x = x_1$$

$$a_x + b_x + c_x + (0) + (s \cdot \cos(\theta_0)) + (x_0) = x_1$$

$$a_x + b_x + c_x = x_1 - x_0 - s \cdot \cos(\theta_0)$$
(13)

$$(4) \Rightarrow a_{y} + b_{y} + c_{y} + d_{y} + e_{y} + f_{y} = y_{1}$$

$$a_{y} + b_{y} + c_{y} + (0) + (s \cdot \sin(\theta_{0})) + (y_{0}) = y_{1}$$

$$a_{y} + b_{y} + c_{y} = y_{1} - y_{0} - s \cdot \sin(\theta_{0})$$

$$(14)$$

$$5a_{x} + 4b_{x} + 3c_{x} + 2d_{x} + e_{x} = s \cdot \cos(\theta_{1})$$

$$5a_{x} + 4b_{x} + 3c_{x} + 2(0) + (s \cdot \cos(\theta_{0})) = s \cdot \cos(\theta_{1})$$

$$5a_{x} + 4b_{x} + 3c_{x} = s \cdot \cos(\theta_{1}) - s \cdot \cos(\theta_{0})$$
(15)

$$5a_{y} + 4b_{y} + 3c_{y} + 2d_{y} + e_{y} = s \cdot \sin(\theta_{1})$$

$$5a_{y} + 4b_{y} + 3c_{y} + 2(0) + (s \cdot \sin(\theta_{0})) = s \cdot \sin(\theta_{1})$$

$$5a_{y} + 4b_{y} + 3c_{y} = s \cdot \sin(\theta_{1}) - s \cdot \sin(\theta_{0})$$
(16)

$$(10) \Rightarrow 20a_x + 12b_x + 6c_x + 2d_x = 0$$
$$20a_x + 12b_x + 6c_x + 2(0) = 0$$
$$20a_x + 12b_x + 6c_x = 0$$
(17)

$$(12) \Rightarrow 20a_y + 12b_y + 6c_y + 2d_y = 0$$
$$20a_y + 12b_y + 6c_y + 2(0) = 0$$
$$20a_y + 12b_y + 6c_y = 0$$
(18)

Using these equations, we can crate 2 systems of 3 linear equations as shown

$$(13) \Rightarrow a_x + b_x + c_x = x_1 - x_0 - s \cdot \cos(\theta_0)$$

$$(15) \Rightarrow 5a_x + 4b_x + 3c_x = s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0)$$

$$(17) \Rightarrow 20a_x + 12b_x + 6c_x = 0$$

$$(14) \Rightarrow \qquad \qquad a_y + b_y + c_y = y_1 - y_0 - s \cdot \sin(\theta_0)$$

$$(16) \Rightarrow \qquad \qquad 5a_y + 4b_y + 3c_y = s \cdot \sin(\theta_1) - s \cdot \sin(\theta_0)$$

$$(18) \Rightarrow \qquad \qquad 20a_y + 12b_y + 6c_y = 0$$

We can write both of these systems in Ax = b form

$$\begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} \begin{bmatrix} a_x \\ b_x \\ c_x \end{bmatrix} = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) \\ 0 \end{bmatrix}$$
$$\begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} \begin{bmatrix} a_y \\ b_y \\ c_y \end{bmatrix} = \begin{bmatrix} y_1 - y_0 - s \cdot \sin(\theta_0) \\ s \cdot \sin(\theta_1) - s \cdot \sin(\theta_0) \\ 0 \end{bmatrix}$$

Since the A matrix is the same for both systems, we can create an LU factorization of the matrix and use that to solve both system

$$A = \begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix}$$

LU Factorization

$$C_1 = \frac{1}{1} \begin{bmatrix} 1\\5\\20 \end{bmatrix} = \begin{bmatrix} 1\\5\\20 \end{bmatrix}$$

$$R_1 = \begin{bmatrix} 1 & 1 & 1 \end{bmatrix}$$

$$A = A - C_1 \cdot R_1$$

$$A = \begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} - \begin{bmatrix} 1 \\ 5 \\ 20 \end{bmatrix} \cdot \begin{bmatrix} 1 & 1 & 1 \end{bmatrix}$$

$$A = \begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} - \begin{bmatrix} 1 & 1 & 1 \\ 5 & 5 & 5 \\ 20 & 20 & 20 \end{bmatrix}$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & -1 & -2 \\ 0 & -8 & -14 \end{bmatrix}$$

$$L = C_1$$

$$L = \begin{bmatrix} 1 \\ 5 \\ 20 \end{bmatrix}$$

$$U = R_1$$
$$U = \begin{bmatrix} 1 & 1 & 1 \end{bmatrix}$$

$$C_2 = \frac{1}{-1} \begin{bmatrix} 0 \\ -1 \\ -8 \end{bmatrix} = \begin{bmatrix} 0 \\ 1 \\ 8 \end{bmatrix}$$

$$R_2 = \begin{bmatrix} 0 & -1 & -2 \end{bmatrix}$$

$$A = A - C_2 \cdot R_2$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & -1 & -2 \\ 0 & -8 & -14 \end{bmatrix} - \begin{bmatrix} 0 \\ 1 \\ 8 \end{bmatrix} \cdot \begin{bmatrix} 0 & -1 & -2 \end{bmatrix}$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & -1 & -2 \\ 0 & -8 & -14 \end{bmatrix} - \begin{bmatrix} 0 & 0 & 0 \\ 0 & -1 & -2 \\ 0 & -8 & -16 \end{bmatrix}$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 2 \end{bmatrix}$$

$$L = \begin{bmatrix} L & C_2 \end{bmatrix}$$

$$L = \begin{bmatrix} 1 & 0 \\ 5 & 1 \\ 20 & 8 \end{bmatrix}$$

$$U = \begin{bmatrix} U \\ R_2 \end{bmatrix}$$

$$U = \begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \end{bmatrix}$$

$$C_3 = \frac{1}{2} \begin{bmatrix} 0 \\ 0 \\ 2 \end{bmatrix} = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$$

$$R_3 = \begin{bmatrix} 0 & 0 & 2 \end{bmatrix}$$

$$A = A - C_3 \cdot R_3$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 2 \end{bmatrix} - \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix} \cdot \begin{bmatrix} 0 & 0 & 2 \end{bmatrix}$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 2 \end{bmatrix} - \begin{bmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 2 \end{bmatrix}$$

$$A = \begin{bmatrix} 0 & 0 & 0 \\ 0 & 0 & 0 \\ 0 & 0 & 0 \end{bmatrix}$$

$$L = \begin{bmatrix} L & C_3 \end{bmatrix}$$

$$L = \begin{bmatrix} 1 & 0 & 0 \\ 5 & 1 & 0 \\ 20 & 8 & 1 \end{bmatrix}$$

$$U = \begin{bmatrix} U \\ R_3 \end{bmatrix}$$

$$U = \begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix}$$

Thus, we have an LU factorization where

$$L = \begin{bmatrix} 1 & 0 & 0 \\ 5 & 1 & 0 \\ 20 & 8 & 1 \end{bmatrix}$$
$$U = \begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix}$$

such that

$$A = LU$$

$$\begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ 5 & 1 & 0 \\ 20 & 8 & 1 \end{bmatrix} \cdot \begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix}$$

Solve for a_x , b_x , c_x

$$\begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} \begin{bmatrix} a_x \\ b_x \\ c_x \end{bmatrix} = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) \\ 0 \end{bmatrix}$$

Substituting in our LU factorization, this becomes

$$\begin{bmatrix} 1 & 0 & 0 \\ 5 & 1 & 0 \\ 20 & 8 & 1 \end{bmatrix} \cdot \begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix} \begin{bmatrix} a_x \\ b_x \\ c_x \end{bmatrix} = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) \\ 0 \end{bmatrix}$$
(19)

Now, let's define a matrix z such that

$$\begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix} \begin{bmatrix} a_x \\ b_x \\ c_x \end{bmatrix} = \begin{bmatrix} z_1 \\ z_2 \\ z_3 \end{bmatrix}$$
 (20)

We can substitute this back into equation (19) to get

$$\begin{bmatrix} 1 & 0 & 0 \\ 5 & 1 & 0 \\ 20 & 8 & 1 \end{bmatrix} \cdot \begin{bmatrix} z_1 \\ z_2 \\ z_3 \end{bmatrix} = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) \\ 0 \end{bmatrix}$$

Now we can solve for z using forward substitution

$$z_1 + (0)z_2 + (0)z_3 = x_1 - x_0 - s \cdot \cos(\theta_0)$$

$$z_1 = x_1 - x_0 - s \cdot \cos(\theta_0)$$

$$5z_1 + z_2 + (0)z_3 = s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0)$$

$$z_2 = s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) - 5(x_1 - x_0 - s \cdot \cos(\theta_0))$$

$$z_2 = s \cdot \cos(\theta_1) - s \cdot \cos(\theta_0) - 5x_1 + 5x_0 + 5s \cdot \cos(\theta_0)$$

$$z_2 = -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0)$$

$$20z_1 + 8z_2 + z_3 = 0$$

$$z_3 = -20(x_1 - x_0 - s \cdot \cos(\theta_0)) - 8(-5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0))$$

$$z_3 = -20x_1 + 20x_0 + 20s \cdot \cos(\theta_0) + 40x_1 - 40x_0 - 8s \cdot \cos(\theta_1) - 32s \cdot \cos(\theta_0)$$

$$z_3 = 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0)$$

Thus, we get

$$z = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0) \\ 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0) \end{bmatrix}$$

We can now substitute z into equation (20) to get

$$\begin{bmatrix} 1 & 1 & 1 \\ 0 & -1 & -2 \\ 0 & 0 & 2 \end{bmatrix} \begin{bmatrix} a_x \\ b_x \\ c_x \end{bmatrix} = \begin{bmatrix} x_1 - x_0 - s \cdot \cos(\theta_0) \\ -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0) \\ 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0) \end{bmatrix}$$

through which we can now solve for a_x , b_x , c_x using back substitution

$$0(a_x) + 0(b_x) + 2c_x = 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0)$$

$$2c_x = 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0)$$

$$c_x = 10x_1 - 10x_0 - 4s \cdot \cos(\theta_1) - 6s \cdot \cos(\theta_0)$$
(21)

$$0(a_x) - b_x - 2c_x = -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0)$$

$$-b_x = -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0) + 2(10x_1 - 10x_0 - 4s \cdot \cos(\theta_1) - 6s \cdot \cos(\theta_0))$$

$$-b_x = -5x_1 + 5x_0 + s \cdot \cos(\theta_1) + 4s \cdot \cos(\theta_0) + 20x_1 - 20x_0 - 8s \cdot \cos(\theta_1) - 12s \cdot \cos(\theta_0)$$

$$-b_x = 15x_1 - 15x_0 - 7s \cdot \cos(\theta_1) - 8s \cdot \cos(\theta_0)$$

$$b_x = -15x_1 + 15x_0 + 7s \cdot \cos(\theta_1) + 8s \cdot \cos(\theta_0)$$
(22)

$$a_{x} + b_{x} + c_{x} = x_{1} - x_{0} - s \cdot \cos(\theta_{0})$$

$$a_{x} = x_{1} - x_{0} - s \cdot \cos(\theta_{0}) - (-15x_{1} + 15x_{0} + 7s \cdot \cos(\theta_{1}) + 8s \cdot \cos(\theta_{0}))$$

$$- (10x_{1} - 10x_{0} - 4s \cdot \cos(\theta_{1}) - 6s \cdot \cos(\theta_{0}))$$

$$a_{x} = x_{1} - x_{0} - s \cdot \cos(\theta_{0}) + 15x_{1} - 15x_{0} - 7s \cdot \cos(\theta_{1}) - 8s \cdot \cos(\theta_{0})$$

$$- 10x_{1} + 10x_{0} + 4s \cdot \cos(\theta_{1}) + 6s \cdot \cos(\theta_{0})$$

$$a_{x} = 6x_{1} - 6x_{0} - 3s \cdot \cos(\theta_{1}) - 3s \cdot \cos(\theta_{0})$$
(23)

Thus, we have computed a_x , b_x , c_x to be the following

$$a_x = 6x_1 - 6x_0 - 3s \cdot \cos(\theta_1) - 3s \cdot \cos(\theta_0)$$

$$b_x = -15x_1 + 15x_0 + 7s \cdot \cos(\theta_1) + 8s \cdot \cos(\theta_0)$$

$$c_x = 10x_1 - 10x_0 - 4s \cdot \cos(\theta_1) - 6s \cdot \cos(\theta_0)$$

Solve for a_y , b_y , c_y

$$\begin{bmatrix} 1 & 1 & 1 \\ 5 & 4 & 3 \\ 20 & 12 & 6 \end{bmatrix} \begin{bmatrix} a_y \\ b_y \\ c_y \end{bmatrix} = \begin{bmatrix} y_1 - y_0 - s \cdot \sin(\theta_0) \\ s \cdot \sin(\theta_1) - s \cdot \sin(\theta_0) \\ 0 \end{bmatrix}$$

At a first glance, we can see here that the system of equations for the y term coefficients is identical to x with the following conversions

$$x_0 \Rightarrow y_0$$

$$x_1 \Rightarrow y_1$$

$$\cos(\theta_0) \Rightarrow \sin(\theta_0)$$

$$\cos(\theta_1) \Rightarrow \sin(\theta_1)$$

Although we could use the same LU factorization from above since the A matrix is identical, the similarities in the b matrix means we can just apply the conversions directly to a_x , b_x , c_x to derive the equations for a_y , b_y , c_y .

$$a_y = 6y_1 - 6y_0 - 3s \cdot \sin(\theta_1) - 3s \cdot \sin(\theta_0) \tag{24}$$

$$b_y = -15y_1 + 15y_0 + 7s \cdot \sin(\theta_1) + 8s \cdot \sin(\theta_0) \tag{25}$$

$$c_y = 10y_1 - 10y_0 - 4s \cdot \sin(\theta_1) - 6s \cdot \sin(\theta_0)$$
(26)

It is good to note here that if the b matrices differed in both cases, this would represent one of the main advantages of LU factorizations and why it was used in this case. Because the LU factorization remains the same, the only math that would have been repeated is the forward and back substitution.