	Significance
Equipment	Overall Weighted Average (1-5)
HAAS VF-1	5.0
Surface Roughness Measurement Gauge	5.0
Granite Plate	3.7
Electronic Height Gauge	3.7
Dynamometer	3.7
Coordinate Measuring Machine	3.1
3D Printer	2.4
Inspection Arm	2.4
Robot Arm	2.4
3D- Digital Microscope	1.3

Frequency		
Frequency of Use (1-5)	30% Weight of Significance	
5	1.5	
2	0	
3	0.9	
3	0.9	
3	0.9	
1	0.3	
1	0.3	
1	0.3	
1	0.3	
2	0.6	

Importance		
Importance of Equipment (1-5)	70% Weight of Significance	
5	3.5	
5	5	
4	2.8	
4	2.8	
4	2.8	
4	2.8	
3	2.1	
3	2.1	
3	2.1	
1	0.7	

Issues				
Overall Weighted Average (1- 5)	Issues Noted (1-5)	40% Weight		
4.0	4	1.6		
5.0	5	2		
5.0	5	2		
5.0	5	2		
5.0	5	2		
5.0	5	2		
3.8	5	2		
3.8	5	2		
3.8	5	2		
5.0	5	2		

Performance		
Performance Satisfaction (1-5)	60% Weight	
4	2.4	
5	3	
5	3	
5	3	
5	3	
5	3	
3	1.8	
3	1.8	
3	1.8	
5	3	