	Significance
Equipment	Overall Weighted Average (1-5)
HAAS VF-1	5.0
Surface Roughness Measurement Gauge	5.0
Granite Plate	3.7
Electronic Height Gauge	3.7
Dynamometer	3.7
Coordinate Measuring Machine	3.1
3D Printer	2.4
Inspection Arm	2.4
Robot Arm	2.4
3D- Digital Microscope	1.3

Frequency		
Frequency of Use (1-5)	30% Weight of Significance	
5	1.5	
2	0	
3	0.9	
3	0.9	
3	0.9	
1	0.3	
1	0.3	
1	0.3	
1	0.3	
2	0.6	

	Importance			
Importance of Equipment (1-5)	70% Weight of Significance			
5	3.5			
5	5			
4	2.8			
4	2.8			
4	2.8			
4	2.8			
3	2.1			
3	2.1			
3	2.1			
1	0.7			

Issues			
Overall Weighted Average (1- 5)	Issues Noted (1-5)	40% Weight	
4.0	4	1.6	
5.0	5	2	
5.0	5	2	
5.0	5	2	
5.0	5	2	
5.0	5	2	
3.8	5	2	
3.8	5	2	
3.8	5	2	
5.0	5	2	

Perfori	Performance		
Performance Satisfaction (1-5)	60% Weight		
4	2.4		
5	3		
5	3		
5	3		
5	3		
5	3		
3	1.8		
3	1.8		
3	1.8		
5	3		