

Reno Budget Northbank

Renovation Budget - Northbank Terrace

Structured renovation budget categories and costs only.

Category	Scope	Estimated Cost
Roof membrane repairs	Partial roof repair and sealing	\$85,000
Common hallway flooring	Replace corridor flooring	\$42,000
Exterior lighting	Security and LED fixtures	\$18,000
Unit turn allowance	Cosmetic turn allowance only	\$120,000
Contingency	10% contingency	\$26,500

Total renovation budget: \$291,500

No rent lift, ROI, payback, phasing, cost recovery, or implementation schedule is provided.

Fictitious test document prepared for InvestorIQ validation only.