




Bias = 0.15V RTD: 20.9C $\Delta T = 0.4C$




Bias = 1.0V RTD: 21.1C $\Delta T = 0.4C$




Bias = 3.0V RTD: 21.4C $\Delta T = 0.5C$




Bias = 5.0V RTD: 21.6C $\Delta T = 0.9C$




Bias = 7.0V RTD: 21.6C $\Delta T = 1.6C$




Bias = 9.0V RTD: 21.7C $\Delta T = 3.1C$




Bias = 11.0V RTD: 20.7C $\Delta T = 5.0C$




Bias = 13.0V RTD: 21.9C $\Delta T = 7.3C$




Bias = 15.0V RTD: 25.2C $\Delta T = 9.9C$




Bias = 17.0V RTD: 30.4C $\Delta T = 12.7C$




Bias = 19.0V RTD: 35.8C $\Delta T = 15.0C$




Bias = 21.0V RTD: 41.5C $\Delta T = 16.9C$




Bias = 23.0V RTD: 47.9C $\Delta T = 18.0C$




Bias = 25.0V RTD: 51.8C $\Delta T = 16.7C$




Bias = 27.0V RTD: 48.7C $\Delta T = 44.1C$



Bias = 29.0V RTD: 43.4C $\Delta T = 47.2C$



Bias = 0.15V RTD: -1.8C $\Delta T = 6.4C$



Bias = 0.15V RTD: -13.5C $\Delta T = 3.0C$

