




Bias = 0.15V RTD: 24.0C  $\Delta T = 0.4C$ 




Bias = 1.0V RTD: 24.1C  $\Delta T = 0.4C$ 




Bias = 3.0V RTD: 23.5C  $\Delta T = 0.5C$ 




Bias = 5.0V RTD: 21.0C  $\Delta T = 1.1C$ 




Bias = 7.0V RTD: 17.8C  $\Delta T = 1.9C$ 



Bias = 9.0V RTD: 12.7C  $\Delta T = 3.2C$ 



Bias = 0.15V RTD: 10.3C  $\Delta T = 0.9C$ 



Bias = 0.15V RTD: 11.8C  $\Delta T = 0.3C$ 

