

Simulated Handwriting Data:

Confidential Field Log - Site Gamma-17

Date: 19/11/2025

Time: 14:15 Hrs.

Observation Notes:

Found the access panel slightly ajar. Temperature reading seems high, maybe 45°C, but my thermometer battery is low, so verify this later.

The main circuit board label reads: "Phoenix Ind. Rev. B-4." Note, this is different from the spec sheet (which listed Rev. A). Need to check inventory for spares. Only 3 bolts securing the housing—one missing from the top left corner. This could be why the environmental seal failed.

Need to purchase:

- New thermal paste (high conductivity)
- 3x M5 10mm stainless steel bolts
- A reliable thermometer

Signature (Simulated): J. F. R.

Contact (Fictional): +1 (800) 555-0199 (Extension 207)

Internal Ref: Project Nightingale