HPT Precision Spindles & Drives, Inc.

5 Seaview Lane
Port Washington, NY 11050
516-944-8446
516-767-7836 Fax
vickym@hpt-drivesystems.com

Name/Address

Federal-Mogul Corporation Cahampion Ignition Products PO Box 500 Southfield, MI 48037

Service Quote

Date	Estimate No.		
3/29/2023	041910-2449		

Ship To

Federal Mogul Corporation 3009 Sylvania Drive Burlington, Iowa 52601 Atten: Steven Mitchell

		Project	
Description	Qty	Rate	Total
Repair-Recondition ARS42-M120.02 S2 Serial Number:54219 Error description: - front bearing is damaged - rear bearing housing has fretting corrosion - front bearing housing has fretting corrosion	1	3,490.00	3,490.00
		Total	USD 3,490.00