CAED Support Shops

Lathe

•Review dress code

-Remind students that long hair must be tied back, loose clothing and/or jewelry must be removed

•Prepare Spindle Blank

- -Draw diagonal lines at each end of blank to find center
- -Remove excess material at corners
 - -Explain to students that this is an optional step
 - -Show how to tilt table on bandsaw to 45 degrees and set up rip fence
- -Make cuts

Parts of Lathe

- -Describe
 - -Bed, Headstock, Tailstock, Tool rest vise, and Tool rest
- -Show Controls
 - -On/Off
 - -Speed Control
- -Speed should only be changed while tool is running
- •Set Up for Spindle Turning
- -Lightly tap Drive Spur into pre-cut groves at end of workpiece
- -Insert Drive spur and piece into Headstock
- -Insert live Center into Tailstock
- -Slide Tailstock in place until Live Center contacts center mark of material

_