AR COUNTY TORON OF THE PARTY OF			Comments
Condition	Yes	°	
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		1	
Roof has holes or large cracks		1	
Gutters or downspouts broken		1	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb			
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting			
siding has miss		1	
Water stains on interior walls or ceilings		1	
Walls or ceilings deteriorated		1	
More than "very small" amount of paint in a room deteriorated			
Two or more windows or doors broken, missing, or boarded up		3	
Porch or steps have major elements broken, missing, or boarded up		1	
Foundation has major cracks, missing material, structure leans, or visibly unsound			Soft Spors in Hallway ar Bey 2 toles 3 Hallway ar
** Total number			
The General on the do wining or with	Link Time	Tout to	ITTD I Rafe Honeing Rule (24 CFR

address:

Notes (including other conditions of concern)

and Ig Kule (24 Cr lead training Housing Kule the Safe under Lead condition" under the Hou in poor amount "paint amount is the de minimis or the amount of paint that is not "402") rule (40 CFR 745.223). very small' 50(d)), or cation

conditions in good concer, specific condition.

Sondition of the dwelling and condition of the dwelling and in good condition for the and a lead hazard screen a lead hazard screen. final condition advisable. conducting any checks, the dwelling is usually considered not to be any checks, ses of a risk assessment, and conducting a lead hazard screen is not adtenuating circumstances should be considered before determining the propriateness of a lead hazard screen. If the "Yes" column has any chened, describe, below, the extenuating circumstances that justify conduced, "Yes" column has