Limitations of Inspection

App# 10101 Location: $1908 \pm .57N ST$ Date: $5/5/77$ Inspector: $F.51M0N$
Date: 5/5/77 Inspector: F. SIMON)
Limitations based on access, safety, or availability:
Asbestos Inspection: - PRESSUMED ACM - MASTIC ARQUNO CHIMMEY POT JESTED DUE SAFETY REASONS
Lead Inspection Risk Assessment:
General Notes: