Apt. No.		2/2
Risk Assessment.		Date of assessment:
Form for Lead Hazard	alm Reside	
Form 5.1 Building Condition F Property address: 55512	Name of property owner: (N/1/1)	isk

Condition	Yes	No	Comments
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		X	
Roof has holes or large cracks		2	
Gutters or downspouts broken		X	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		>	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting	X		
Exterior siding has missing boards or shingles	X		
Water stains on interior walls or ceilings	X		
Walls or ceilings deteriorated	X		
More than "very small" amount of paint in a room deteriorated	X		
Two or more windows or doors broken, missing, or boarded up			
Porch or steps have major elements broken, missing, or boarded up	X		
Foundation has major cracks, missing material, structure leans, or visibly unsound			
** Total number	9	-	
* The Wagner constitution is it is it is	1	1	

training and Rule Safe Housing Rul der the EPA lead t under the The "very small" amount is the de minimis amount under the HUD Lead 5.1350(d)), or the amount of paint that is not "paint in poor condition" undertification ("402") rule (40 CFR 745.223).

Imposes of a risk assessment, and conducting a lead hazard screen is not advisable. However, specific conditions id extenuating circumstances should be considered before determining the final condition of the dwelling and e appropriateness of a lead hazard screen. If the "Yes" column has any checks, and a lead hazard screen is to be aformed, describe, below, the extenuating circumstances that justify conducting a lead hazard screen. for the condition pood E If the "Yes" column has any checks, the dwelling is usually considered not to be irposes of a risk assessment, and conducting a lead hazard screen is not advisable

Notes (including other conditions of concern);