Assessme Hazard ead Building Form

ssment: asse Date 0 of property owner: of risk assessor: address: perty ame me

Condition	Yes	0N	Comments
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		~	
Roof has holes or large cracks		×	
Gutters or downspouts broken		×	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		>	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting		>	
siding has m		X	
Water stains on interior walls or ceilings		X	
Walls or ceilings deteriorated		×	
More than "very small" amount of paint in a room deteriorated		/	
Two or more windows or doors broken, missing, or boarded up		<	
Porch or steps have major elements broken, missing, or boarded up		X	
Foundation has major cracks, missing material, structure leans, or visibly unsound	>		
** Total number	-	-	
* The "row compile, and is the do mining am	Junt Inno	ler the	HITD Lead Safe Housing Rule (24 CFR

Housing K the Sare under condition" und amount under the HUD in poor "paint not amount is the de minimis 745.223). 35.1350(d)), or the amount of paint that certification ("402") rule (40 CFR 745.2 Jo he "very small" 1350(d)), or the

Notes (including other conditions of concern):

onditions However, specific condition ndition of the dwelling and condition for the lead hazard screen. ourposes of a risk assessment, and conducting a lead hazard screen is not advisable. However a extenuating circumstances should be considered before determining the final condition he appropriateness of a lead hazard screen. If the "Yes" column has any checks, and a lead beformed, describe, below, the extenuating circumstances that justify conducting a lead has usually considered not to be dwelling is If the "Yes" column has any checks, the urposes of a risk assessment, and conducting