Limitations of Inspection

App# 10243 Location	n: 717 HORRINGTON ST or: F. SMON
App# 10243 Location Date: 5/1/37 Inspector	or: F. Smar
Limitations based on access, safety, or availability	ity:
Asbestos Inspection: - Pressumed Roof SNINGLE	S UNDER METAL HOOF
Lead Inspection Risk Assessment:	
General Notes:	