Assessm FEW Risk Hazard for L Condition Building 5.1 Form

property owner: address:_ Property of Name

Rodgers

Elliott

of risk assessor:

sessment: ass of Date

Condition	Yes	No	Comments
Roof missing parts of surfaces (tiles, boards, shakes, etc.)	X		
Roof has holes or large cracks	X		
Gutters or downspouts broken	>		
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting	X		
Exterior siding has missing boards or shingles	X		
Water stains on interior walls or ceilings	X		
Walls or ceilings deteriorated	X		
More than "very small" amount of paint in a room deteriorated	X		
Two or more windows or doors broken, missing, or boarded up		X	
Porch or steps have major elements broken, missing, or boarded up		X	
Foundation has major cracks, missing material, structure leans, or visibly unsound		X	
** Total number	00	1	

training and Rule Safe Housing under ead "paint in poor condition" under the HUD I "very small" amount is the de minimis amount not paint that 18 no. CFR 745.223). certification ("402") rule (40 CFR of amount 35.1350(d)), or the

condition purposes of a risk assessment, and conducting a lead hazard screen is not advisable. However and extenuating circumstances should be considered before determining the final condition the appropriateness of a lead hazard screen. If the "Yes" column has any checks, and a lead performed, describe, below, the extenuating circumstances that justify conducting a lead has a lead has a second to be a lead has a in Fifthe "Yes" column has any checks, the dwelling is usually considered not to be purposes of a risk assessment, and conducting a lead hazard screen is not advisable

lotes (including other conditions of concern);