assess ssessmen Jo Date Risk ead Hazard Thir Ma for For dittion Elliott of property owner: of risk assessor: Ell Building address: 5.1 Form.
Property of Name

Condition	Yes	No	Comments
Roof missing parts of surfaces (tiles, boards, shakes, etc.)	>		
Roof has holes or large cracks	X		
Gutters or downspouts broken	X		
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		\ \	
Exterior or interior walls have obvious large cracks or holes, requiring more than routine pointing (if masonry) or painting	>		
Exterior siding has missing boards or shingles	X		
Water stains on interior walls or ceilings	X		
Walls or ceilings deteriorated	X		
More than "very small" amount of paint in a room deteriorated	X		
Two or more windows or doors broken, missing, or boarded up		×	
Porch or steps have major elements broken, missing, or boarded up		X	
Foundation has major cracks, missing material, structure leans, or visibly unsound		X	
** Total number	3	7	

" under the EPA poor condition" The "very small" amount is the de minimis amount under the HUD L 35.1350(d)), or the amount of paint that is not "paint in poor condition" certification ("402") rule (40 CFR 745.223).

purposes of a risk assessment, and conducting a lead hazard screen is not advisable. He and extenuating circumstances should be considered before determining the final cond the appropriateness of a lead hazard screen. If the "Yes" column has any checks, and a performed, describe, below, the extenuating circumstances that justify conducting a lead

Notes (including other conditions of concern):