Assessment Risk Hazard Lead Forn Condition Building 5.1

°Z assessment: Jo Date 3 Elliott Rodgers me of property owner: of risk assessor: address:_ Forn.
Property
Name of
Name of

		The state of the s	
Condition	Yes	No	Comments
Roof missing parts of surfaces (tiles, boards, shakes, etc.)		X	
Roof has holes or large cracks		2	
Gutters or downspouts broken		X	
Chimney masonry cracked, bricks loose or missing, obviously out of plumb		X	
or into		X	
Exterior siding has missing boards or shingles		X	
Water stains on interior walls or ceilings		X	
Walls or ceilings deteriorated		×	
More than "very small" amount of paint in a room deteriorated	X	*	
Two or more windows or doors broken, missing, or boarded up		X	
Porch or steps have major elements broken, missing, or boarded up		X	
Foundation has major cracks, missing material, structure leans, or visibly unsound		X	
** Total number		-	
* The Warmy complete the designation of			1

lead training and Housing Rule (24 CFR
ne EPA lead training and the amount under the HUD Lead Safe t "paint in poor condition" under th not The "very small" amount is the de minimis 5.1350(d)), or the amount of paint that is no ertification ("402") rule (40 CFR 745.223).

concern); other conditions (including

conditions dwelling and d screen is to b for the urposes of a risk assessment, and conducting a lead hazard screen is not advisable. However, specific conditions of the dwelling of extenuating circumstances should be considered before determining the final condition of the dwelling the appropriateness of a lead hazard screen. If the "Yes" column has any checks, and a lead hazard screen erformed, describe, below, the extenuating circumstances that justify conducting a lead hazard screen. condition in good conc.

le. However, spec dwelling is usually considered not to be in ting a lead hazard screen is not advisable. If the "Yes" column has any checks, the purposes of a risk assessment, and conducand extenuating circumstances should be