Fontaneria Rapida S.L. - Repair estimate

SYNTHETIC DEMO DOCUMENT - fictional company and figures, generated for a take-home assignment.

Estimate no. E-2026-1147 Date: 2026-10-09

Client: policy HOME-55821, bedroom ceiling, Madrid

Findings: water ingress from the upper floor bathroom supply pipe. Plaster saturated over approx. 9 m2. Ceiling light fitting wet; electrical check recommended before re-energising the circuit.

1. Removal of damaged plaster and drying (dehumidifier, 5 days) ..... EUR 1,150.00
2. New plasterboard ceiling, 9 m2 ..... EUR 1,620.00
3. Painting of ceiling and walls ..... EUR 780.00
4. Electrician inspection and new ceiling light fitting ..... EUR 800.00

TOTAL (VAT included) ..... EUR 4,350.00