Profile: rot | Shot: 206584 | Tau: 20



Actuator Signals | Shot: 206584 | Tau: 1500










Profile: rot | Shot: 206585 | Tau: 20
rad idx 0
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
signal
target
Time (ms)


Actuator Signals | Shot: 206585 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
2.5
2.0
1.5
1.0
0.5
0.0
0
1000
2000
3000
4000
5000
6000
Time (ms)
off_axis_pwr
1e6
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
Time (ms)
gasA
4
3
2
1
0
Time (ms)
echpwrc
0.04
0.02
0.00
−0.02
−0.04
Time (ms)

Profile: etemp | Shot: 206586 | Tau: 20




Actuator Signals | Shot: 206586 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
3.0
2.5
2.0
1.5
1.0
0.5
0.0
0
1000
2000
3000
4000
5000
6000
Time (ms)
off_axis_pwr
1e6
1.4
1.2
1.0
0.8
0.6
0.4
0.2
0.0
Time (ms)
gasA
4
3
2
1
0
Time (ms)
echpwrc
400000
300000
200000
100000
0
Time (ms)

Profile: etemp | Shot: 206587 | Tau: 20



Actuator Signals | Shot: 206587 | Tau: 1500










Profile: etemp | Shot: 206588 | Tau: 20
rad idx 0
signal
target
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
Time (ms)

Actuator Signals | Shot: 206588 | Tau: 1500









Profile: etemp | Shot: 206589 | Tau: 20




Actuator Signals | Shot: 206589 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)


Profile: rot | Shot: 206590 | Tau: 20
rad idx 0
signal
target
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
Time (ms)


Actuator Signals | Shot: 206590 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)

Profile: rot | Shot: 206591 | Tau: 20




Actuator Signals | Shot: 206591 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)

Profile: pres | Shot: 206592 | Tau: 20



Actuator Signals | Shot: 206592 | Tau: 1500










Profile: pres | Shot: 206593 | Tau: 20
rad idx 0
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
signal
target
Time (ms)


Actuator Signals | Shot: 206593 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)


Profile: pres | Shot: 206594 | Tau: 20
rad idx 0
signal
target
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
Time (ms)

Actuator Signals | Shot: 206594 | Tau: 1500



Profile: pres | Shot: 206595 | Tau: 20
rad idx 0
signal
target
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
Time (ms)


Actuator Signals | Shot: 206595 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)


Profile: pres | Shot: 206596 | Tau: 20
rad idx 0
signal
target
rad idx 5
rad idx 10
rad idx 15
rad idx 20
rad idx 25
rad idx 30
Time (ms)


Actuator Signals | Shot: 206596 | Tau: 1500
on_axis_pwr
1e6
on_axis_pwr
Time (ms)
off_axis_pwr
1e6
Time (ms)
gasA
Time (ms)
echpwrc
Time (ms)