

041500 UTC DEC 25

NAVAREA IX 566/25

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751) AND BA 707

1. NAVAL SHIPS WILL CONDUCT LIVE SURFACE AND
SUBSURFACE FIRING FROM 0300 TO 1900 UTC ON
06 DEC 25 IN FOLLOWING AREAS:

A. 24-24.30N 066-42.00E 24-19.00N 066-58.00E 24-00.00N 066-39.00E 24-11.00N
066-27.00E B. 24-22.00N 066-27.00E 24-16.30N 066-33.00E 24-10.30N 066-27.00E
24-16.18N 066-20.50E MARINERS KEEP WELL CLEAR OFF EXERCISE AREA

2. CANCEL THIS MSG 062000 UTC DEC 25

031500 UTC DEC 25

NAVAREA IX 565/25

SOUTHERN GULF

UAE, DUBAI

CHARTS BA 3175, 3176 AND 3412

ANCHORAGE AREA ESTABLISHED IN AREA
BOUNDED BY FOLLOWING COORDINATES:

25-25.94N 055-11.92E 25-25.04N 055-10.08E 25-23.84N 055-11.47E 25-24.80N 055-13.36E
MARINERS CAUTIONED

011500 UTC DEC 25

NAVAREA IX 564/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA PIPELINE INSTALLATION WILL BE CONDUCTED
FROM 02 DEC 25 TO 15 JAN 26 BY DERRICK BARGE 30
(DB30) IN AREA BOUNDED BY FOLLOWING COORDINATES:
A. 26 23.52N 052-13.83E B. 26-24.67N 052-14.99E C. 26-25.67N 052-17.14E D. 26-22.73N
052-18.90E E. 26-20.76N 052-17.61E F. 26-21.39N 052-13.38E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 524/25

301100 UTC NOV 25

NAVAREA IX 563/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

MOORING BUOY MO"U".15S PERMANENTLY DEPLOYED IN POSITION
26-42.32N 051-52.06E MARINERS CAUTIONED

291500 UTC NOV 25

NAVAREA IX 561/25

CENTRAL GULF

BAHRAIN

CHARTS BA 3734, 3736, AND 3737

BUOY K-1 AT 26-10.53N 050-42.56E REPORTED OFF POSITION

MARINERS CAUTIONED

290300 UTC NOV 25

NAVAREA IX 560/25

SELF CANCELLING

NAVIGATIONAL WARNINGS INFORCE:

2021 SERIES: 109, 397, 399, 445, 448, 490 AND 491

2022 SERIES: 027, 039, 067, 095, 102, 112, 185, 198, 220, 294, 295, 311, 328, 331, 358, 443, 477, 480, 489, 497, 507 AND 513

2023 SERIES: 028, 034, 058, 067, 068, 071, 094, 096, 111, 116, 159, 177, 190, 221, 226, 293, 307, 314, 318, 326, 338, 341, 346, 355, 376, 435, 447, 448, 453 AND 475

2024 SERIES: 042, 048, 076, 094, 103, 115, 130, 132, 139, 140, 141, 163, 168, 198, 200, 240, 250, 253, 267, 281, 285, 288, 289, 299, 311, 329, 333, 340, 361, 362, 363, 365, 382, 399, 402, 403, 432, 452, 476, 486, 488, 501, 509, 519, 529 AND 531

2025 SERIES: 002, 006, 014, 018, 021, 024, 047, 063, 066, 071, 090, 101, 111, 147, 158, 176, 185, 216, 218, 227, 246, 250, 254, 256, 261, 267, 272, 280, 287, 289, 292, 297, 300, 321, 325, 328, 331, 332, 335, 339, 349, 352, 353, 356, 365, 375, 377, 379, 387, 399, 405, 418, 434, 439, 440, 441, 442, 443, 448, 450, 453, 458, 463, 467, 477, 481, 484, 485, 505, 516, 522, 524, 526, 529, 530, 535, 542, 546, 548, 550, 553, 554, 557, 558 AND 559

281500 UTC NOV 25

NAVAREA IX 559/25

SOUTHERN GULF

UAE

CHART BA 3174

BREAKWATER REPLACEMENT OPERATION

WILL BE CARRIED OUT BETWEEN

FOLLOWING COORDINATES:

A. 25-41.63N 055-45.22E B. 25-41.45N 055-45.03E MARINERS CAUTIONED

271500 UTC NOV 25

NAVAREA IX 557/25

SOUTHERN GULF

UAE

CHARTS BA 3520, 3709 AND 3723

YACHT KRANOS SUNK IN POSITION 25-06.49N 056-24.32E WITH LEAST DEPTH 12 METERS
MARINERS CAUTIONED

271500 UTC NOV 25

NAVAREA IX 554/25

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 38 AND 707

1. NAVAL SHIPS WILL CONDUCT LIVE FIRING PRACTICE

BETWEEN 0300 TO 1900 UTC FROM 01-05, 08-12, 15-19,

22-26 AND 29-31 DEC 25 IN FOLLOWING AREAS:

A. 24-24.30N 066-42.00E 24-19.00N 066-58.00E 24-00.00N 066-39.00E 24-11.00N

066-27.00E B. 24-36.02N 062-30.03E 24-36.02N 063-15.03E 24-21.02N 063-15.03E

24-21.02N 062-30.03E C. 24-36.02N 061-45.03E 24-36.02N 062-30.03E 24-21.02N

062-30.03E 24-21.02N 061-45.03E D. DEPTH CHARGE FIRING AREA

24-22.00N 066-27.00E 24-16.30N 066-33.00E 24-10.30N 066-27.00E 24-16.18N 066-20.50E

MARINERS KEEP WELL CLEAR OFF EXERCISE AREAS

2. CANCEL THIS MSG 312000 UTC DEC 25

262000 UTC NOV 25

NAVAREA IX 553/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

GEOPHYSICAL SURVEY WILL BE CONDUCTED BY ASTRO AQUILA UNTIL

31 DEC 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:

26-42.5N 051-53.5E 26-40.1N 051-57.2E 26-36.2N 051-58.7E 26-39.2N 051-52.9E MARINERS

CAUTIONED

251500 UTC NOV 25

NAVAREA IX 550/25

CENTRAL GULF

QATAR

CHARTS BA 2886, 3781, 3790 AND 3950

1. SUBSEA PIPELINE INSTALLATION OPERATION WILL

BE CONDUCTED FROM 26 NOV TO 03 DEC 25 BY

BARGE MC DERMOTT (DB32) SUPPORTED BY MULTI VESSELS

IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 25-59.67N 051-54.25E B. 25-59.26N 051-59.01E C. 25-56.53N 051-58.78E D. 25-56.93N

051-53.02E E. 25-57.27N 051-52.26E MARINERS CAUTIONED

2. CANCEL THIS MSG 032359 UTC DEC 25

251500 UTC NOV 25

NAVAREA IX 548/25

SOUTHERN GULF

UAE

CHARTS BA 2889, 3179 AND 3951

1. WAVE RIDER BUOY PTM-61182 WITH CHARACTERISTICS

FL.Y.2S TEMPORARILY MOVED FROM POSITION 24-38.58N 052-35.32E TO 24-38.68N 052-35.37E

2. WAVE BUOY PTM-6376 WITH CHARACTERISTICS FL.Y.2S

TEMPORARILY DEPLOYED IN POSITION 24-39.13N 052-35.55E MARINERS CAUTIONED
3. CANCEL NAVAREA IX 388/25

221500 UTC NOV 25

NAVAREA IX 546/25

PERSIAN GULF, KHOWR E MUSA

IRAN

CHARTS GB 2884 (INT 7278) AND ENC IR308760

CHANNEL ESTABLISHED FROM PORT HAND BUOY NO 14 TO PORT

HAND BEACON NO 32 WITH DEPTH 9M AND LENGTH 14.5NM

JOINING FOLLOWING COORDINATES:

1. 29-54.51N 049-09.68E 2. 29-57.00N 049-05.14E 3. 30-00.18N 049.01.55E
4. 30-05.35N 048-59.32E 5. 30-05.41N 048-59.49E 6. 30-04.60N 048-59.91E 7. 30-00.30N
049-01.76E 8. 29-57.15N 049-05.31E 9. 29-54.69N 049-09.82E MARINERS CAUTIONED

211500 UTC NOV 25

NAVAREA IX 542/25

PAKISTAN

PORT MUHAMMAD BIN QASIM CHANNEL

CHARTS PAK 20 (INT 7316) AND BA 59

1. MAXIMUM PERMISSIBLE DRAUGHTS/ DIMENSIONS FOR SHIPS CALLING AT
PORT MUHAMMAD BIN QASIM TILL 15 MAY 26 ARE AS UNDER:

BERTH	PERMISSIBLE DRAUGHT (METER)	LENGTH OVER ALL (METER)	BEAM (METER)
LCT	10*	210	33
MW-1	9.5	225	33
MW-2	10	225	33
MW-3	10	225	33
MW-4	10.5*	225	33
QICT-I (BERTH NO 5)	12**	UP TO 310	48
QICT-I (BERTH NO 5)	12**	MORE THAN 310 AND UP TO 340	46.5
QICT-I (BERTH NO 7)	12.5**	UP TO 310	48
QICT-I (BERTH NO 7)	12.5**	MORE THAN 310 AND UP TO 340	46.5
QICT-II	13	UP TO 310	48
QICT-II	13	MORE THAN 310 AND UP TO 340	46.5
FAP (GRAIN AND FERTILIZER)	13 (MAXDWT 75000 TONS)	250	43.5
EVTL-13	11	225	40
IOCB	12 (MAX DWT 75000 TONS)	230	40
EETL (LNG-1)	12***	295	43.4

PGPC (LNG-2)	12***	295	43.4
FOTCO OIL TERMINAL	13 (MAX DWT 75000 TONS)	245	42
SSGC/LPG	10	163	33
PIBT	13	230	33
PQEPC	12	210	33

TERMINAL

* VESSELS MORE THAN 9.5 METER AND UPTO 10 METER DRAUGHT AT LCT TERMINAL AND VESSELS MORE THAN 10 METER AND UPTO 10.5 METER

DRAUGHT AT MW-4 WILL BE ALLOWED BY TAKING BENEFIT OF TIDE

** VESSELS MORE THAN 11.5 METER AND UPTO 12 METER DRAUGHT AT QICT-I (BERTH NO 5) AND VESSELS MORE THAN 12 METER AND UPTO 12.5 METER DRAUGHT AT QICT-I (BERTH NO 7) WILL BE ALLOWED BY TAKING BENEFIT OF TIDE

*** LNG Q-FLEX CALLING TO EETL TERMINAL UNDER DISPENSATION ARE ALLOWED FROM 16 SEP TO 15 MAY UPTO DRAUGHT OF 11.5 METER

2. CANCEL THIS MSG 16 MAY 26

151130 UTC NOV 25

NAVAREA IX 535/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SEISMIC ACQUISITION OPERATION WILL BE CONDUCTED ON 16 NOV 25 BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:

AREA 32

A. 26-48.08N 051-53.95E B. 26-43.32N 051-59.79E C. 26-41.03N 051-57.46E D. 26-43.62N 051-54.28E E. 26-47.28N 051-53.15E AREA 31

A. 26-36.98N 051-55.50E B. 26-36.40N 051-58.27E C. 26-32.34N 052-02.84E D. 26-31.40N 052-03.39E E. 26-30.04N 052-03.03E F. 26-25.31N 051-59.36E G. 26-27.18N 051-57.07E

H. 26-32.72N 051-54.19E MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND KEEP CLEAR FROM MENTIONED AREA

2. CANCEL NAVAREA IX 394/24

111500 UTC NOV 25

NAVAREA IX 530/25

CENTRAL GULF

QATAR

CHARTS BA 2886, 3781, 3790 AND 3950

1. SUBSEA PIPELINE INSTALLATION OPERATION WILL BE CONDUCTED FROM 12 TO 26 NOV 25 BY BARGE MC DERMOTT (DB32) IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 25-58.99N 051-51.38E B. 25-59.94N 051-53.48E C. 25-58.75N 052-00.93E D. 25-57.48N 052-03.12E E. 25-56.12N 052-01.87E F. 25-57.10N 051-53.10E 2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

GIVE WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

101500 UTC NOV 25
NAVAREA IX 529/25
SOUTHERN GULF
UAE, RAS AL KHAIMAH
CHARTS BA 2888, 3174 AND 3175

1. SINKER PIPELINE TEMPORARILY WET STORED BETWEEN AL MARJAN ISLAND AND AL JAZEERA PORT
RESTRICTED AREA AROUND PIPELINE DESIGNATED BY FOLLOWING CARDINAL BUOYS:
NORTH CARDINAL BUOY 25-43.05N 055-45.82E EAST CARDINAL BUOY 25-42.87N
055-46.38E SOUTH CARDINAL BUOY 25-42.51N 055-46.24E WEST CARDINAL BUOY
25-42.70N 055-45.68E MARINERS CAUTIONED
 2. CANCEL NAVAREA IX 337/25
-

090745 UTC NOV 25
NAVAREA IX 526/25
CENTRAL GULF
QATAR
CHARTS BA 2523, 2883 AND 2886
SPM BUOY NO 3 IN POSITION 26-38.81N 051-53.50E REPORTED UNLIT MARINERS CAUTIONED

051400 UTC NOV 25
NAVAREA IX 522/25
ARABIAN SEA
PAKISTAN
CHARTS PAK 33, 57(INT 751) AND BA 39

FISHING VESSEL MASHAALLAH SUNK IN POSITION
23-02.00N 067-24.00E AND REPORTED MAN OVER BOARD(.)
VESSELS TRANSITING THE AREA ARE REQUESTED TO KEEP A SHARP
LOOKOUT AND RENDER ASSISTANCE

021500 UTC NOV 25
NAVAREA IX 516/25
GULF OF OMAN
OMAN
CHARTS BA 2837, 3171 AND 3520
1. CABLE INSTALLATION OPERATION IN PROGRESS BY VESSEL
C/S ILE DE BATZ ALONG THE LINE JOINING FOLLOWING POINTS:
WP1 25-39.58N 056-46.23E WP2 25-30.70N 056-48.90E WP3 25-24.20N 056-52.10E WP4
25-22.60N 056-51.60E WP5 25-20.40N 056-50.30E WP6 25-18.20N 056-49.10E WP7
25-15.40N 056-48.30E WP8 25-12.50N 056-48.40E WP9 25-07.10N 056-45.30E WP10
25-03.10N 056-42.50E WP11 25-00.60N 056-41.40E 2. MARINERS ARE REQUESTED TO NAVIGATE
WITH CAUTION
GIVE WIDE BERTH OF 1NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

281500 UTC OCT 25

NAVAREA IX 505/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA INSTALLATION OF BRIDGES, BOLLARDS AND PRELAY ROUTE SURVEY ACTIVITIES
IN PROGRESS BY DSV CONSTRUCTOR IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 26-28.58N 051-43.78E B. 26-30.36N 051-45.47E C. 26-34.44N 051-49.35E D. 26-35.50N
051-50.33E E. 26-36.76N 051-53.24E F. 26-37.50N 051-57.94E G. 26-37.30N 051-58.18E
H. 26-38.11N 051-58.54E I. 26-38.11N 051-58.54E J. 26-36.98N 051-58.59E K. 26-36.69N
051-58.20E 2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

171500 UTC OCT 25

NAVAREA IX 485/25

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 2884 AND 3773

BATHYMETRIC SURVEY IN PROGRESS BY VESSEL SEALINE-8

ALONG FOLLOWING POSITIONS:

A. 29-07.20N 048-08.23E B. 29-06.85N 048-08.34E C. 29-07.34N 048-08.76E D. 29-07.01N
048-08.88E MARINERS CAUTIONED

171500 UTC OCT 25

NAVAREA IX 484/25

SOUTHERN GULF

UAE

CHARTS BA 2889, 3177 AND 3178

1. PIPELINE INSTALLATION OPERATION IN PROGRESS BY MULTI
VESSELS TILL 15 FEB 26 ALONG LINE JOINING:

START POINT 24-30.82N 054-01.29E END POINT 24-53.45N 053-03.62E 2. MARINERS ARE
REQUESTED TO NAVIGATE WITH CAUTION AND
MAINTAIN LISTENING WATCH ON VHF CHANNEL 23 AND 12

151500 UTC OCT 25

NAVAREA IX 481/25

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 3773 AND KU CHART 01

MOORING BUOY SIB IN POSITION 29-06.72N 048-17.54E FL(4).Y.20 SEC TEMPORARILY
WITHDRAWN

MARINERS CAUTIONED

141500 UTC OCT 25

NAVAREA IX 477/25

SOUTHERN GULF

UAE DELMA ISLAND

CHARTS BA 2837 AND 3951

BATHYMETRIC SURVEY OPERATION WILL BE CONDUCTED BY VESSELS BLUE WAVES,
OWN OCEAN DEZIRE UNTIL 30 OCT 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:
A. 24-30.00N 052-15.00E B. 24-20.00N 052-15.00E C. 24-20.00N 052-23.00E D. 24-30.00N
052-23.00E MARINERS ARE REQUESTED TO NAVIGATE WITH EXTREME CAUTION

091500 UTC OCT 25

NAVAREA IX 467/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886 AND 3950

1. TOPSIDE INSTALLATION OPERATION IN PROGRESS BY VESSELS

MCDERMOTT DB50, WISH WAY AND SUPPORT VESSELS IN AREA

BOUNDED BY FOLLOWING COORDINATES:

A. 25-53.06N 051-54.04E B. 25-52.98N 051-57.03E C. 25-50.90N 051-57.04E D. 25-50.88N
051-54.03E 2. WAVERIDER BUOY INSTALLED IN POSITION 25-51.80N 051-56.08E AND MOORING
BUOY INSTALLED IN POSITION 25-51.55N 051-54.83E MARINERS CAUTIONED

071500 UTC OCT 25

NAVAREA IX 463/25

SOUTHERN GULF

UAE

CHARTS BA 2888 AND 2889

1. SPECIAL MARK BUOYS WITH FLASHING YELLOW LIGHTS TEMPORARILY
RELOCATED TO FOLLOWING POSITIONS:

UID01	25-19.91N 054-49.78E	UID02	25-25.75N 054-52.53E	UID03	25-22.64N
054-48.64E	UID04	25-25.98N 054-48.35E	MARINERS CAUTIONED		

2. CANCEL NAVAREA IX 429/25

050300 UTC OCT 25

NAVAREA IX 458/25

SOUTHERN GULF

UAE

CHARTS BA 2889 AND 2444

ZAQQUM LIGHT BUOY IN POSITION 25-06.56N 053-25.06E REPORTED RACON
NOT OPERATIONAL AND LANTERN FLASH CHARACTERISTIC MALFUNCTIONING
MARINERS CAUTIONED

031500 UTC OCT 25

NAVAREA IX 453/25

NORTHERN GULF

KUWAIT

CHARTS BA 1214, 1235, 2884, 3773 AND KU 1

1. AIDS TO NAVIGATION DEVELOPMENT AND SEABED SURVEY OPERATION
WILL BE CONDUCTED BY MULTI VESSELS IN FOLLOWING AREAS:

DOHA

A. 29-23.68N 047-52.47E B. 29-23.70N 047-54.25E C. 29-21.43N 047-54.10E D. 29-21.44N 047-52.45E FAYLAKA ISLAND
A. 29-32.84N 048-37.57E B. 29-32.84N 048-12.26E C. 29-21.40N 048-12.22E D. 29-21.40N 048-37.66E BUBIYAN ISLAND
A. 29-43.37N 048-34.40E B. 29-29.47N 048-11.35E C. 29-56.87N 047-56.01E D. 30-01.12N 048-09.46E 2. TEMPORARY SPECIAL MARK BUOYS WILL BE DEPLOYED DURING MAINTENANCE OF AIDS TO NAVIGATION MARINERS CAUTIONED

011500 UTC OCT 25

NAVAREA IX 450/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886 AND 3950

1. ROV SURVEY OPERATION IN PROGRESS BY VESSEL HALUL-51 TILL 31 DEC 25 ALONG THE FOLLOWING ROUTES:

MIDSTREAM LINE ROUTE (QATAR TO UAE)

A. 25-56.62N 051-31.25E B. 25-59.28N 051-32.78E C. 25-57.08N 051-48.39E D. 25-52.38N 052-02.00E E. 25-23.11N 053-01.96E F. 25-25.66N 053-27.76E G. 24-49.99N 054-36.08E

H. 24-45.45N 054-40.17E UPSTREAM ROUTE (QATAR)

A. 25-56.52N 051-31.18E B. 25-57.49N 051-31.76E C. 25-59.13N 051-32.71E D. 26-06.28N 051-55.03E E. 26-09.27N 052-02.43E F. 26-12.25N 052-07.25E G. 26-14.79N 052-09.74E

H. 26-17.32N 052-12.24E I. 26-19.15N 052-14.45E J. 26-19.34N 052-14.67E 2. MARINERS

ARE REQUESTED TO NAVIGATE WITH CAUTION AND

GIVE WIDE BERTH OF 2NM

010900 UTC OCT 25

NAVAREA IX 448/25

ARABIAN GULF

SAUDI ARABIA

CHARTS BA 3777, 3788 AND 3812

LIFE BOAT REPORTED MISSING FROM MV CELINA (IMO NO 9306378)

IN VICINITY OF POSITION 26-34.66N 050-19.48E MARINERS

CAUTIONED

291500 UTC SEP 25

NAVAREA IX 443/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA PIPELINE INSTALLATION OPERATION IN PROGRESS TILL 15 OCT 25 BY DERRICK BARGE 30 ASSISTED BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:

26-31.76N 051-59.05E 26-28.89N 051-56.09E 26-30.47N 051-54.03E 26-33.08N 051-56.71E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16
3. CANCEL NAVAREA IX 433/25

291500 UTC SEP 25
NAVAREA IX 442/25
NORTHERN GULF
KUWAIT
CHARTS BA 1214, 3773 AND KU 1
SEABED SURVEY IN PROGRESS BY MULTI VESSELS ALONG FOLLOWING POSITIONS:
MPA-1 29-21.17N 047-50.56E MPA-2 29-20.63N 047-50.71E MPA-3 29-21.56N 047-50.78E
MPA-4 29-21.18N 047-53.23E LTMP-1 29-21.61N 047-52.35E LTMP-2 29-24.78N
047-54.45E LTMP-3 29-25.82N 048-05.31E MARINERS CAUTIONED

291500 UTC SEP 25
NAVAREA IX 441/25
PERSIAN GULF
IRAN
CHARTS BA 2883 AND IR 3059(INT 7247)
FOLLOWING AIDS TO NAVIGATION ESTABLISHED:
A. PORT HAND BEACON TOWER WITH TOPMARK FL (2) 5SEC 3M IN POSITION
27-09.70N 052-54.70E B. SAFEWATER PILLAR BUOY WITH TOPMARK ISO 4SEC 5M IN POSITION
27-08.45N 052-55.27E C. STARBOARD HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M IN
POSITION 27-09.21N 052-55.24E D. PORT HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M
IN POSITION
27-09.12N 052-55.02E E. STARBOARD HAND PILLAR BUOY WITH TOPMARK FL (2) 5SEC 3M IN
POSITION 27-09.75N 052-54.92E MARINERS CAUTIONED

281500 UTC SEP 25
NAVAREA IX 440/25
RED SEA
SAUDI ARABIA, YANBU INDUSTRIAL PORT
CHARTS BA 158, 326 AND 328
BUOY NO (W) IN POSITION 23-55.00N 038-12.52E REPORTED MISSING MARINERS CAUTIONED

271500 UTC SEP 25
NAVAREA IX 439/25
CENTRAL GULF
QATAR
CHARTS BA 3772, 2523 AND 2886
ROV OPERATION WILL BE CONDUCTED BY VESSEL HALUL 51 FROM 28 SEP 25 ALONG
FOLLOWING POSITIONS:
A. 25-57.32N 051-30.13E B. 26-00.68N 051-32.25E C. 26-05.20N 051-33.73E D. 26-07.22N
051-31.83E E. 26-12.43N 051-32.97E F. 26-17.26N 051-34.91E G. 26-27.66N 051-42.79E
H. 26-36.89N 051-51.65E I. 26-36.89N 051-56.43E J. 26-38.11N 051-57.58E MARINERS
CAUTIONED

241500 UTC SEP 25

NAVAREA IX 434/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

1. SUBSEA PIPELINE INSTALLATION OPERATION WILL BE CONDUCTED BY NON-PROPELLED BARGE MC DERMOTT DB32 SUPPORTED BY MULTI VESSELS IN POSITION 25-57.00N 051-32.50E FROM 24 SEP TO 15 OCT 25

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

151500 UTC SEP 25

NAVAREA IX 418/25

SOUTHERN GULF

UAE

CHARTS BA 3520, 3709 AND 3723

1. FUJAIRAH BEACON FL 5 SECONDS 176 METERS 20M SHIFTED PERMANENTLY TO POSITION 25-10.61N 056-20.76E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 515/24

031500 UTC SEP 25

NAVAREA IX 405/25

PAKISTAN

KARACHI APPROACHES

CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40

CHANNEL BUOY S-13 24-46.84N 066-59.38E REPORTED

MISSING MARINERS CAUTIONED

011500 UTC SEP 25

NAVAREA IX 399/25

CENTRAL GULF

QATAR

CHARTS BA 2886

1. SUBSEA PIPELINE INSTALLATION OPERATION IN PROGRESS TILL 15 DEC 25

BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:

26-22.70N 051-33.50E 26-27.30N 052-27.80E 25-46.90N 052-27.30E 25-46.30N 051-42.90E

25-57.70N 051-24.40E 2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION GIVE WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 12 AND 16

261500 UTC AUG 25

NAVAREA IX 387/25

SOUTHERN GULF

UAE

CHARTS BA 2837, 2889 AND 3412

1. RESTRICTED AREA ESTABLISHED IN OFFSHORE

UMM SUQEIM COASTAL AREA BOUNDED BY FOLLOWING COORDINATES:

A. 25-11.20N 055-11.36E B. 25-11.75N 055-11.80E C. 25-11.52N 055-12.90E D. 25-10.60N

055-12.90E E. 25-10.32N 055-12.59E F. 25-10.06N 055-11.88E G. 25-10.15N 055-11.56E

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

AND KEEP CLEAR FROM MENTIONED AREA

3. CANCEL NAVAREA IX 278/25

221500 UTC AUG 25

NAVAREA IX 379/25

SOUTHERN GULF

UAE

CHARTS BA 2889 AND 3176

1. RESTRICTED AREA ESTABLISHED IN VICINITY
OF BURJ AL ARAB AND MADINAT JUMEIRAH BOUNDED
BY FOLLOWING COORDINATES:

A. 25 07.99N 055 10.77E B. 25 08.29N 055 10.63E C. 25 08.98N 055 11.22E D. 25 08.91N

055 11.38E 2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

AND KEEP CLEAR FROM MENTIONED AREA.

201500 UTC AUG 25

NAVAREA IX 377/25

CENTRAL GULF

QATAR

CHARTS BA 2523, 2886, 3772 AND 3950

1. PIPELINE INSPECTION OPERATION WILL BE CONDUCTED
BY VESSELS FUGRO PEGASUS AND LADY BEATRICE IN AREA
BOUNDED BY FOLLOWING COORDINATES:

25-57.72N 051-30.12E 26-01.68N 051-32.30E 26-01.72N 051-42.03E 26-05.41N 051-57.83E

26-10.95N 052-04.10E 26-08.01N 052-06.08E 26-03.04N 051-59.50E 25-59.06N 051-42.56E

25-59.05N 051-33.09E 25-56.59N 051-32.06E 2. MARINERS ARE REQUESTED TO GIVE WIDE

BERTH

AND MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

131500 UTC AUG 25

NAVAREA IX 375/25

CENTRAL GULF

QATAR, AL SHAHEEN FIELD

CHARTS BA 2523, 2837, 2883, AND 2886

PIPE LAYING AND SLEEPERS INSTALLATION OPERATION WILL BE CONDUCTED

ON 14 AUG 25 BY MULTI VESSELS IN AREA BOUNDED BY FOLLOWING COORDINATES:

26-18.90N 051-48.90E 26-37.70N 051-51.00E 26-42.50N 051-53.50E 26-40.20N 052-00.70E

26-35.60N 052-00.40E MARINERS CAUTIONED

031500 UTC AUG 25

NAVAREA IX 365/25

PAKISTAN

KARACHI APPROACHES
CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40
CHANNEL BUOY S-3 24-44.30N 066-57.14E REPORTED MISSING
MARINERS CAUTIONED

251500 UTC JUL 25
NAVAREA IX 356/25
SOUTHERN GULF
UAE
CHARTS BA 2889, 3179 AND 3413
YELLOW MOORING BUOY IN POSITION 25-07.24N 052-53.04E REPORTED UNLIT MARINERS
CAUTIONED

221500 UTC JUL 25
NAVAREA IX 353/25
CENTRAL GULF
QATAR
CHARTS BA 2523, 2886 AND 3950
CABLE LAYING OPERATION IN PROGRESS BY VESSEL POSH ENDEAVOUR
IN AREA BOUNDED BY FOLLOWING POSITIONS:
A. 25-56.30N 051-34.40E B. 25-58.00N 051-35.33E C. 26-01.87N 052-05.17E D. 26-00.42N
052-05.27E E. 25-57.33N 051-35.80E F. 25-56.13N 051-35.33E MARINERS CAUTIONED

211500 UTC JUL 25
NAVAREA IX 352/25
CENTRAL GULF
QATAR
CHARTS BA 2523, 2886, 2887, AND 2889
1. SUBSEA COMPOSITE CABLE INSTALLATION AND MISCELLANEOUS
ACTIVITIES ARE IN PROGRESS BY MULTI VESSELS IN AREA BOUNDED
BY FOLLOWING POSITIONS:
25-57.71N 051-24.37E 26-22.65N 051-33.50E 26-27.29N 052-27.79E 25-46.92N 052-27.29E
25-46.27N 051-42.91E 2. MARINERS CAUTIONED

171500 UTC JUL 25
NAVAREA IX 349/25
PAKISTAN
GWADAR PORT APPROACHES
CHART PAK 40
CHANNEL BUOY NO 1 FL.Q.G(GREEN) AT 25-06.98N 062-24.16E REPORTED BROKEN MARINERS
CAUTIONED

120830 UTC JUL 25
NAVAREA IX 339/25
RED SEA

CHARTS BA 1, 157 AND 2964

1. MV ETERNITY C (IMO 9588249) REPORTED SUNK IN POSITION 14-42.00N 042-26.00E 10
CREW MEMBERS RESCUED AND REMAINING STILL PRESUMED
IN WATER ALL VESSELS IN VICINITY ARE REQUESTED TO MAINTAIN SHARP
LOOKOUT AND RENDER ASSISTANCE

2. CANCEL NAVAREA IX 333/25

101500 UTC JUL 25

NAVAREA IX 335/25

PAKISTAN

KARACHI APPROACHES

CHARTS PAK 5 (INT 7314), 30 (INT 7315) AND BA 40
CHANNEL BUOY S-7 24-45.49N 066-58.13E REPORTED MISSING
MARINERS CAUTIONED

091500 UTC JUL 25

NAVAREA IX 332/25

SOUTHERN GULF

UAE

BA CHARTS 2889, 3179 AND 3780

1.DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS

PORT IN PROGRESS FOLLOWING NAVIGATIONAL BUOYS TEMPORARILY CHANGED:

GS-12 24-08.54N 052-46.66E TO 24-08.58N 052-46.63E TRB-4 24-08.41N 052-46.87E TO
24-08.39N 052-46.82E 2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND
MAINTAIN LISTENING WATCH ON CHANNEL VHF 21

081500 UTC JUL 25

NAVAREA IX 331/25

PERSIAN GULF

IRAN

CHARTS BA 2523, 2886 AND 2887

FOUR LEGGED JACKET ESTABLISHED AT POSITION 26-18.09N 052-32.92E MARINERS CAUTIONED

080700 UTC JUL 25

NAVAREA IX 328/25

RED SEA

YEMEN

CHARTS BA 6, 143 AND 157

RISK OF EXPLOSION MAY EXIST IN VICINITY OF ATTACKED VESSEL MV MAGIC SEAS

CAUTION AREA ESTABLISHED BOUNDED BY FOLLOWING COORDINATES:

A. 14-38.00N 42-08.00E B. 14-10.00N 42-34.00E C. 14-04.00N 42-26.00E D. 14-30.00N
42-00.00E MARINERS CAUTIONED

071500 UTC JUL 25

NAVAREA IX 327/25

CENTRAL GULF

QATAR

CHARTS BA 2886 AND 3950

1. SEISMIC OPERATION IN PROGRESS BY MULTI VESSELS

IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 25-46.60N 052-04.91E B. 25-41.02N 052-11.67E C. 25-21.60N 051-52.17E D. 25-21.64N
051-45.41E E. 25-23.01N 051-41.28E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 239/25

021500 UTC JUL 25

NAVAREA IX 321/25

IRAN

BANDAR-E KUHESTAK

CHARTS BA 2837, 2888 AND 3173

FOLLOWING ESTABLISHED:

A. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M AT

26-47.91N 057-00.95E B. PORT HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M AT
26-47.93N 057-01.06E MARINERS CAUTIONED

191600 UTC JUN 25

NAVAREA IX 300/25

PORT OF FUJAIRAH

UAE

CHARTS BA 3520 AND 3171

MT ADALYNN IMO 9231767 ANCHORED IN POSITION 25-36.99N 056-24.85E AT
DIBBA ANCHORAGE AREA W REPORTED UNMANNED AND IN COMPLETE BLACKOUT
MARINERS CAUTIONED

191500 UTC JUN 25

NAVAREA IX 297/25

CENTRAL GULF

QATAR

CHARTS BA 2886 AND 3950

SEABED DEBRIS SURVEY WILL BE CONDUCTED BY VESSEL HALUL 83

FROM 19 JUN 25 IN AREA BOUNDED BY FOLLOWING COORDINATES:

25-45.28N 051-56.59E 25-45.28N 051-57.04E 25-44.87N 051-57.04E 25-44.87N 051-56.59E
MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND
MAINTAIN LISTENING WATCH ON VHF CHANNEL 16

171500 UTC JUN 25

NAVAREA IX 292/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 2884 AND 3773

1.RIG ORIENTAL PHOENIX STATIONED ON POSITION 29-14.35N 048-20.56E UNTIL END OF JUN
26(.) RESTRICTED AREA OF 0.5 NM
ESTABLISHED MARINERS CAUTIONED
2.CANCEL NAVAREA IX 262/25

161500 UTC JUN 25
NAVAREA IX 289/25
SOUTHERN GULF
UAE
CHARTS BA 3178 AND 3179
FOLLOWING UNLIT MOORING BUOYS DEPLOYED TEMPORARILY:
7086 24-53.92N 053-01.57E 8995 24-53.85N 053-02.02E 3972 24-53.67N 053-01.96E
MARINERS CAUTIONED

151500 UTC JUN 25
NAVAREA IX 287/25
SOUTHERN GULF
UAE
CHARTS BA 2837, 2888 AND 3174
1. BATHYMETRIC SURVEY WILL BE CONDUCTED FROM 16 JUN 25
BY BOAT ECO-1 IN AREA BOUNDED BY FOLLOWING COORDINATES:
A. 26-01.57N 056-03.68E B. 26-01.31N 056-04.85E C. 26-00.52N 056-04.62E D. 26-00.78N
056-03.45E 2. SPECIAL MARK BOUY TEMPORARILY ESTABLISHED IN POSITION
26-01.12N 056-03.85E MARINERS CAUTIONED

101500 UTC JUN 25
NAVAREA IX 280/25
SOUTHERN GULF
UAE
BA CHARTS 3179, 3780, 3778 AND 3796

1. DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS
PORT IN PROGRESS FOLLOWING NAVIGATIONAL BUOYS
TEMPORARILY WITHDRAWN:
GS-20 24-07.97N 052-46.95E GS-22 24-07.87N 052-46.90E FOLLOWING NAVIGATIONAL BUOYS
TEMPORARILY DEPLOYED:
TRB-5 24-07.69N 052-46.95E Q.R
TRB-6 24-07.59N 052-46.90E FL(3).R.10S

2. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION
AND MAINTAIN LISTENING WATCH ON CHANNEL VHF 21

071500 UTC JUN 25
NAVAREA IX 272/25
RED SEA
SAUDI ARABIA

CHARTS BA 326, 327 AND 328

FOLLOWING BUOYS REPORTED MISSING:

A. BUOY NO.7 23-55.07N 038-09.17E B. BUOY NO.08R 23-54.05N 038-17.22E
MARINERS CAUTIONED

051500 UTC JUN 25

NAVAREA IX 267/25

SOUTHERN GULF

UAE

CHARTS BA 3176 AND 3739

SPECIAL MARK BUOY IN POSITION 25-04.02N 054-48.00E REPORTED UNLIT

MARINERS CAUTIONED

311500 UTC MAY 25

NAVAREA IX 261/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 2884, AND 3773

RESTRICTED AREA ESTABLISHED AT POSITION 29-13.10N 048-44.42E WITH 600 METER DIAMETER
MARINERS CAUTIONED

291500 UTC MAY 25

NAVAREA IX 256/25

RED SEA

SAUDI ARABIA, JEDDAH

CHARTS BA 158, 2599, 2658 AND 2659

BUOY 04W 21-26.80N 039-03.50E REPORTED MISSING

MARINERS CAUTIONED

25-09.98N 052-51.45E 25-09.98N 052-52.14E 25-09.88N 052-52.14E 25-09.57N 052-51.64E

25-09.57N 052-51.45E MARINERS CAUTIONED

291500 UTC MAY 25

NAVAREA IX 254/25

IRAN

BANDAR E LENGEH

CHARTS BA 2441, 2887 AND 2888

ISOLATED DANGER BEACON IN POSITION 26-32.21N 054-57.79E PERMANENTLY DISCONTINUED

ISOLATED DANGER PILLAR

LIGHTBUOY WITH TOPMARK FL(2)6SEC 5 MILES ESTABLISHED

IN POSITION 26-32.31N 054-57.83E MARINERS CAUTIONED

241500 UTC MAY 25

NAVAREA IX 246/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

SELF PROPELLED DP2 VESSEL "HYSY289" WILL BE CARRYING OUT SLEEPERS

INSTALLATION IN FOLLOWING BOUNDED AREA:

A- 26-41.99N 051-53.26E B- 26-41.94N 052-00.75E C- 26-37.65N 052-00.72E D- 26-37.70N
051-53.23E MARINERS CAUTIONED

131500 UTC MAY 25

NAVAREA IX 227/25

RED SEA

SAUDI ARABIA

CHARTS BA 158, 326, 327 AND 328

1. FOLLOWING BUOYS ARE OUT OF SERVICE:

BUOY	TYPE	POSITION
------	------	----------

LIGHT

NAME

CHARACTERISTICS

EAST	EAST CARDINAL BUOY	24-05.90N 037-47.15E Q.(3).10S
------	--------------------	--------------------------------

REEF

S02	LATERAL PORT BUOY	23-27.96N 038-25.86E FL(2)R.5S
-----	-------------------	--------------------------------

10	SOUTH CARDINAL BUOY	23-56.20N 038-11.28E V.Q.(6)+FL.10S
----	---------------------	-------------------------------------

16	SOUTH CARDINAL BUOY	23-54.20N 038-15.15E V.Q.(6)+FL.10S
----	---------------------	-------------------------------------

MARINERS CAUTIONED

2. ISOLATED DANGER BUOY FL(2)5S IN POSITION 23-55.00N 038-12.52E OPERATIONAL

CANCEL NAVAREA IX 454/24

081500 UTC MAY 25

NAVAREA IX 218/25

SOUTHERN GULF

UAE

CHARTS BA 3174 AND 3175

FOLLOWING SPECIAL MARK DATA BUOY ESTABLISHED:

25-44.21N, 055-41.60E QY

MARINERS CAUTIONED

061500 UTC MAY 25

NAVAREA IX 216/25

ARABIAN GULF

SAUDI ARABIA, PORT RAS AL KHAIR

CHARTS BA 2882 AND 3775

FOLLOWING BUOYS REPORTED MISSING:

RAZ-17	27-38.19N 049-17.96E RAZ-18	27-38.11N 049-18.02E MARINERS
--------	-----------------------------	-------------------------------

CAUTIONED

241500 UTC APR 25

NAVAREA IX 185/25

NORTHERN GULF

KUWAIT

CHARTS BA 1235 AND 2884

BATHYMETRIC SURVEY AND EXCAVATION OPERATION WILL BE CONDUCTED ON FOLLOWING POSITIONS:

A. 29-54.04N 048-17.98E B. 29-51.85N 048-21.48E C. 29-51.40N 048-22.03E D. 29-50.68N 048-22.73E E. 29-49.30N 048-22.28E F. 29-51.52N 048-19.54E G. 29-53.77N 048-17.68E TIDE STATION (T), CURRENT OBSERVATION PROFILE (C) AND WAVE OBSERVATION STATION (WA) WILL BE INSTALLED IN FOLLOWING POSITIONS:

T1 29-36.12N 048-10.44E T2 29-59.21N 048-07.90E T3 29-51.96N 048-19.95E T4 29-48.58N 048-23.78E C1 29-36.12N 048-10.44E C2 29-59.21N 048-07.90E C3 29-53.24N 048-19.03E WA 29-48.58N 048-23.78E MARINERS CAUTIONED

201500 UTC APR 25

NAVAREA IX 176/25

RED SEA

SAUDI ARABIA, YANBU INDUSTRIAL PORT

CHARTS BA 158 AND 326

BUOY S-10 IN POSITION 23-49.08N 038-17.82E REPORTED UNLIT
MARINERS CAUTIONED

091500 UTC APR 2025

NAVAREA IX 158/25

PAKISTAN

PORT MUHAMMAD BIN QASIM

CHARTS PAK 5 (INT 7314), 20 (INT 7316) AND BA 59

1. AHSAN CHANNEL BEACON NO.7 TEMPORARILY REPLACED WITH BUOY IN POSITION 24-36.38N 067-05.24E MARINERS CAUTIONED
2. CANCEL NAVAREA IX 294/24

281500 UTC MAR 2025

NAVAREA IX 147/25

SOUTHERN GULF

UAE

BA CHARTS 3179, 3780, 3778 AND 3796

DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS PORT IN PROGRESS FOLLOWING THREE NAVIGATIONAL BUOYS TEMPORARILY WITHDRAWN:

GS-14 24-08.43N 052-46.83E Q(3).R.10S

GS-16 24-08.31N 052-47.01E Q.R

GS-18 24-08.21N 052-47.04E Q(2).R.10S

FOLLOWING TWO NAVIGATIONAL BUOYS TEMPORARILY DEPLOYED:

TRB-3 24-08.27N 052-46.97E Q.R

TRB-4 24-09.40N 052-46.88E FL(3).R.10S

MARINERS CAUTIONED

061500 UTC MAR 25
NAVAREA IX 111/25
CENTRAL GULF
BAHRAIN
BA CHARTS 3734, 3736 AND 3737

1. DREDGING OPERATION WILL BE CONDUCTED EAST OF BAHRAIN
STEEL TERMINAL ON 08 MAR 25 A TEMPORARY SPECIAL MARK
BUOY DEPLOYED 26-10.73N 050-41.70E FOLLOWING BUOYS
TEMPORARILY SHIFTED:
BS 3 26-11.24N 050-41.84E BS 5 26-11.39N 050-41.65E 2. MARINERS EXERCISE
EXTREME CAUTION AND GIVE WIDE BERTH

281500 UTC FEB 25
NAVAREA IX 101/25
SOUTHERN GULF
UAE
BA CHARTS 3179, 3780, 3778 AND 3796

1. DREDGING AND RECLAMATION OPERATION IN JEBEL DHANNA/RUWAIS
PORT IN PROGRESS NO-GO AREA HAS BEEN ESTABLISHED MARKED
BY FOLLOWING BUOYS:
24-09.82N 052-47.25E FL.Y
24-09.70N 052-47.34E FL.Y
24-09.57N 052-47.14E FL.Y
24-09.69N 052-47.04E FL.Y
2. MARINERS EXERCISE EXTREME CAUTION MAINTAIN CONTINUOUS
LISTENING WATCH ON VTIS VHF CH 21
3. CANCEL NAVAREA IX 080/25

201500 UTC FEB 25
NAVAREA IX 090/25
NORTHERN GULF
KUWAIT
CHARTS BA 1214, 2884 AND 3773
FOLLOWING SPECIAL MARK BUOYS TEMPORARILY DEPLOYED
SHOWING BORDERS OF KUWAIT SPORTS CLUB RACETRACK:
BUOY 1 29-20.35N 048-06.05E BUOY 2 29-20.50N 048-06.09E MARINERS CAUTIONED

111500 UTC FEB 25
NAVAREA IX 071/25
SOUTHERN GULF
UAE
CHARTS BA 7179 AND 2889

WAVE RIDER BUOY TEMPORARILY DEPLOYED 24-08.89N 052-46.54E MARINERS CAUTIONED

101500 UTC FEB 25

NAVAREA IX 066/25

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

FOLLOWING NAVIGATION LIGHTS AT AL SHAHEEN

FIELD REPORTED UNLIT FOR MAINTENANCE:

PLATFORM B 26-38.31N 051-57.10E PLATFORM G 26-26.93N 051-58.34E MARINERS
CAUTIONED

071600 UTC FEB 25

NAVAREA IX 063/25

SOUTHERN GULF

UAE

CHARTS BA 2444, 3179 AND 3413

ANCHOR WITH 2.5 SHACKLE CHAIN REPORTED LOST

25-07.69N, 052-53.09E MARINERS REQUESTED NOT TO ANCHOR IN VICINITY

281500 UTC JAN 2025

NAVAREA IX 047/25

SOUTHERN GULF

UAE, RAS AL KHAIMAH

BA CHARTS 2888, 3174 AND 3175

1. DREDGING OPERATION IN PROGRESS BY VESSELS TSHD

ROTTERDAM AND SUPPORTING TUGS IN FOLLOWING AREA:

25-44.46N 055-41.92E 25-44.92N 055-45.58E 25-43.21N 055-44.98E 25-42.87N 055-42.87E

2. TEMPORARY CARDINAL MARK BUOYS DEPLOYED IN FOLLOWING POSITIONS:

NORTH CARDINAL 25-42.56N 055-45.00E EAST CARDINAL 25-41.99N 055-45.57E WEST

CARDINAL 25-42.11N 055-43.85E 3. SPECIAL MARK BUOYS DEPLOYED TO INDICATE
THE DRAUGHT RESTRICTED ARE

(MAX 3 METERS) AND PIPELINE IN FOLLOWING POSITIONS:

A. 25-41.60N 055-45.79E B. 25-41.52N 055-46.05E C. 25-41.11N 055-45.82E 4.

VESSELS INTENDING TO ENTER 1.5 NM RADIUS OF TSHD ROTTERDAM

COORDINATE ON VHF CH 11 AND 16 MARINERS CAUTIONED

5. CANCEL NAVAREA IX 347/24

131500 UTC JAN 2025

NAVAREA IX 021/25

NORTHERN GULF

KUWAIT

CHARTS BA 1223, 2847, 2858, 2884 AND 3773

1. METEOROLOGICAL TOWER REPORTED COLLAPSED 28-46.00N 048-26.10E POSITION MARKED BY
YELLOW BUOY FL(4)15SEC 5NM MARINERS CAUTIONED

2. CANCEL NAVAREA IX 135/23

111800 UTC JAN 2025

NAVAREA IX 018/25

SOUTHERN GULF

UAE,

CHART BA 2444, 2889

1. DATA BUOY DWR 25-07.14N 052-56.06E PERMANENTLY WITHDRAWN

DATA BUOY MIDI 018 25-03.01N 053-04.16E FL(5).Y.20S REMAINS MARINERS CAUTIONED

2. CANCEL NAVAREA IX 433/24

081500 UTC JAN 2025

NAVAREA IX 014/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 2884 AND 3773

RESTRICTED AREA ESTABLISHED AT POSITION 29-24.10N 048-50.50E WITH 600 METER DIAMETER
MARINERS CAUTIONED

061500 UTC JAN 2025

NAVAREA IX 006/25

NORTHERN GULF

KUWAIT

CHARTS BA 2882, 3773 AND KU CHART 1

RESTRICTED AREA ESTABLISHED AT POSITION 28-52.49N 048-21.63E WITH 600 METER DIAMETER
MARINERS CAUTIONED

021500 UTC JAN 2025

NAVAREA IX 002/25

PAKISTAN

PORT MUHAMMAD BIN QASIM

CHARTS PAK 5, 20 AND BA 59

1. FOLLOWING NAVIGATIONAL CHANNEL BUOYS TEMPORARILY MOVED

FOR DREDGING OPERATION:

BUOY NAME	CHARTED POSITION	NEW POSITION
K-7	24-47.24N 067-15.39E	24-47.20N 067-15.27E
	24-47.31N 067-15.66E	24-47.31N
	24-47.28N 067-15.65E	
067-16.04E	K-13	
24-47.28N	067-16.02E	24-47.22N
067-16.52E	K-15	
24-47.16N	067-16.47E	MARINERS CAUTIONED
24-47.22N		
067-16.52E		

2. CANCEL NAVAREA IX 227/22

291500 UTC DEC 2024

NAVAREA IX 531/24

CENTERAL GULF

BAHRAIN

CHARTS BA 3736 AND 3737, BH 1501

MSI-2 BUOY ALTERED IN POSITION 26-11.68N 050-36.68E MARINERS CAUTIONED

261500 UTC DEC 2024

NAVAREA IX 529/24

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 39 AND 707

1. MSV TAJDARE HARAM (MMSI 419956194) REPORTED SUNK

IN POSITION 22-55.50N 066-56.50E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 523/24

231500 UTC DEC 2024

NAVAREA IX 519/24

SAUDI ARABIA

RED SEA, JIZAN

CHARTS BA 15

BUOY F2 IN POSITION 16-49.40N 042-18.20E REPORTED MISSING

MARINERS CAUTIONED

191045 UTC DEC 2024

NAVAREA IX 509/24

RED SEA

1. VESSEL ISA STAR (IMO 9210270) REPORTED AGROUND 18-26.00N 041-06.00E MARINERS
CAUTIONED

2. CANCEL NAVAREA IX 508/24

141500 UTC DEC 2024

NAVAREA IX 501/24

NORTHERN GULF

KUWAIT

CHARTS KU 1, BA 3773

1. RIG 'ORIENTAL DRAGON 1' WILL BE MOVED FROM
POSITION 28-52.490 048-21.634E TO 28-55.298N 048-28.485E ON 14 DEC 24 AND WILL
REMAIN STATIONED
UNTIL END OF DEC 25 MARINERS CAUTIONED KEEP
WELL CLEAR OF ABOVE MENTIONED AREA

101500 UTC DEC 24

NAVAREA IX 488/24

IRAN

KUH-E MAND

CHARTS BA 2847, 2883 AND 2884

FOLLOWING LATERAL MARKS ESTABLISHED:

A. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(2)6SEC 7M

ESTABLISHED 28-14.55N 051-16.29E B. PORT HAND BEACON TOWER WITH TOPMARK FL(2)6SEC

7M

ESTABLISHED 28-14.48N 051-16.24E C. PORT HAND BEACON TOWER WITH TOPMARK FL(2)6SEC
7M

ESTABLISHED 28-31.89N 051-05.09E MARINERS CAUTIONED

091500 UTC DEC 24

NAVAREA IX 486/24

RED SEA

SAUDI ARABIA, JIZAN

CHARTS BA 15, 16, 157 AND 2964

1. BUOY FCH-4 FL (2) R 6 SEC IN POSITION 16-51.12N 042 24.74E REPORTED

MISSING MARINERS CAUTIONED

2. BUOY F1 RESTORED CANCEL NAVAREA IX 474/24

040700 UTC DEC 24

NAVAREA IX 476/24

ARABIAN SEA

PAKISTAN

CHARTS PAK 33, 57 (INT 751), BA 707 AND 4705

MSV AL PIRANPIR (MMSI 419956499) REPORTED SUNK IN
POSITION 22-44N 066-24E MARINERS CAUTIONED

181500 UTC NOV 2024

NAVAREA IX 452/24

CENTRAL GULF

QATAR

CHARTS BA 2523 AND 2886

SCUBA DIVING OPERATION WILL BE CONDUCTED FOR CORAL
RELOCATION ENVIRONMENT PROJECT IN AREA BOUNDED BY
FOLLOWING COORDINATES:

26-05.33N 051-26.25E 26-05.23N 051-26.25E 26-05.22N 051-26.38E 26-05.33N 051-26.38E
MARINERS CAUTIONED

041500 UTC NOV 24

NAVAREA IX 432/24

PERSIAN GULF

IRAN, DARGAHAN AND BOSTANEH PORTS

CHARTS BA 2441, 2887, 3173, 3599 AND IR 3086

FOLLOWING LATERAL MARKS ESTABLISHED:

A. PORT HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M

26-58.04N 056-02.77E B. STARBOARD HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M

26-58.04N 056-02.71E C. PORT HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M

26-30.44N 054-39.93E B. STARBOARD HAND BEACON TOWER WITH TOP MARK FL(1)5SEC 3M

26-30.48N 054-39.85E MARINERS CAUTIONED

161500 UTC OCT 24
NAVAREA IX 403/24
SAUDI ARABIA
APPROACHES TO DAMMAM
CHARTS BA 3777 AND 3812
BUOY D-7 FL(2)G.6S 26-35.26N 050-12.45E REPORTED UNLIT MARINERS CAUTIONED

161500 UTC OCT 24
NAVAREA IX 402/24
IRAN
BANDAR-E SHENAS
CHARTS BA 2441, 2887 AND 2888
FOLLOWING LATERAL MARKS ESTABLISHED:
A. PORT HAND BEACON TOWER WITH TOPMARK FL(1)5SEC 3M
26-29.75N 054-46.98E B. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)5SEC
3M 26-29.80N 054-47.02E MARINERS CAUTIONED

141500 UTC OCT 24
NAVAREA IX 399/24
SAUDI ARABIA
ARABIAN GULF, APPROACHES TO JUBAIL
CHARTS BA 3719 AND 3788
BUOY ANCHORAGE 3 FL.Y.5S 27-10.82N 049-47.00E REPORTED
MISSING MARINERS CAUTIONED

271500 UTC SEP 24
NAVAREA IX 382/24
CENTRAL GULF
QATAR
CHARTS BA 2523, 2883 AND 2886
1. ROV OPERATIONS BY VESSEL MPSV HALUL 49 FOR SEVERAL PLATFORMS
IN AREA BOUNDED BY FOLLOWING COORDINATES EXTENDED TILL END OF JAN 25:
A.26-43.55N 051-50.86E B.26-43.55N 052-04.14E C.26-26.81N 052-04.14E D.26-26.81N
051-50.86E MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND GIVE WIDE BERTH
2.CANCEL NAVAREA IX WARNING 209/24

181500 UTC SEP 24
NAVAREA IX 365/24
NORTHERN GULF
KUWAIT
CHARTS BA 1223, 2882 AND 3773
MOORING BUOY M1 PERMANENTLY MOVED FROM POSITION
29-06.44N 048-17.68E TO 29-06.57N 048-17.27E MARINERS CAUTIONED

161530 UTC SEP 24

NAVAREA IX 363/24

IRAN

KHALIJ-E CHABAHAR

CHART BA 38, 2851 AND 2858

PORT HAND PILLAR LIGHTBUOY FL(2)5SEC 5M MOVED 0.2M

NORTH-EAST FROM 25 18.61N 060 34.82E TO 25 18.72N 060 34.98E(.) MARINERS CAUTIONED

161530 UTC SEP 24

NAVAREA IX 362/24

SOUTHERN GULF

UAE

CHARTS BA 2889 AND 3175

MV KNIDOS REPORTED SUNK WITH FLOATING DEBRIS IN POSITION

25-35.02N 054-51.15E MARINERS NAVIGATE WITH CAUTION

AND KEEP CLEAR OF THE AREA

161500 UTC SEP 24

NAVAREA IX 361/24

IRAN

JAZIREH-YE LARK

CHARTS BA 2851, 2888 AND 3173

NORTH CARDINAL PILLAR LIGHT BUOY WITH TOPMARK Q 5M 4 METERS ESTABLISHED

IN POSITION 26-53.49N 056-21.26E MARINERS CAUTIONED

031500 UTC SEP 24

NAVAREA IX 340/24

IRAN

JAZIREH-YE QEYS

CHARTS BA 2887 AND 3409

FOLLOWING LATERAL MARKS ESTABLISHED:

A. STARBOARD BEACON TOWER WITH TOPMARK FL(2)6SEC 3M ESTABLISHED

IN POSITION 26-31.35N 054-02.98E B. PORT BEACON TOWER WITH TOPMARK FL(2)6SEC 3M ESTABLISHED

IN POSITION 26-31.36N 054-03.03E C. STARBOARD BEACON TOWER WITH TOPMARK FL(1)5SEC 3M ESTABLISHED

IN POSITION 26-34.66N 053-56.80E D. PORT BEACON TOWER WITH TOPMARK FL(1)5SEC 3M ESTABLISHED

IN POSITION 26-34.60N 053-56.76E MARINERS CAUTIONED

011500 UTC SEP 24

NAVAREA IX 333/24

GULF OF OMAN

IRAN

CHARTS BA 2888, 3171, 3173 AND 3599

FOLLOWING NEW TRAFFIC CONTROL TOWERS ESTABLISHED:

A. SHAHID BAHONAR TRAFFIC CONTROL TOWER, 22 METERS HEIGHT,

IN POSITION 27-09.22N 056-12.22E B. SHAHID HAGHANI TRAFFIC CONTROL TOWER, 12 METERS HEIGHT,
IN POSITION 27-10.45N 056-16.91E C. BUNJI TRAFFIC CONTROL TOWER, 5 METERS HEIGHT,
IN POSITION 25-54.67N 057-16.50E D. JASK TRAFFIC CONTROL TOWER, 25 METERS HEIGHT, IN
POSITION 25-38.74N 057-46.02E MARINERS CAUTIONED

291500 UTC AUG 24

NAVAREA IX 329/24

CENTRAL GULF

QATAR

CHARTS BA 2523, 2887, 2886 AND 3950

PIPE LAYING OPERATION IN PROGRESS BY NON-PROPELLED BARGE
'DERRICK BARGE 30' IN AREA BOUNDED BY FOLLOWING POSITIONS:

25-57.01N 051-27.34E 25-47.74N 052-06.21E 26-15.43N 052-24.61E 26-15.49N 052-16.53E

MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTIONED, GIVE

WIDE BERTH OF 2NM AND MAINTAIN LISTENING WATCH ON VHF

CHANNEL 16

211500 UTC AUG 2024

NAVAREA IX 311/24

RED SEA

SAUDI ARABIA

PORT OF NEOM (DUBA PORT)

CHART BA 12

LIGHT (Fl.12s 15m 5M) AND RACON IN POSITION

27-39.10N 035-16.70E REPORTED UNRELIABLE

(.) MARINERS CAUTIONED

151500 UTC AUG 2024

NAVAREA IX 299/24

CENTRAL GULF

BAHRAIN

CHARTS BA 3736, 3737 AND 3790

1. OPERATIONS FOR TRESTLE CONSTRUCTION, SEABED EXCAVATION AND PIPELINE
LAYING ACTIVITIES OF BAPCO TERMINAL TO SITRA PORT EXTENDED TILL END OF JUN 25
IN THE FOLLOWING BOUNDED AREA:

26-10.03N 050-39.57E 26-10.05N 050-39.72E 26-10.07N 050-40.00E 26-09.98N
050-40.28E 26-09.77N 050-40.42E 26-09.73N 050-40.37E 26-10.00N 050-39.90E 26-09.95N
050-39.72E 26-09.88N 050-39.58E 26-09.95N 050-39.55E MARINERS ARE ADVISED TO
NAVIGATE WITH CAUTION, MAINTAIN LISTENING WATCH ON VHF
CHANNEL 16/72/74 (BAHRAIN PORT CONTROL AND BAPCO WHARF CONTROL)

2. CANCEL NAVAREA IX WARNING 007 OF 24

061500 UTC AUG 2024

NAVAREA IX 289/24

RED SEA
SAUDI ARABIA (SHAYBARA ISLAND)
CHARTS BA 159
SEAPLANE LANDING AREA ESTABLISHED
BOUNDED BY FOLLOWING POSITIONS:
25-22.54N 036-55.03E 25-21.90N 036-55.76E 25-21.48N 036-54.97E 25-21.95N 036-55.84E
MARINERS CAUTIONED

051500 UTC AUG 2024
NAVAREA IX 288/24
CENTRAL GULF
QATAR
CHARTS BA 2523 AND 2886
WAVE RIDER BUOY FL (5)Y 2.5S DEPLOYED IN POSITION
26-26.52N 051-57.86E MARINERS CAUTIONED

021500 UTC AUG 2024
NAVAREA IX 285/24
ARABIAN SEA
YEMEN
CHARTS BA 6, 2964, 2970 AND 3784
UNLIT VESSEL ROYAL BLUE (IMO NO 8795962) ANCHORED IN POSITION
14-21.60N, 048-59.92E MARINERS CAUTIONED

311500 UTC JUL 2024
NAVAREA IX 281/24
SOUTHERN GULF
UAE
CHARTS BA 2887, 2888, 3176 AND 3739
SPECIAL MARK BUOY FL Y DEPLOYED IN POSITION
25-12.10N 055-00.63E MARINERS CAUTIONED

181500 UTC JUL 2024
NAVAREA IX 267/24
OMAN
ARABIAN SEA
CHARTS OM 1, 3501 AND BA 3785
SAR OPERATION FOR VESSEL "PRESTIGE FALCON" MISSING CREW IN PROGRESS
CENTERED AROUND 19-09.50N, 058-18.30E MARINERS ARE ADVISED TO
NAVIGATE WITH CAUTION AND KEEP SHARP LOOK FOR MISSING CREW

081500 UTC JUL 2024
NAVAREA IX 253/24
BANDAR-E PARS
IRAN

CHART BA 2883

STARBOARD BEACON TOWER WITH TOPMARK FL(1)5SEC 7M 9 METERS
ESTABLISHED AT 27-34.96N 052-30.66E PORT BEACON TOWER WITH
TOPMARK FL(1)5SEC 7M 9 METERS ESTABLISHED AT 27-34.82N 052-30.47E (.) MARINERS
CAUTIONED

061500 UTC JUL 2024

NAVAREA IX 250/24

NORTHERN GULF

KUWAIT

CHARTS KU 1, 4, BA 1265, 2884 AND 3773

A TEMPORARILY RESTRICTED AREA ESTABLISHED FOR 'NO NAVIGATION,
FISHING AND ANCHORING' IN LOCATION CENTERED AT 29-24.10N 048-50.50E WITH 600 METERS
DIAMETER MARINERS CAUTIONED

031500 UTC JUL 2024

NAVAREA IX 240/24

IRAN

BANDAR-E SHAHID RAJAI

CHARTS BA 3173 AND 3599

SHAHID RAJA'I CONTROL TOWER (HEIGHT 66 METERS) INSTALLED
AT LOCATION 27-06.13N 056-04.57E NON-IALA RED FLESHING
LANTERN INSTALLED ON 12 METER LATTICE TOWER ON TOP OF
CONTROL TOWER MARINERS CAUTIONED

281500 UTC MAY 2024

NAVAREA IX 200/24

ARABIAN GULF

SAUDI ARABIA (JIZAN)

CHARTS BA 15, 157 AND 2964

FOLLOWING BUOYS REPORTED UNLIT:

NO.103 16 59.79N 41 20.56E (LATERAL STBD)

NO.109 17 10.40N 41 22.62E (LATERAL PORT)

MARINERS CAUTIONED

261230 UTC MAY 2024

NAVAREA IX 198/24

IRAN

SHATT AL ARAB

CHART BA 3842 (INT 7292)

STARBOARD HAND PILLAR BUOY WITH TOPMARK, CHARACTERISTICS

FL(3)18SEC 5M ESTABLISHED AT 29-52.58N 048-40.86E MARINERS CAUTIONED

291400 UTC APR 2024

NAVAREA IX 168/24

PAKISTAN

KHOBAR CREEK

CHARTS PAK 28, 33, BA 39 AND 707

1. FISHING VESSEL REPORTED SUNK IN VICINITY OF POSITION

23-51.8N 067-20.9E MARINERS CAUTIONED

2. CANCEL NAVAREA IX 113/24

261500 UTC APR 2024

NAVAREA IX 163/24

SOUTHERN GULF

UAE

CHARTS BA 2442, 2887 AND 3413

"ZH" PLATFORM IN POSITION 25-38.82N 054-24.85E IN FATEH OIL FIELD REPORTED UNLIT
MARINERS CAUTIONED

081500 UTC APR 2024

NAVAREA IX 141/24

ARABIAN GULF

SAUDI ARABIA (PORT AL JUBAIL)

CHARTS BA 3718 AND 3719

BUOY NO 7 IN POSITION 27 02.07N 049 41.60E UNLIT

MARINERS CAUTIONED

071500 UTC APR 2024

NAVAREA IX 140/24

BANDAR E JASK

IRAN

CHARTS BA 2888 AND 2851

LATTICE BEACON 25-38.19N 057-45.86E TEMPORARILY REMOVED

MARINERS CAUTIONED

061500 UTC APR 2024

NAVAREA IX 139/24

PERSIAN GULF

IRAN

CHARTS BA 2837 AND 2888

STARBOARD BEACON WITH TOPMARK FL(1) 5 SEC 3M 6 METERS ESTABLISHED
IN POSITION 26-58.42N 055-44.99E MARINERS CAUTIONED

011500 UTC APRIL 2024

NAVAREA IX 132/24

ARABIAN GULF

SAUDI ARABIA (PORT AL JUBAIL)

CHARTS BA 3718 AND 3719

FOLLOWING BUOYS REPORTED UNLIT:

BUOY NO 2 27 14.63N 049 58.92E BUOY CH 5 27 02.02N 049 41.88E MARINERS CAUTIONED

011500 UTC APRIL 2024

NAVAREA IX 130/24

IRAN

SHATT AL ARAB

CHART BA 3842 (INT 7292)

STARBOARD LIGHTBUOY NO.11 FL(2)18SEC 5M MOVED FROM 29-52.74N 048-40.94E TO 29-52.58N 048-40.86E MARINERS CAUTIONED

160930 UTC MAR 2024

NAVAREA IX 115/24

IRAN

RAS AL KUH

CHARTS BA 2888 AND 3171

SINGLE POINT MOORING BUOY NO.1 ESTABLISHED IN POSITION 25-50.75N 057-14.54E MARINERS CAUTIONED

041500 UTC MAR 24

NAVAREA IX 103/24

SAUDI ARABIA

RED SEA

CHARTS BA 15

WEST CARDINAL BUOY 'MAK' IN POSITION 17-01.60N 041-13.45E REPORTED MISSING MARINERS CAUTIONED

291500 UTC FEB 2024

NAVAREA IX 094/24

SOUTHERN GULF

UAE

CHARTS BA 3174, AND 3404

RECLAMATION WORK IN PROGRESS IN AREA BOUNDED BY FOLLOWING COORDINATES:

25-58.19N 056-02.13E 25-58.01N 056-02.82E 25-57.38N 056-02.87E 25-57.62N 056-01.95E

FOLLOWING TEMPORARY MARKER BUOYS DEPLOYED:

B1 YELLOW FLASHING 25-58.15N 056-02.30E B2 YELLOW FLASHING 25-57.85N 056-02.21E

B3 YELLOW FLASHING 25-57.56N 056-02.11E MARINERS CAUTIONED

191500 UTC FEB 24

NAVAREA IX 076/24

SOUTHERN GULF

UAE

CHARTS BA 2443, 2887 AND 2889

SEMI-SUBMERGED UNLIT WRECK REPORTED IN VICINITY
OF POSITION 25-11.64N 054-10.12E MARINERS CAUTIONED

SECURITE
291500 UTC JAN 2024
NAVAREA IX 048/24
CENTRAL GULF
BAHRAIN
CHARTS BA 3736, 3737 AND 3738

1. TWO NEW PIPELINES ESTABLISHED IN
ROUTES BOUNDED BY FOLLOWING COORDINATES:
26-12.06N 050-39.61E 26-11.15N 050-39.24E 26-10.10N 050-39.20E 26-09.79N 050-39.14E
MARINERS CAUTIONED
 2. CANCEL NAVAREA IX 026/24
-

SECURITE
251500 UTC JAN 2024
NAVAREA IX 042/24
NORTHERN GULF
KUWAIT
CHARTS BA 1223, 3773, LOCAL CHARTS 1, 4, 8
1. CARGO VESSEL BAHAREH REPORTED SUNK IN POSITION 29-05.49N 048-22.09E ISOLATED
DANGER BUOY TEMPORARILY DEPLOYED IN
POSITION 29-05.52N 048-22.06E WITH CHARACTERISTICS FL(2) 5SEC
(.) MARINERS CAUTIONED
2. CANCEL NAVAREA IX 020/24

SECURITE
271500 UTC DEC 2023
NAVAREA IX 475/23
IRAN
JAZIREH-YE KHARKU
CHARTS BA 11, 2882 AND 2884
EMERGENCY WRECK MARKING BUOY IN POSITION 29-19.24N 050-19.70E PERMANENTLY
DISCONTINUED WEST CARDINAL PILLAR BUOY WITH
TOPMARK Q (9) 15SEC 5M ESTABLISHED IN POSITION 29-19.20N 050-19.70E (.) MARINERS
CAUTIONED

SECURITE
041500 UTC DEC 2023
NAVAREA IX 453/23
RED SEA
SAUDI ARABIA
CHARTS BA 158, 326, 327, 328
ISOLATED DANGER BUOY A3-1 GP FL(2)10SEC WITH
TOPMARK 2 BLACK SPHERES ESTABLISHED IN POSITION
23-57.95N 038-09.63E MARINERS CAUTIONED

SECURITE
011500 UTC DEC 2023

NAVAREA IX 448/23

CENTRAL GULF

BAHRAIN

CHARTS BA 3736, 3737 AND 3790

1. MINA SALMAN OUTER REAR LEADING LIGHT IN POSITION

26-11.17N 050-39.25E SHIFTED TO 26-11.165N 050-39.261E AND RESTORED TO NORMAL

MARINERS CAUTIONED

2. CANCEL NAVAREA IX 445/23

SECURITE
291500 UTC NOV 2023

NAVAREA IX 447/23

PERSIAN GULF

IRAN

CHARTS BA 2523, 2837, 2883 AND 2886

SEAPAD ACCOMMODATION BARGE TEMPORARILY MOORED AT 26-41.40N 052-15.50E IN
SOUTH PARS GAS FIELD WITH ANCHORS POSITIONED AT FOLLOWING LOCATIONS:

STARBOARD SIDE	PORT SIDE
----------------	-----------

S1: 26-42.20N 052-15.15E P1: 26-41.84N 052-14.67E S3: 26-42.23N 052-15.72E P3:

26-41.22N 052-14.58E S5: 26-41.60N 052-16.42E P4: 26-40.59N 052-15.24E S6: 26-41.13N

052-16.40E P6: 26-40.58N 052-15.74E MARINERS CAUTIONED

SECURITE
201500 UTC NOV 2023

NAVAREA IX 435/23

IRAN

BANDAR-E AFTAB

CHART BA 2837, 2887

FISH FARM ESTABLISHED IN AREA BOUNDED BY FOLLOWING COORDINATES:

A. 26-42.29N 054-03.88E B. 26-42.15N 054-04.08E C. 26-41.97N 054-03.89E D. 26-42.12N
054-03.68E MARINERS CAUTIONED

SECURITE
091500 UTC OCT 2023

NAVAREA IX 376/23 IRAN TANGEH-YE HORMOZ

CHARTS BA 2888, 2851 AND 3173

2. FOLLOWING CHANGES IN AIDS TO NAVIGATION OF
HORMOZGAN COASTAL WATERS

A. STARBOARD HAND BEACON TOWER FL 5 SEC 5 M 5 METERS

ESTABLISHED IN POSITION 25-40.99N 057-51.93E B. PORT HAND BEACON TOWER FL 5 SEC 5 M
5 METERS

ESTABLISHED IN POSITION 25-41.04N 057-51.92E C. LATTICE BEACON TEMPORARILY
DISCONTINUED IN

POSITION 27-05.25N 056-49.48E D. ISOLATED DANGER BUOY PERMANENTLY REMOVED IN

POSITION 27-04.38N 056-44.10E AND ISOLATED DANGER
PERCH BEACON WITH TOP MARK FL(2)6 SEC 5 M ESTABLISHED
ON WRECK IN POSITION 27-04.23N 056-44.62E E. PORT HAND BUOY FL 5 SEC 5 M IN
POSITION
27-06.18N 056-14.88E MOVED TO 27-06.62N 056-14.95E F. TOWER BEACON FL(2) 15 SEC 18
M 40 METERS RACON
INOPERATIVE IN POSITION 25-49.85N 057-19.20E 3. MARINERS CAUTIONED
4. CANCEL NAVAREA IX WARNING 375 OF 2023

SECURITE
191500 UTC SEP 2023
NAVAREA IX 355/23 SOUTHERN GULF UAE
CHARTS BA 2444 AND 3413
2. LOST ANCHOR WITH CHAIN REPORTED IN POSITION
25-07.23N 052-53.27E 3. MARINERS ARE ADVISED NOT TO ANCHOR IN THE VICINITY

SECURITE
131500 UTC SEP 2023
NAVAREA IX 346/23 CENTRAL GULF BAHRAIN
CHARTS BA 2837, 2847 AND 2886
2. CABLE INSTALLATION OPERATION IN PROGRESS BY VESSELS
HALL-1, ABS, OCEAN-10 BARGE, OCEAN CAT AND TUG OCEAN
CABLE IS BEING LAID BETWEEN RAS AL BAR AND HAWAR ISLAND
ON FOLLOWING ROUTE:
25-47.89N 050-34.07E 25-46.59N 050-37.04E 25-44.47N 050-37.68E 25-42.04N 050-44.08E
25-41.95N 050-45.27E 3. VESSELS WILL BE RESTRICTED IN THEIR ABILITY TO MANOEUVRE
AND AN EXCLUSION AREA OF 500 METERS IS REQUESTED
4. MARINERS CAUTIONED
5. CANCEL NAVAREA IX WARNING 239 OF 2023

SECURITE
111500 UTC SEP 2023
NAVAREA IX 341/23 IRAN KHALIJ-E-CHABAHAR
CHART OM 7501
2. FOLLOWING AIDS TO NAVIGATION HAVE BEEN MOVED TO
NEW POSITIONS IN KHALIJ-E CHABAHAR

BUOY NAME	OLD POSITION	NEW POSITION
STARBOARD HAND BUOY	25-18.89N 060-35.78E	25-18.86N 060-35.81E FL (2) 5s 5M
STARBOARD HAND BUOY	25-18.97N 060-35.96E	25-18.98N 060-36.06E FL (2) 5s 5M
PORT HAND BUOY	25-18.54N 060-34.74E	25-18.61N 060-34.82E FL (2) 5s 5M

3. SPECIAL BUOY FL(1) 5s 3M ESTABLISHED IN POSITION
25-18.41N 060-36.05E 4. MARINERS CAUTIONED

SECURITE
091500 UTC SEP 2023
NAVAREA IX 338/23 PERSIAN GULF (IRAN)

LAVAN ISLAND CHART BA 2883, 2886 AND 2887
2. SOUTH CARDINAL LIGHTBUOY, Q(6)+LFL 15SEC 5M ESTABLISHED
IN POSITION 26-47.92N 053-12.83
3. MARINERS CAUTIONED

SECURITE
031500 UTC SEP 2023
NAVAREA IX 326/23 IRAN KHALIJ-E-CHABAHAR
CHART OM 7501(INT 7016)
2. SPECIAL BUOY FL (1)5SEC 3M MOVED FROM 25-18.41N 060-36.05E TO 25-18.52N
060-35.99E 3. MARINERS CAUTIONED

SECURITE
281500 UTC AUG 2023
NAVAREA IX 318/23 SOUTHERN GULF UAE
CHARTS BA 2443, 2889, 3178 AND 3179
2. OLD SPM SOUTH OF ZIRKUH ISLAND IN POSITION
24-51.60N, 053-05.41E REPORTED UNLIT
3. MARINERS CAUTIONED

SECURITE
271500 UTC AUG 2023
NAVAREA IX 314/23 RED SEA SAUDI ARABIA
(.) RA'S KURKUMA UMMAHAT ALSHAYKH ISLAND
CHARTS BA 159
2. SEA PLANE LANDING AND OPERATIONAL AREA ESTABLISHED
AT UMMAHAT ALSHAYKH ISLAND IN FOLLOWING POSITIONS:
25 32.31N 036 43.59E 25 34.88N 036 44.71E 25 33.40N 036 48.15E 25 31.06N 036 46.43E
3. MARINERS CAUTIONED

SECURITE
231500 UTC AUG 2023
NAVAREA IX 307/23 IRAN JAZIREH YE QESHM CHART
BA 2441, 2887 AND 2888
2. ESTABLISHMENT AND MOVEMENT OF AIDS TO NAVIGATION
IN JAZIREH YE QESHM
A. NORTH CARDINAL PILLAR BUOY WITH TOPMARK Q(1)
1 SEC 5M 3 METER ESTABLISHED IN POSITION 26-39.42N 055-14.85E B. WEST CARDINAL
PILLAR BUOY WITH TOPMARK Q(9)
15 SEC 5M 3 METER ESTABLISHED IN POSITION 26-35.63N 055-12.76E C. WEST CARDINAL
PILLAR BUOY WITH TOPMARK 26-37.21N 055-12.88E Q(9) 15 SEC 7M 3 METER MOVED IN
POSITION
26-37.40N 055-12.71E D. STARBOARD HAND BEACON TOWER WITH TOPMARK FL(1)
5 SEC 3M ESTABLISHED IN POSITION 26-39.67N 055-16.15E E. PORT HAND BEACON TOWER
WITH TOPMARK FL(1)
5 SEC 5M ESTABLISHED IN POSITION 26-39.71N 055-16.08E 3. MARINERS CAUTIONED

SECURITE

071600 UTC AUG 2023

NAVAREA IX 293/23 PAKISTAN ORMARA

CHARTS PAK 24, PAK 33, PAK 57 (INT 751), PAK 58 (INT 7019)

AND BA 38

2. FISHING BOAT AL-MUSTAFA REPORTED SUNK IN VICINITY OF
POSITION (25-10N 065-04E)

3. MARINERS CAUTIONED

SECURITE

301500 UTC MAY 2023

NAVAREA IX 226/23 IRAN KHOWR-E MINAB

CHARTS BA 2888 AND 3173

2. FOLLOWING LATERAL BUOYS ESTABLISHED AT ENTRANCE
OF KOLAHY PORT:

A. STARBOARD HAND PILLAR LIGHTBUOY WITH TOP MARK
IN POSITION 27-03.49N 056-47.43E, CHARACTERISTICS

FL(1) 5 SEC 3 MILE

B. PORT HAND PILLAR LIGHTBUOY WITH TOP MARK IN
POSITION 27-03.55N 056-47.40E, CHARACTERISTICS

FL(1) 5 SEC 3 MILE

3. MARINERS CAUTIONED

SECURITE

280230 UTC MAY 2023

NAVAREA IX 221/23 PAKISTAN SONMIANI BAY

CHARTS BA-39, 707, PAK 22 AND 33

2. MV ERA (IMO NO 8121422) REPORTED GROUNDED IN
POSITION 25 08.60N 066 42.90E. 3. MARINERS CAUTIONED.
4. CANCEL NAVAREA IX WARNING 220 OF 2023

SECURITE

031500 UTC MAY 2023

NAVAREA IX 190/23 IRAN TOREH-YE KHVORAN

CHART BA 2837, 2888 AND 3173

2. SUBMERGED PIPELINE (01 MILE LONG) ESTABLISHED FROM
27-01.35N 055-56.90E TO 27-00.73N 055-57.87E. 3. ISOLATED DANGER PILLAR BUOYS WITH
TOPMARK, FL(2) 6SEC 5M,
ESTABLISHED IN FOLLOWING POSITIONS:

A. 27-01.09N 055-57.36E B. 27-01.03N 055-57.46E C. 27-00.76N 055-57.88E 4. MARINERS
CAUTIONED

SECURITE

271500 UTC APR 2023

NAVAREA IX 177/23 SOUTHERN GULF UAE
CHARTS BA 2444, 2889 AND 3178

2. LOST ANCHOR REPORTED IN POSITION 25-01.57N 053-03.22E 3. MARINERS ARE ADVISED NOT TO ANCHOR IN THE VICINITY

SECURITE

071500 UTC APR 2023

NAVAREA IX 159/23 SOUTHERN GULF U A E

CHARTS BA 2837, 2858, 2889, 3178 AND 3179

2. MAJOR CONSTRUCTION WORKS IN PROGRESS TO CONSTRUCT ARTIFICIAL ISLANDS INSIDE HAIL AND GHASHA OIL FIELDS AT ABU DHABI OFFSHORE ON THE FOLLOWING BOUNDARIES:

GHASHA FIELD AREA:

P01 24-40.22N 052-52.61E P02 24-39.08N 053-00.18E P03 24-30.79N
053-03.24E P04 24-26.33N 052-56.63E P05 24-30.70N 052-52.08E HAIL FIELD

AREA:

P01 24-24.56N 053-21.72E P02 24-24.46N 053-28.22E P03 24-17.96N
053-28.09E P04 24-18.07N 053-21.60E 3. ENTRY IN BOUNDED AREA IS STRICTLY PROHIBITED,

MAINTAIN COMMUNICATION WITH MARINE CONTROL CENTER
ON VHF CH.16

4. CANCEL NAVAREA IX WARNING 024/21

SECURITE

101500 UTC MAR 2023

NAVAREA IX 116/23 PAKISTAN KARACHI APPROACHES CHARTS PAK 5

BA 40, BA 58 AND BA 707

2. WRECK BUOY IN POSITION 24-46.861N 066-56.048E REPORTED UNLIT

3. MARINERS CAUTIONED

SECURITE

071500 UTC MAR 2023

NAVAREA IX 111/23 IRAN BANDARE JASK

CHART BA 2888

2. PILLER BUOYS ESTABLISHED AS FOLLOWS:

A. STARBOARD HAND PILLER BUOY IN POSITION 25-39.13N 057-45.95E WITH TOP MARK AND CHARACTERISTICS FL(2) 5 SEC 5 MILE

B. PORT HAND PILLER BUOY IN POSITION 25-39.10N 057-46.02E WITH TOP MARK AND CHARACTERISTICS FL(2) 5 SEC 5 MILE

3. MARINERS CAUTIONED

SECURITE

281500 UTC FEB 2023

NAVAREA IX 096/23 IRAN BANDAR-E SHAHID RAJAI CHART BA 2888, 3173 AND 3599

2. CHANGES IN CHARACTERISTICS OF AIDS TO NAVIGATION:

A. STARBOARD HAND PILE BEACON WITH TOPMARK IN POSITION

27-06.34N 056-04.94E, FL(3) 5 SEC 7 MILES 7 METERS

B. PORT HAND PILE BEACON WITH TOPMARK IN POSITION 27-06.30N 056-04.77E, FL(3) 5 SEC 7

MILES 7 METERS

C. STARBOARD HAND PILE BEACON WITH TOPMARK IN POSITION

27-06.14N 056-05.01E, FL(2) 5 SEC 7 MILES 5 METERS

D. PORT HAND PILE BEACON WITH TOPMARK IN POSITION 27-06.20N 056-04.84E, FL(2) 5 SEC 7

MILES 5 METERS

3. MARINERS CAUTIONED

SECURITE

271500 UTC FEB 2023

NAVAREA IX 094/23 IRAN BANDARE KHAMIR CHART BA 2888

2. ESTABLISHMENT OF PILLER BUOYS IN TANGEH-YE KHURAN

A. STARBOARD HAND PILLER BUOYS WITH TOP MARK FL(1) 5 SEC 5 MILE ESTABLISHED IN POSITION:

BUOY NO 01: 26-58.08N 055-43.50E BUOY NO 03: 26-57.90N 055-40.94E BUOY NO 05:

26-57.78N 055-39.65E B. PORT HAND PILLER BUOYS WITH TOP MARK FL(1) 5 SEC 5 MILE ESTABLISHED IN POSITION:

BUOY NO 02: 26-57.90N 055-42.54E BUOY NO 04: 26-57.62N 055-39.68E 3. MARINERS CAUTIONED

SECURITE

151600 UTC FEB 2023

NAVAREA IX 071/23 SOUTHERN GULF DUBAI

(AL FATEH OIL FIELD) CHARTS BA 3413

2. SUBSEA GAS LEAKAGE OBSERVED IN POSITION 25 38.9N 054 27.8E SURFACE MARKER BUOY FITTED WITH RADAR REFLECTOR

AND WHITE FLASHING LIGHT LAID

3. MARINERS CAUTIONED

SECURITE

141500 UTC FEB 2023

NAVAREA IX 068/23 NORTHERN GULF KUWAIT

(ASH SHUWAYKH PORT) CHARTS BA 1214 AND 2884

2. DEVELOPMENT OF ANCHORAGE AREA NUMBER 1 TO 7

IN PROGRESS IN POSITION 29-21.16N 047-56.10E 3. MARINERS CAUTIONED

SECURITE

141500 UTC FEB 2023

NAVAREA IX 067/23 SOUTHERN GULF UAE (DUBAI)

CHARTS BA 2887, 2888, 2889, 3412 AND 3414

2. MOORING BUOYS DEPLOYED IN FOLLOWING POSITIONS:

25-08.14N 055-09.52E 25-07.78N 055-09.65E 25-14.77N 055-12.60E 25-14.34N 055-12.75E

3. MARINERS CAUTIONED

SECURITE
091500 UTC FEB 2023

NAVAREA IX 058/23 CENTRAL GULF QATAR

CHARTS BA 2523, 2837, 2883 AND 2886

2. SAFETY ZONES OF 1500 METER ESTABLISHED AROUND
SPMs IN FOLLOWING POSITIONS:

SPM2 26-35.496N 052-01.986E SPM3 26-38.808N 051-53.496E SPM4 26-40.375N

051-53.896E 3. MARINERS ARE ADVISED TO OBTAIN APPROVAL FROM

AL SHAHEEN OIL TERMINAL ON VHF CHANNEL 16 OR 72

WHILE ENTERING THE AREA

SECURITE
231500 UTC JAN 2023
NAVAREA IX 034/23 SAUDI ARABIA JIZAN

CHARTS BA 15, 157 AND 2964

2. JIZAN APPROACH CHANNEL BUOYS REPORTED UNLIT/
DAMAGED/MISSING FROM CHARTED POSITION AS UNDER:

BUOY	POSITIONS	TYPE AND ISSUE
101	16-56.77N 041-17.37E	SAFE WATER (UNLIT)
102	16-56.71N 041-18.84E	STBD LATERAL (UNLIT)
104	16-59.72N 041-19.28E	ISOLATED DANGER (MISSING)
108	17-08.41N 041-24.40E	STBD LATERAL (MISSING)
110	17-13.52N 041-34.57E	STBD LATERAL (UNLIT)
111	17-14.70N 041-33.30E	PORT LATERAL (MISSING)
112A	17-19.15N 041-40.95E	PORT LATERAL (UNLIT)
113	17-15.45N 041-49.63E	PORT LATERAL (UNLIT)
117	17-06.25N 042-03.82E	PORT LATERAL WITH RECON B (UNLIT)
118	17-02.30N 042-02.10E	STBD LATERAL (UNLIT)
122	17-04.95N 042-10.41E	STBD LATERAL (DAMAGED UNLIT)
124	17-09.82N 042-13.02E	PORT LATERAL(DAMAGED UNLIT)
129	17-13.47N 042-14.49E	PORT LATERAL MARK (UNLIT)
209	17-17.81N 042-07.10E	SPECIAL MARK (UNLIT)
210	17-15.39N 042-16.09E	SPECIAL MARK (UNLIT)
211	17-17.38N 042-15.15E	SPECIAL MARK (UNLIT)
212	17-17.51N 042-12.61E	SPECIAL MARK (UNLIT)
213	17-14.45N 042-12.07E	SPECIAL MARK (UNLIT)
214	17-15.40N 042-08.20E	SPECIAL MARK (UNLIT)
215	17-19.48N 042-07.29E	SPECIAL MARK (UNLIT)
216	17-20.30N 042-10.09E	SPECIAL MARK (UNLIT)
217	17-20.30N 042-11.70E	SPECIAL MARK (UNLIT)
302	17-14.64N 042-16.97E	PORT LATERAL MARK (UNLIT)
303	17-14.76N 042-17.41E	STBD LATERAL MARK (UNLIT)
307	17-15.29N 042-18.05E	STBD LATERAL MARK (UNLIT)
308	17-15.44N 042-17.92E	PORT LATERAL MARK (UNLIT)
313	17-16.09N 042-19.01E	STBD LATERAL MARK (MISSING)
314	17-16.24N 042-18.89E	PORT LATERAL MARK (MISSING)

316 17-16.50N 042-19.21E PORT LATERAL MARK (UNLIT)
602 17-14.92N 042-10.13E SPECIAL MARK (UNLIT)
603 17-16.60N 042-07.65E SPECIAL MARK (UNLIT)
604 17-17.80N 042-09.00E SPECIAL MARK (UNLIT)
606 17-18.65N 042-07.19E SPECIAL MARK (UNLIT)
607 17-19.88N 042-08.69E SPECIAL MARK (UNLIT)
608 17-17.44N 042-13.88E SPECIAL MARK (UNLIT)
609 17-16.72N 042-15.46E SPECIAL MARK (UNLIT)
610 17-16.05N 042-15.79E SPECIAL MARK (UNLIT)
611 17-14.43N 042-15.29E SPECIAL MARK (UNLIT)
908 17-14.46N 042-16.58E PORT LATERAL MARK (UNLIT)

3. MARINERS CAUTIONED

SECURITE

171500 UTC JAN 2023

NAVAREA IX 028/23 RED SEA SAUDI ARABIA (JEDDAH)

BA CHARTS 158 AND 2659

2. DGPS STATION 961 IN POSITION 21-28.4N 039-08.9E REPORTED OFF AIR

3. MARINERS CAUTIONED

SECURITE

221500 UTC DEC 2022

NAVAREA IX 513/22 RED SEA SAUDI ARABIA (YANBU)

(.) CHARTS BA 158 AND 327

2. YANBU COMMERCIAL PORT MOORING BUOY B-3 IN POSITION

23-57.82N, 038-01.30E REPORTED MISSING

3. MARINERS CAUTIONED

SECURITE

151500 UTC DEC 2022

NAVAREA IX 507/22 IRAN BANDAR ABBAS

(BANDAR-E SHAHID RAJAI) CHARTS BA 2888, 3173

AND 3599

2. ISOLATED DANGER LIGHTBUOY (FL (2) 6 SECOND 5 M)

ESTABLISHED IN POSITION 27-06.60N 056 05.96E 3. SOUTH CARDINAL BEACON (Q (6) + LFL
15 SECOND 5 M)

ESTABLISHED IN POSITION 27-06.86N 056-06.46E 4. MARINERS CAUTIONED

SECURITE

061500 UTC DEC 2022

NAVAREA IX 497/22 CENTERAL GULF BAHRAIN

CHARTS BA 3736,3737 AND 3790

2. STARBOARD HAND BUOY S1-3 PERMANENTLY SHIFTED TO

POSITION 26-11.31N, 050-37.24E 3. MARINERS CAUTIONED

SECURITE

301500 UTC NOV 2022

NAVAREA IX 489/22 RED SEA

SAUDI ARABIA (YANBU)(.) CHARTS BA 158 AND 327
2 YANBU COMMERCIAL PORT MOORING BUOY B-2 IN POSITION
23 59.10N, 038-01.70E REPORTED MISSING
3 MARINERS CAUTIONED

SECURITE

241500 UTC NOV 2022

NAVAREA IX 480/22 IRAN KHALIJ-E-CHAHBAHAR

CHARTS BA 2851

2. CHANGES IN AID TO NAVIGATION CHAHBAHAR APPROACH CHANNEL
A. BUOYS/BEACON MOVED:
SAFE WATER BUOY ISO (1) 4 SECOND 5M
FROM: 25-16.34N 060-33.23E TO: 25-16.25N 060-33.29E CHAHBAHAR LATTICE BEACON
FL (2) 15 SECOND 12M
FROM: 25-17.17N 060-36.62E TO: 25-17.18N 060-36.62E PORT HAND BUOY NO.2 FL
(2) 5 SECOND 5M
FROM: 25-18.92N 060-33.33E TO: 25-19.02N 060-35.70E B. NEW BUOYS/BEACON
ESTABLISHED:
STARBOARD HAND BUOY NO.1 25-18.89N 060-35.78E FL(2)5SECOND 5M
STARBOARD HAND BUOY (HAFT-E TIR) 25-18.51N 060-36.85E FL(2)5SECOND 3M
STARBOARD HAND BEACON (BREAKWATER END) 25-18.37N 060-35.00E FL(3)6SECOND 5M
STARBOARD HAND BEACON (BREAKWATER BEND) 25-18.09N 060-35.80E FL(3)6SECOND 5M
PORT HAND BEACON (BREAKWATER END) 25-18.64N 060-36.02E FL(3)6SECOND 5M
C. BUOYS PERMANENTLY DISCONTINUED:
PREFERRED CHANNEL TO PORT HAND BUOY 25-18.81N 060-35.58E SPECIAL BUOY
25-17.87N 060-36.25E SOUTH CARDINAL BUOY
25-18.74N 060-35.05E SOUTH CARDINAL BUOY 25-19.02N 060-35.71E 3.
MARINERS CAUTIONED

SECURITE

221500 UTC NOV 2022

NAVAREA IX 477/22 IRAN RAS-E-BOSTANEH

CHARTS BA 2441, 2837 AND 2887

2. LATTICE BEACON IN POSITION 26-30.05N 054-37.32E TEMPORARILY DISCONTINUED
3. MARINERS CAUTIONED.

SECURITE

010650 UTC NOV 2022

NAVAREA IX 443/22 EGYPT GULF OF

SUEZ CHARTS BA 159 AND 2374

2. ANCHORING PROHIBITED IN SUBMARINE CABLE
AREA BOUNDED BY FOLLOWING COORDINATES:

28-22.05N 033-04.90E 28-23.13N 033-06.34E 28-22.55N 033-07.05E 28-21.72N 033-05.79E

3. MARINERS CAUTIONED

SECURITE

151500 UTC SEP 2022

NAVAREA IX 358/22 IRAN BANDAR-E EMAM KHOMEINI

CHARTS BA 1269 AND 2884

2. BUOYS PERMANENTLY DISCONTINUED:

PORT HAND BUOY NO 40 30-22.82N 048-54.28E PORT HAND BUOY NO 44 30-23.89N
049-00.58E 3. NEW BEACONS ESTABLISHED:

PORT HAND BEACON NO 40 30-22.84N 048-54.26E FL(1) 3SEC 7M

PORT HAND BEACON NO 44 30-23.90N 049-00.53E FL(2) 4SEC 7M

4. MARINERS CAUTIONED

SECURITE

160440 UTC MAY 2022

NAVAREA IX 185/22 NORTHERN GULF

KUWAIT CHARTS BA 2882, 2884 AND 3773

2. SOUTH CARDINAL BUOY (VQ (6) LFL 10 SECONDS)

TEMPORARILY DEPLOYED TO MARK SUNKEN VESSEL IN

POSITION 29-19.65N 048-25.48E. 3. MARINERS CAUTIONED

SECURITE

310300 UTC AUG 2022

NAVAREA IX 331/22 PAKISTAN PORT MUHAMMAD BIN

QASIM CHARTS PAK 5 (INT 7314), 20 (INT 7316) AND BA 59

2. AHSAN CHANNEL FORWARD LEADING LIGHT (FLL) IN POSITION

24-37.98N 067-06.27E REPORTED DAMAGED

3. AHSAN CHANNEL REAR LEADING LIGHT (RLL) IN POSITION

24-39.44N 067-07.29E REPORTED UNLIT

4. MARINERS CAUTIONED

5. CANCEL NAVAREA WARNINGS 336/21 AND 194/22

SECURITE

301500 UTC AUG 2022

NAVAREA IX 328/22 PAKISTAN KPT CHARTS

PAK 30 (INT 7315) AND BA 40

2. FOLLOWING LEADING LIGHTS ROPORTED NON OPERATIONAL:

FRONT LEADING LIGHT (FLL) 24-47.72N 067-00.06E OC G.7S 13 METER

REAR LEADING LIGHT (RLL) 24-47.96N 067-00.28E OC G.5S 31.5 METER

3. MARINERS CAUTIONED

SECURITE

190500 UTC AUG 2022

NAVAREA IX 311/22 UAE DUBAI CHARTS 2442,

2887, 2889 AND 3413

2. UNDER WATER OPERATION IN PROGRESS (SUBSEA GAS LEAKAGE)

IN POSITION 25-36.90N 054-25.50E 3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION AND
MAINTAIN AN EXCLUSION ZONE OF 500 METERS AROUND THE POSITION
4. CANCEL NAVAREA IX WARNING 301 OF 2022

SECURITE

041500 UTC AUG 2022

NAVAREA IX 295/22 IRAN SHATT AL ARAB

CHARTS BA 1235 AND 3842

2. 03 LIGHTBUOYS ESTABLISHED:

A. STARBOARD HAND NO.03 FL(2) 18SEC 5M 29-50.72N 048-45.58E B. STARBOARD HAND NO.11 FL(2) 18SEC 5M 29-52.74N 048-40.94E C. STARBOARD HAND NO.13 FL(2) 20SEC 5M 29-53.64N 048-39.98E 4. MARINERS CAUTIONED

SECURITE

041500 UTC AUG 2022

NAVAREA IX 294/22 IRAN

RESHADAT OIL FIELD CHARTS BA 2886, 2887 AND 2889

2. SADRA SADAF-132 ACCOMMODATION BARGE TEMPORARILY MOORED WITH ANCHORS AND MARKED BY BUOYS IN POSITION 25-53.70N 052-54.80E 4. WIDE BERTH REQUESTED

SECURITE

071500 UTC JUNE 2022

NAVAREA IX 220/22 PAKISTAN OFF CAPE MONZE

CHARTS PAK 33, 57 (INT 751), BA 38 AND 707

2. 50 METERS LONG DHOW BURHAN NOOR (IMO NO 616897000)
SUNK IN POSITION 24-53N, 066-00E ON 06 JUN 22.

3. MARINERS CAUTIONED

SECURITE

241500 UTC MAY 2022

NAVAREA IX 198/22 CENTRAL GULF BAHRAIN

CHARTS BA 2837, 2847, 2886, 3738 AND 3790

2. BAHRAIN LIGHT BUOY IN POSITION 26-33.00N, 051-03.59E REPORTED UNLIT
3. MARINERS CAUTIONED

SECURITE

171550 UTC MAR 2022

NAVAREA IX 112/22 CENTRAL GULF QATAR

CHARTS BA 2837, 2883, 2886 AND 2887

2. VESSEL REPORTED CAPSIZED IN POSITION 26-52.1N, 052-19.4E WITHIN QATAR NORTH OIL AND GAS FIELD. THE SEARCH AND RESCUE

STILL LOOKING FOR ONE OF THE CREW MEMBERS WITHIN THE AREA

3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION WHILE

TRANSITING IN THE AREA

SECURITE

111500 UTC MAR 2022

NAVAREA IX 102/22 PAKISTAN

PORT MUHAMMAD BIN QASIM CHARTS

PAK 5, 20 AND BA 59

2. AHSAN CHANNEL BEACON NO.3 IN POSITION

24-34.70N 067-04.08E REPORTED DAMAGE AND BROKEN

3. NEW BOUY NO-3 FL(3)G 7S LAYED IN POSITION

24 34.68N 067 04.07E 4. MARINERS CAUTIONED

5. CANCEL NAVAREA IX WARNING 340/21

SECURITE

071500 UTC MAR 2022

NAVAREA IX 095/22 PAKISTAN PORT

MUHAMMAD BIN QASIM CHARTS PAK 5 (INT 7314),

20 (INT 7316) AND BA 59

2. KHUDDI LIGHT HOUSE (APPROACHES TO PORT
QASIM CHANNEL) REPORTED UNLIT.

3. MARINERS CAUTIONED

SECURITE

161100 UTC FEB 2022

NAVAREA IX 067/22 EASTERN GULF

DUBAI (PALM DEIRAH) CHARTS BA 2887, 2888,

3175 AND 3176

2. AN OBSTRUCTION REPORTED IN POSITION 25-20.90N 055-08.62E 3. MARINERS CAUTIONED

SECURITE

281500 UTC JAN 2022

NAVAREA IX 039/22 EASTERN GULF

DUBAI (PALM DEIRAH) CHARTS BA 2888, 2889, 3175 AND 3412

2. SHALLOW PATCHES REPORTED IN AREA BOUNDED BY

FOLLOWING COORDINATES:

25-20.90N 055-12.90E 25-23.00N 055-10.60E 25-23.80N 055-12.10E 25-22.50N 055-14.80E

3. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION

SECURITE

170450 UTC JAN 2022

NAVAREA IX 027/22 CENTRAL GULF

BAHRAIN CHARTS BA 2847, 2886 AND 3790

2. WRECK BUOY IN POSITION 26-35.94N, 050-58.51E REPORTED UNLIT

3. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION

SECURITE
141500 UTC DEC 2021
NAVAREA IX 491/21 IRAN BANDAR-E PARS
CHARTS BA 2837, 2858, 2883, 2886 AND 2887
2. DEEPSEA TREASURE JACKUP DRILLING RIG ESTABLISHED
IN POSITION 26-57.49N 052-26.85E 4. MARINERS ARE REQUESTED TO NAVIGATE WITH CAUTION
AND GIVE WIDE BERTH

SECURITE
141500 UTC DEC 2021
NAVAREA IX 490/21 IRAN KHALIJ-E CHABAHAR
CHARTS BA 2851, 2858 AND 4705
2. PREFERRED CHANNEL PILLAR LIGHT BUOY MOVED TO POSITION
25-18.81N 060-35.58E WITH FOLLOWING CHARACTERISTICS:
FLASHING: (2+1)7 SECONDS
HEIGHT : 3 METERS
RANGE : 3 MILES
3. PORT HAND BUOY IN POSITION 25-18.22N 060-34.39E PERMANENTLY DISCONTINUED
4. MARINERS CAUTIONED

SECURITE
171500 UTC NOV 2021
NAVAREA IX 448/21 IRAN SOUTH PARS
GAS FIELD CHARTS BA 2523, 2837, 2886 AND 2887
2. FATEH 900 ACCOMMODATION BARGE TEMPORARILY
MOORED IN POSITION 26-48.63N 052-20.16E WITH
ANCHORS MARKED BY BUOYS
3. MARINERS CAUTIONED

SECURITE
151500 UTC NOV 2021
NAVAREA IX 445/21 CENTRAL GULF
(.) QATAR CHART BA 2886 AND 2887
2. CREW BOAT MOORING BUOY AT AL KHALIJ
OILFIELD REPORTED MISSING IN POSITION 25-56.10N 052-41.40E 3. MARINERS CAUTIONED

SECURITE
251500 UTC OCT 2021
NAVAREA IX 399/21 PAKISTAN KARACHI
CHARTS PAK 33, 57 (INT 751), 58 (INT 7019), BA 38
AND 707
2. KARACHI RADIO (NAVTEX STATION) IN POSITION 24-52.78N 067-09.94E INOPERATIVE ALL
NAVIGATIONAL WARNINGS ARE
BEING TRANSMITTED ON INTERNATIONAL SAFETYNET AND AVAILABLE
ON WEBSITE WWW.HYDROGRAPHY.PAKNAVY.GOV.PK/NAVAREA-IX-WARNINGS

3. MARINERS CAUTIONED.
 4. CANCEL NAVAREA IX WARNING 301 OF 2021
-

SECURITE

251500 UTC OCT 2021

NAVAREA IX 397/21 ARABIAN SEA, GULF OF OMAN
AND PERSIAN GULF

2. US NGA HYDROGRAPHIC OFFICE (NAVIGATIONAL WARNING) 1478/20 (62,63)
IS REPRODUCED AS RECEIVED FOR THE INFORMATION OF MARINERS
AND SAFETY OF NAVIGATION
3. U.S. NAVAL FORCES ARE CONDUCTING ROUTINE OPERATIONS IN
THE REGION WITH A COMMITMENT TO FREEDOM OF NAVIGATION AND
THE FREE FLOW OF MARITIME COMMERCE. DUE TO RECENT EVENTS,
IN ORDER TO ENHANCE SAFETY, MINIMIZE AMBIGUITY, AND REDUCE
OPPORTUNITIES FOR MISCALCULATION, ALL VESSELS ARE ADVISED
TO MAINTAIN A SAFE DISTANCE OF AT LEAST 100 METERS FROM U.S.
NAVAL VESSELS IN INTERNATIONAL WATERS/STRAITS. ARMED VESSELS
APPROACHING WITHIN 100 METERS OF A U.S. NAVAL VESSEL MAY BE
INTERPRETED AS A THREAT AND SUBJECT TO LAWFUL DEFENSIVE MEASURES.
MARINERS ARE REMINDED TO OPERATE IN ACCORDANCE WITH INTERNATIONAL
LAW AND WITH DUE REGARD FOR THE SAFE NAVIGATION OF OTHER VESSELS.
ALL VESSELS OPERATING IN THE VICINITY OF U.S. NAVAL VESSELS ARE
ADVISED TO CLEARLY COMMUNICATE INTENTIONS, RESPOND TO QUERIES
CONCERNING COURSE AND SPEED, EXERCISE PRINCIPLES OF PRUDENT
SEAMANSHIP AS REQUIRED UNDER INTERNATIONAL LAW, AND REMAIN AT
THE MAXIMUM AVAILABLE DISTANCE FROM U.S. NAVAL FORCE.
4. CANCEL NAVAREA IX WARNING 215 OF 2020

SECURITE

141500 UTC MAR 2021

NAVAREA IX 109/21 QATAR CENTRAL GULF
CHARTS BA 3772, 3950, 2886, 2837, 2847, AND 2858

2. BARGE WRECK BUOY MISSING AT POSITION
25-57.71N 051-52.86E
 3. MARINERS ARE REQUESTED TO EXERCISE EXTREME CAUTION
WHEN TRANSITING THIS AREA
 4. CANCEL NAVAREA IX WARNING 096 OF 2019
-