HYUNDAI **Technical Service Bulletin**	GROUP **CAMPAIGN**	NUMBER **22-01-034H**
	DATE **APRIL 2022**	MODEL(S) **SEE APPLICABLE VEHICLES BELOW**

SUBJECT: OP CODE/PART NUMBER (REFERENCE GUIDE FOR SERVICE CAMPAIGN T3G)

Please note that this TSB references the op codes to use for claim submission and the parts required based on the vehicle's inspection results from TSB 22-01-033H (Theta GDI Engine DTC P1326 – Engine Bearing Inspection/Replacement).

This TSB supersedes 21-01-067H to:

- Add inspection op code 10D191R8 & 21102F08 to account for the additional 'seized' vehicle scenario of EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (NO)
- Add the case of 'EXTERNAL DAMAGE (YES) + SUBMIT PA' to inspection op codes 10D191R0 and 21102F00.
- To add a 'Notice' box on page 1 that a PA must be submitted for vehicles requiring an engine
- Input a note under all 'replacement' tables to submit a separate campaign 953 claim, as needed
- To clarify the 'special exception cases in #3' under the Warranty Information on page 2

Consult the Hyundai Warranty Policy & Procedures and the below tables to determine New or Reman engine usage.

- In some cases, a Reman engine may not be available for certain vehicle models/model years listed in the TSB. Thus, an 'OE' part would be used by default.

NOTICE

A Warranty Prior Approval (PA) must be submitted on all applicable vehicles that require an engine replacement.

Applicable Vehicles:

- Certain 2011-2014 MY Sonata (YF) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2015-2019 MY Sonata (LF) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2019 MY Santa Fe (TM) vehicles with Theta II 2.0L Turbo and 2.4L GDI engines
- Certain 2014-2015 MY Tucson (LM) vehicles with Theta II 2.4L GDI engines
- Certain 2018-2019 MY Tucson (TL) vehicles with Theta II 2.4L GDI engines
- Certain 2019 MY Veloster N (JSN) vehicles with Theta II 2.0L Turbo GDI engines

Warranty Information:

1. Claim Submission:

- **One (1) claim for inspection.**
- **One (1) claim for replacement of engine/knock sensor, as needed.**
- **11-18MY** vehicles: Submit Claim(s) on **Campaign Claim Entry Screen.**
- **19MY** vehicles: Submit Claim(s) on **Warranty Claim Entry Screen.** Q75 for Nature, ZZ1 for Cause.
- **Additional claims, as needed:**
  - If a part is in need of replacement and the **malfunction is directly caused by Campaign T3G** related engine failure, or if additional labor is required while performing Campaign T3G:
    - Submit one compiled separate claim using the same Repair Order number AND
    - Submit with 21101NTT using the engine Causal Part number associated with the T3G OP Code AND
    - Ensure part replacement and punch times are accurate and that they match the labor performed along with the service manager's signature approving the TT time.
      - For TT time best practices, refer to Hyundaidealer.com > Service Tab > Documents Library > Warranty > ATT-NTT Documentation and Claim Submission Guide
    - Note: If the part replacement does not require additional labor, follow the above steps and use the system minimum of .1 labor time with a quantity of 1.
- If a part is found in need of replacement while performing this campaign and the affected part **(malfunction not directly caused by Campaign T3G**) is still under warranty, submit a separate claim using the same repair order. If the affected part(s) are out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

2. **PA approval only required for op codes with engine replacement:**
- OP Codes for engine replacement must only be used if engine replacement is deemed necessary by the service procedure in **T3G TSB 22-01-033H (or latest version).**

3. **Special Exception Cases**
- For 2017MY Sonata 2.4L engine replacement ONLY, please refer below for specific instructions:
  - If production date is before 5/13/2016, order 21101-2GK33QQH/RM.
  - If production date is after 5/19/2016, order 21101-2GK34QQH/RM.
  - If the last 6 digits of the VIN **are below**, order 21101-2GK33QQH/RM.
  - If the last 6 digits of the VIN are **not below**, order 21101-2GK34QQH/RM.

443013	443094	443107	443124	443137	443148	443159	443173	443202
443026	443095	443109	443125	443138	443149	443160	443175	443206
443051	443097	443110	443127	443139	443150	443161	443178	443208
443069	443098	443113	443128	443140	443151	443162	443181	443210
443083	443099	443114	443131	443141	443152	443164	443185	
443086	443100	443116	443132	443142	443153	443165	443187	
443087	443102	443117	443133	443143	443154	443166	443195	
443089	443104	443119	443134	443145	443156	443167	443196	
443091	443105	443120	443135	443146	443157	443170	443197	
443093	443106	443123	443136	443147	443158	443171	443200	

- Engines for 19MY vehicles may be superseded by a different part number than what is listed in this TSB. Please use the latest engine part number available if such a supersession occurs.

4. **Campaign 953 Claim Submission**
   - Campaign 953 Engine ECM update is only required if new software is available.
   - Please submit a separate campaign claim for the ECM update using Campaign 953 OP Codes. These particular op codes are identified in the replacement op code tables below with an asterisk (*).

A Summary of the Updated T3G Claim Submission Process can also be accessed via:

- **QR Code or Link: https://vimeo.com/642066125/1aec30b26a**

Table of Contents

Replacement tables are by models/model years, Smart Cruise Control (SCC) (if applicable), & Drive Train (FWD/AWD) (if applicable).

Op Code Tables:

1) Inspection Table for 11-18MY Vehicles (Campaign) – Page 4
2) Replacement Tables for 11-18MY (Campaign)
- **A)** 2011-13MY Sonata 2.0T & 2011-13 Sonata 2.4L – **Page 5**
- **B)** 2014 Sonata 2.0T & 2014 Sonata 2.4L – **Page 6**
- **C)** 2015-18 Sonata 2.0T, non-SCC & 2015-18 Sonata 2.0T, SCC – **Page 7**
- **D)** 2015 Sonata 2.4L, non-SCC & 2015 Sonata 2.4L, SCC – **Page 8**
- **E)** 2016 Sonata 2.4L, non-SCC & 2016 Sonata 2.4L, SCC – **Page 9**
- **F)** 2017 Sonata 2.4L, non-SCC & 2017 Sonata 2.4L, SCC – **Page 10**
- **G)** 2018 Sonata 2.4L, non-SCC & 2018 Sonata 2.4L, SCC – **Page 11**
- **H)** 2013 Santa Fe Sport 2.0T, FWD, non-SCC & 2013 Santa Fe Sport 2.0T, FWD, SCC – **Page 12**
- **I)** 2013 Santa Fe Sport 2.0T, AWD, non-SCC & 2013 Santa Fe Sport 2.0T, AWD, SCC – **Page 13**
- **J)** 2014-16 Santa Fe Sport 2.0T, FWD, non-SCC & 2014-16 Santa Fe Sport 2.0T, FWD, SCC – **Page 14**
- **K)** 2014-16 Santa Fe Sport 2.0T, AWD, non-SCC & 2014-16 Santa Fe Sport 2.0T, AWD, SCC – **Page 15**
- **L)** 2017-18 Santa Fe Sport 2.0T, FWD, non-SCC & 2017-18 Santa Fe Sport 2.0T, FWD, SCC – **Page 16**
- **M)** 2017-18 Santa Fe Sport 2.0T, AWD, non-SCC & 2017-18 Santa Fe Sport 2.0T, AWD, SCC – **Page 17**
- **N)** 2013 Santa Fe Sport 2.4L, FWD, non-SCC & 2013 Santa Fe Sport 2.4L FWD, SCC – **Page 18**
- **O)** 2013 Santa Fe Sport 2.4L, AWD, non-SCC & 2013 Santa Fe Sport 2.4L AWD, SCC – **Page 19**
- **P)** 2014-16 Santa Fe Sport 2.4L, FWD, non-SCC & 2014-16 Santa Fe Sport 2.4L, FWD, SCC – **Page 20**
- **Q)** 2014-16 Santa Fe Sport 2.4L, AWD, non-SCC & 2014-16 Santa Fe Sport 2.4L, AWD, SCC – **Page 21**
- **R)** 2017-18 Santa Fe Sport 2.4L, FWD, non-SCC & 2017-18 Santa Fe Sport 2.4L, FWD, SCC – **Page 22**
- **S)** 2017-18 Santa Fe Sport 2.4L, AWD, non-SCC & 2017-18 Santa Fe Sport 2.4L, AWD, SCC – **Page 23**
- **T)** 2014-15 Tucson 2.4L, FWD & 2014-15 Tucson 2.4L, AWD – **Page 24**
- **U)** 2018 Tucson 2.4L, FWD & 2018 Tucson 2.4L, AWD **Page 25**

3) Inspection Table for 19MY Vehicles (Warranty) – Page 26
4) Replacement Tables for 19MY (Warranty)
- A) 2019 Sonata 2.0T, 2019 Sonata 2.4L, 2019 Santa Fe 2.0T, FWD – **Page 27**
- B) 2019 Santa Fe 2.0T, AWD, 2019 Santa Fe 2.4L, FWD & 2019 Santa Fe 2.4L, AWD – **Page 28**
- C) 2019 Tucson 2.4L, FWD & 2019 Tucson 2.4L, AWD – **Page 29**
- D) 2019 Veloster N 2.0T – **Page 30**

11-18MY Inspection OP Code Table (Campaign)

VEHICLES	DESCRIPTION	OP CODE	OP TIME
ALL 11-18MY	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (NO) + SUBMIT PA **OR** EXTERNAL DAMAGE (YES) + SUBMIT PA	10D191R0	0.3
	(SEIZED): EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (NO) + SUBMIT PA	10D191R1	1.7
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (NO PASS)	10D191R2	1.4
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (PASS)	10D191R3	1.1
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (NO BCT)	10D191R4	1.7
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (NO PASS)	10D191R5	1.1
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (PASS)	10D191R6	0.8
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (NO BCT)	10D191R7	1.4
	(SEIZED): EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (NO) + SUBMIT PA	10D191R8	1.4

Replacement Op Code Tables (11-18MY)

1) 2011-2013MY Sonata (YF) 2.0T (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192AA	5.8	211012GK60QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192AC	5.8	211012GK60QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AB	5.7	211012GK60QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AD	5.7	211012GK60QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192AE	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192AF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192AG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192AH	6.4	211012GK60QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192AJ	6.4	211012GK60QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AI	6.3	211012GK60QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AK	6.3	211012GK60QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

2) 2011-2013MY Sonata (YF) 2.4L (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192BA	5.3	211012GK50QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192BC	5.3	211012GK50QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BB	5.2	211012GK50QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BD	5.2	211012GK50QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192BE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192BF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192BG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192BH	5.9	211012GK50QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192BJ	5.9	211012GK50QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BI	5.8	211012GK50QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BK	5.8	211012GK50QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

3) 2014MY Sonata (YF) 2.0T (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192AA	5.8	211012GK80QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192AC	5.8	211012GK80QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AB	5.7	211012GK80QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AD	5.7	211012GK80QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192AE	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192AF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192AG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192AH	6.4	211012GK80QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192AJ	6.4	211012GK80QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AI	6.3	211012GK80QQH	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192AK	6.3	211012GK80QQHRM	211112GK60QQH	211112GK70QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

4) 2014MY Sonata (YF) 2.4L (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192BA	5.3	211012GK70QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192BC	5.3	211012GK70QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BB	5.2	211012GK70QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BD	5.2	211012GK70QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192BE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192BF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192BG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192BH	5.9	211012GK70QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192BJ	5.9	211012GK70QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BI	5.8	211012GK70QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192BK	5.8	211012GK70QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

5) 2015-2018MY Sonata (LF) 2.0T, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192DA	6.3	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192DC	6.3	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192DB	6.2	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192DD	6.2	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192DE	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192DF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192DG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192DH	6.9	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192DJ	6.9	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192DI	6.8	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192DK	6.8	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

6) 2015-2018MY Sonata (LF) 2.0T, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192CA	6.8	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192CC	6.8	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192CB	6.7	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192CD	6.7	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192CE	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192CF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192CG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192CH	7.4	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192CJ	7.4	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192CI	7.3	211012GK32QQH	211112GK52QQH	211112GK72QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192CK	7.3	211012GK32QQHRM	211112GK52QQH	211112GK72QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

7) 2015MY Sonata (LF) 2.4L, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FA	5.4	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FC	5.4	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FB	5.3	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FD	5.3	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192FE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192FF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192FG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FH	6.0	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FJ	6.0	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FI	5.9	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FK	5.9	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

8) 2015MY Sonata (LF) 2.4L, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EA	5.9	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EC	5.9	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EB	5.8	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ED	5.8	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192EE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192EF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192EG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EH	6.5	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EJ	6.5	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EI	6.4	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EK	6.4	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

9) 2016MY Sonata (LF) 2.4L, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FA	5.4	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FC	5.4	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FB	5.3	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FD	5.3	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192FE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192FF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192FG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FH	6.0	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FJ	6.0	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FI	5.9	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FK	5.9	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

10) 2016MY Sonata (LF) 2.4L, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EA	5.9	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EC	5.9	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EB	5.8	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ED	5.8	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192EE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192EF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192EG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EH	6.5	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EJ	6.5	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EI	6.4	211012GK33QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EK	6.4	211012GK33QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

11) 2017MY Sonata (LF) 2.4L, non-SCC (Campaign) – Refer to page 2 for specific engine usage

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FA	5.4	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FC	5.4	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FB	5.3	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FD	5.3	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192FE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192FF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192FG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FH	6.0	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FJ	6.0	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FI	5.9	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FK	5.9	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

12) 2017MY Sonata (LF) 2.4L, SCC (Campaign) – Refer to page 2 for specific engine usage

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EA	5.9	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EC	5.9	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EB	5.8	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ED	5.8	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192EE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192EF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192EG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EH	6.5	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EJ	6.5	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EI	6.4	211012GK33QQH 211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EK	6.4	211012GK33QQHRM 211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

13) 2018MY Sonata (LF) 2.4L, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FA	5.4	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FC	5.4	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FB	5.3	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FD	5.3	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192FE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192FF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192FG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192FH	6.0	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192FJ	6.0	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FI	5.9	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192FK	5.9	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

14) 2018MY Sonata (LF) 2.4L, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EA	5.9	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EC	5.9	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EB	5.8	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ED	5.8	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192EE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192EF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192EG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192EH	6.5	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192EJ	6.5	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EI	6.4	211012GK34QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192EK	6.4	211012GK34QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

15) 2013MY Santa Fe Sport (AN) 2.0T, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LA	6.1	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LC	6.1	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LB	6.0	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LD	6.0	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192LE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192LF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192LG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LH	6.7	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LJ	6.7	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LI	6.6	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LK	6.6	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

16) 2013MY Santa Fe Sport (AN) 2.0T, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KA	6.6	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KC	6.6	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KB	6.5	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KD	6.5	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192KE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192KF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192KG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KH	7.2	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KJ	7.2	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KI	7.1	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KK	7.1	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

17) 2013MY Santa Fe Sport (AN) 2.0T, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NA	6.5	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NC	6.5	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NB	6.4	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ND	6.4	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192NE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192NF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192NG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NH	7.1	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NJ	7.1	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NI	7.0	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NK	7.0	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

18) 2013MY Santa Fe Sport (AN) 2.0T, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MA	7.0	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MC	7.0	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MB	6.9	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MD	6.9	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192ME	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192MF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192MG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MH	7.6	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MJ	7.6	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MI	7.5	211012GK03QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MK	7.5	211012GK03QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

19) 2014-2016MY Santa Fe Sport (AN) 2.0T, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LA	6.1	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LC	6.1	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LB	6.0	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LD	6.0	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192LE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192LF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192LG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LH	6.7	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LJ	6.7	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LI	6.6	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LK	6.6	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

20) 2014-16MY Santa Fe Sport (AN) 2.0T, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KA	6.6	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KC	6.6	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KB	6.5	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KD	6.5	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192KE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192KF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192KG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KH	7.2	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KJ	7.2	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KI	7.1	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KK	7.1	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

21) 2014-2016MY Santa Fe Sport (AN) 2.0T, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NA	6.5	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NC	6.5	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NB	6.4	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ND	6.4	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192NE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192NF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192NG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NH	7.1	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NJ	7.1	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NI	7.0	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NK	7.0	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

22) 2014-16MY Santa Fe Sport (AN) 2.0T, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MA	7.0	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MC	7.0	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MB	6.9	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MD	6.9	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192ME	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192MF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192MG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MH	7.6	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MJ	7.6	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MI	7.5	211012GK04QQH	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MK	7.5	211012GK04QQHRM	211112GK60QQH	211112GK80QQH	254702G650QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

23) 2017-2018MY Santa Fe Sport (AN) 2.0T, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LA	6.1	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LC	6.1	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LB	6.0	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LD	6.0	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192LE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192LF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192LG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192LH	6.7	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192LJ	6.7	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LI	6.6	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192LK	6.6	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

24) 2017-18MY Santa Fe Sport (AN) 2.0T, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KA	6.6	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KC	6.6	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KB	6.5	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KD	6.5	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192KE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192KF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192KG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192KH	7.2	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192KJ	7.2	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KI	7.1	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192KK	7.1	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

25) 2017-2018MY Santa Fe Sport (AN) 2.0T, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NA	6.5	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NC	6.5	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NB	6.4	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ND	6.4	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192NE	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192NF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192NG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192NH	7.1	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192NJ	7.1	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NI	7.0	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192NK	7.0	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

26) 2017-18MY Santa Fe Sport (AN) 2.0T, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MA	7.0	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MC	7.0	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MB	6.9	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MD	6.9	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192ME	1.5	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192MF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192MG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192MH	7.6	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192MJ	7.6	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MI	7.5	211012GK32QQH	211112GK52QQH	211112GK73QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192MK	7.5	211012GK32QQHRM	211112GK52QQH	211112GK73QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

27) 2013MY Santa Fe Sport (AN) 2.4L, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HA	5.3	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HC	5.3	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HB	5.2	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HD	5.2	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192HE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192HF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192HG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HH	5.9	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HJ	5.9	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HI	5.8	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HK	5.8	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

28) 2013MY Santa Fe Sport (AN) 2.4L, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GA	5.8	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GC	5.8	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GB	5.7	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GD	5.7	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192GE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192GF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192GG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GH	6.4	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GJ	6.4	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GI	6.3	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GK	6.3	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

29) 2013MY Santa Fe Sport (AN) 2.4L, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JA	5.7	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JC	5.7	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JB	5.6	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JD	5.6	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192JE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192JF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192JG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JH	6.3	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JJ	6.3	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JI	6.2	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JK	6.2	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

30) 2013MY Santa Fe Sport (AN) 2.4L, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IA	6.2	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IC	6.2	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IB	6.1	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ID	6.1	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192IE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192IF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192IG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IH	6.8	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IJ	6.8	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192II	6.7	211012GK01QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IK	6.7	211012GK01QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

31) 2014-16MY Santa Fe Sport (AN) 2.4L, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HA	5.3	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HC	5.3	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HB	5.2	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HD	5.2	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192HE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192HF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192HG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HH	5.9	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HJ	5.9	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HI	5.8	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HK	5.8	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

32) 2014-16MY Santa Fe Sport (AN) 2.4L, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GA	5.8	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GC	5.8	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GB	5.7	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GD	5.7	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192GE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192GF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192GG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GH	6.4	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GJ	6.4	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GI	6.3	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GK	6.3	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

33) 2014-16MY Santa Fe Sport (AN) 2.4L, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JA	5.7	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JC	5.7	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JB	5.6	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JD	5.6	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192JE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192JF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192JG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JH	6.3	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JJ	6.3	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JI	6.2	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JK	6.2	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

34) 2014-16MY Santa Fe Sport (AN) 2.4L, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IA	6.2	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IC	6.2	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IB	6.1	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ID	6.1	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192IE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192IF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192IG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IH	6.8	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IJ	6.8	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192II	6.7	211012GK02QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IK	6.7	211012GK02QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

35) 2017-18MY Santa Fe Sport (AN) 2.4L, FWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HA	5.3	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HC	5.3	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HB	5.2	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HD	5.2	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192HE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192HF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192HG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192HH	5.9	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192HJ	5.9	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HI	5.8	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192HK	5.8	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

36) 2017-18MY Santa Fe Sport (AN) 2.4L, FWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GA	5.8	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GC	5.8	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GB	5.7	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GD	5.7	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192GE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192GF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192GG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192GH	6.4	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192GJ	6.4	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GI	6.3	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192GK	6.3	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

37) 2017-18MY Santa Fe Sport (AN) 2.4L, AWD, non-SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JA	5.7	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JC	5.7	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JB	5.6	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JD	5.6	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192JE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192JF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192JG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192JH	6.3	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192JJ	6.3	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JI	6.2	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192JK	6.2	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

38) 2017-18MY Santa Fe Sport (AN) 2.4L, AWD, SCC (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IA	6.2	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IC	6.2	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IB	6.1	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192ID	6.1	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192IE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192IF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192IG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192IH	6.8	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192IJ	6.8	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192II	6.7	211012GK31QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192IK	6.7	211012GK31QQHRM	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

39) 2014-15MY Tucson (LM) 2.4L, FWD (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192QA	5.2	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192QC	5.2	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192QB	5.1	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192QD	5.1	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192QE	0.5	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192QF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192QG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192QH	5.8	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192QJ	5.8	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192QI	5.7	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192QK	5.7	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

40) 2014-15MY Tucson (LM) 2.4L, AWD (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192SA	5.7	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192SC	5.7	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192SB	5.6	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192SD	5.6	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192SE	0.5	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192SF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192SG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192SH	6.3	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (NO)	10D192SJ	6.3	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192SI	6.2	211012GK36QQH	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192SK	6.2	211012GK36QQHRM	211112GK50QQH	211112GK70QQH	254702G050QQH	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

41) 2018MY Tucson (TL) 2.4L, FWD (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192OA	5.1	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192OB	5.0	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192OE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192OF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192OG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192OH	5.7	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192OI	5.6	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

42) 2018MY Tucson (TL) 2.4L, AWD (Campaign)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192PA	5.5	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192PB	5.4	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	10D192PE	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	10D192PF	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	10D192PG	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (NO)	10D192PH	6.1	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	10D192PI	6.0	211012GK52QQH	211112GK51QQH	211112GK71QQH	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

19MY Inspection OP Code Table (Warranty)

VEHICLES	DESCRIPTION	OP CODE	OP TIME
ALL 19MY	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (NO) + SUBMIT PA **OR** EXTERNAL DAMAGE (YES) + SUBMIT PA	21102F00	0.3
	(SEIZED): EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (NO) + SUBMIT PA	21102F01	1.7
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (NO PASS)	21102F02	1.4
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (PASS)	21102F03	1.1
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (NO) + OIL DRAIN ≥ 1.5QT (YES) + CRANK ROTATION (YES) + BCT RESULT (NO BCT)	21102F04	1.7
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (NO PASS)	21102F05	1.1
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (PASS)	21102F06	0.8
	EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (YES) + BCT RESULT (NO BCT)	21102F07	1.4
	(SEIZED): EXTERNAL DAMAGE (NO) + OIL DIPSTICK (YES) + CRANK ROTATION (NO) + SUBMIT PA	21102F08	1.4

Replacement Op Code Tables (19MY)

43) 2019MY Sonata (LF) 2.0T (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F00	7.7	211012GK16 211012GK16HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F01	7.6	211012GK16 211012GK16HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F02	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F03	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F04	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F05	8.3	211012GK16 211012GK16HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F06	8.2	211012GK16 211012GK16HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

44) 2019MY Sonata (LF) 2.4L (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F07	6.9	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F08	6.8	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F09	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F10	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F11	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F12	7.5	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F13	7.4	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

45) 2019MY Santa Fe (TM) 2.0T, FWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F28	7.6	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F29	7.5	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F30	1.3	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F31	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F32	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F33	8.2	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F34	8.1	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

46) 2019MY Santa Fe (TM) 2.0T, AWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F35	8.0	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F36	7.9	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F37	1.3	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F38	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F39	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F40	8.6	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F41	8.5	211012GK17 211012GK17HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

47) 2019MY Santa Fe (TM) 2.4L, FWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F42	7.1	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F43	7.0	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F44	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F45	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F46	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F47	7.7	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F48	7.6	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

48) 2019MY Santa Fe (TM) 2.4L, AWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F49	7.5	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F50	7.4	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F51	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F52	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F53	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F54	8.1	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F55	8.0	211012GK18 211012GK18HRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

49) 2019MY Tucson (TL) 2.4L, FWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F14	7.0	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F15	6.9	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F16	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F17	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F18	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F19	7.6	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F20	7.5	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

50) 2019MY Tucson (TL) 2.4L, AWD (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F21	7.4	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F22	7.3	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F23	1.1	N/A	N/A	N/A	N/A	392502G100
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F24	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F25	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F26	8.0	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F27	7.9	1T20G2GA13F 1T20G2GA13FHRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.

51) 2019MY Veloster (JSN) 2.0T (Warranty)

DESCRIPTION	OP CODE	TIME	ENGINE	SVC KIT 1	SVC KIT 2	OIL COOLER PIPE	KNOCK SENSOR
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F56	8.1	1T05T2GA14F 1T05T2GA14FHRM	N/A	N/A	N/A	N/A
REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F57	8.0	1T05T2GA14F 1T05T2GA14FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (NO) + REPLACE KNOCK SENSOR + ECM UPDATE (NO)	21103F58	1.1	N/A	N/A	N/A	N/A	392502G700
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (NO)	21103F59	0.6	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + ECM UPDATE (YES)*	21103F60	0.5	N/A	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (NO)	21103F61	8.7	1T05T2GA14F 1T05T2GA14FHRM	N/A	N/A	N/A	N/A
ABNORMAL ENGINE NOISE (YES) + REFER TO HTSS (YES)/SUBMIT PA + REPLACE ENGINE (OE/REMAN) + NEW ECM S/W AVAILABLE (YES) + ECM UPDATE (YES)*	21103F62	8.6	1T05T2GA14F 1T05T2GA14FHRM	N/A	N/A	N/A	N/A

*Please submit an additional campaign claim under service campaign 953 for performing software update if new software is available.