



Inspection report, Final: PO003459

KS101920-GOLD: CHERRY JEWELRY SET



[Online report](#)

Inspector	QC-JOJO Chen	Inspection Date	Jun 04, 2026
Sample Qty	80	Order Qty	804
Location	29° 21' 13" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Jun 04, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved
----------------------	----------

SUMMARY

	PO003459:KS101920-GOLD
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	



	CRITICAL	MAJOR	MINOR
WX Other.	-	1	-
F5 Coarse/thick Yarn.	-	-	2
F7 Damaged fabric.	-	-	1
TOTAL	0	1	3
AQL MAX	0	5	7

DEFECTS: 4

1	WX Other. The buckle has poor elasticity. (Automatic translation)	MAJOR Items affected: 1
---	--	-----------------------------------



2	F5 Coarse/thick Yarn. -	MINOR Items affected: 2
---	-------------------------	---



3	F7 Damaged fabric. The edges of the leaves are blemishes (Automatic translation)	MINOR Items affected: 1
---	--	---



CHECKPOINTS: 25

1	Factory details	
---	-----------------	-------------

1.1	Factory name at the location for QC (not supplier name)	OK
-----	---	----

Factory Name:

昊林饰品有限公司

Factory Address:

浙江省金华市义乌市后宅街道柳青路1569号





2	Quantity Check	
---	----------------	-------------

2.1	Warehouse / carton piled view	OK
-----	-------------------------------	----



2.2	Production quantity match PO	OK
	Bulk order quantity: 804 sets Bulk packing quantity: 804 sets (Automatic translation)	



3	Product	
---	---------	-------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
-----	--	----




3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----

OS: (804)

Barcode can be scanned	OK
Scanned barcode	5715404340137
Barcode from order data	5715404340137
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715404341998
Barcode from order data	
Scanned format	EAN_13



3.3	Embroidery / Printing check	OK
-----	-----------------------------	----



3.4	Lace / Trimming / Accessories check	
-----	-------------------------------------	--

3.5	Workmanship	OK
-----	-------------	----



3.6	Measurement	OK
The bulk order and the confirmed sample are the same length. (Automatic translation)		


	Specification	Tolerance	Actual
	-	-	



4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
-----	-----------	----




4.3	Smell check	OK
-----	-------------	----



4.4	Humidity check	
-----	----------------	--

4.5	Garment weight (sweater only)	
-----	-------------------------------	--


4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
-----	--	----



4.8	功能测试	OK
-----	------	----



5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
-----	---	----




Confirmation sample provided by the factory



5.2	Export carton (shipping mark, barcode)	OK
-----	--	----


Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	40
W	-	-	35
H	-	-	40

Gross Weight	-	-	7.7
--------------	---	---	-----





5.4 Carton Packing (quantity, ratio etc), 3 ply carton


OK



5.5 Inner package (polybag, sticker, tissue paper, silica gel etc)

OK





5.6	Hanger (quality, size etc)	
5.7	Header card	
5.8	Products are in polybags	OK

