



Inspection report, Final: PO003632

KS103368-SIROCCO: VALENTINES TUT SHOULDER BAG



[Online report](#)

Inspector	QC-JOJO Chen	Inspection Date	Sep 23, 2026
Sample Qty	125	Order Qty	1398
Location	29° 21' 10" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Sep 23, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Rejected	Reasons for rejection in bulk orders: - Excessive dirt on the lining, covering approximately 20%-30% of the bag; stitched-in care labels; needle holes; glue residue on care labels. - Uneven width of the 4.5cm height strip; uneven width of exposed zippers and webbing; serious issues will result in rejection. - Loose threads and debris inside the bag must be cleaned. - Bags with exposed sequins will not be accepted. All of the above issues require rework; each bag must be carefully inspected. (Automatic translation)
----------------------	-----------------	---





SUMMARY

	PO003632:KS103368-SIROCCO
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	




	CRITICAL	MAJOR	MINOR
T6 Care label.	-	4	-
F1 Soiling/stains.	-	-	7
A5 Unevenness.	-	-	4
A5 Unevenness.	-	-	2
W7 Seam slippage.	-	-	1
W1 Threads, untrimmed.	-	-	1
W5 Seam (overlock).	-	-	1
TOTAL	0	4	16
AQL MAX	0	7	10

DEFECTS: 20



1	T6 Care label. The care label was sewn on, there were pinholes and glue marks. (Automatic translation)	MAJOR Items affected: 4
---	---	----------------------------





2	F1 Soiling/stains. Lining stains (Automatic translation)	MINOR Items affected: 7
---	---	----------------------------



3	A5 Unevenness. The sequins fell off, revealing the base layer. (Automatic translation)	MINOR Items affected: 4
---	---	----------------------------




4	A5 Unevenness. Uneven width (Automatic translation)	MINOR Items affected: 2
---	--	----------------------------



5	W7 Seam slippage. Broken embroidery thread (Automatic translation)	MINOR Items affected: 1
---	---	----------------------------



6	W1 Threads, untrimmed. -	MINOR Items affected: 1
---	--------------------------	----------------------------



7	W5 Seam (overlock). dislocation (Automatic translation)	MINOR Items affected: 1
---	--	----------------------------



CHECKPOINTS: 27

1	Factory details	
---	-----------------	-------------


1.1	Factory name at the location for QC (not supplier name)	OK
-----	---	----

Factory Name:

义乌市萌萱贸易有限公司

Factory Address:

浙江省金华市义乌市柳青路1565号



2	Quantity Check	
---	----------------	-------------

2.1	Warehouse / carton piled view	OK
-----	-------------------------------	----



2.2	Production quantity match PO	OK
	Bulk order quantity: 1398 units Bulk packing quantity: 1398 units (Automatic translation)	



3	Product	
---	---------	-------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
-----	--	----











3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----

OS: (1398)

Barcode can be scanned	OK
Scanned barcode	5715681048788
Barcode from order data	5715681048788
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681048795
Barcode from order data	
Scanned format	EAN_13






3.3	Embroidery / Printing check	OK
-----	-----------------------------	----



3.4	Lace / Trimming / Accessories check	OK
-----	-------------------------------------	----



3.5	Workmanship	
-----	-------------	--

3.6	Measurement	OK
-----	-------------	----

Measurement-OS	Specification	Tolerance	Actual
A: WIDTH (cm)	15.00	-	0
B: DEPTH (cm)	4.50	-	-0.2


C: STRAP LENGTH (cm)	74.00	-	-0.5
----------------------	-------	---	------



4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
-----	-----------	----



4.3	Smell check	OK
-----	-------------	----



4.4	Humidity check	
-----	----------------	--

4.5	Garment weight (sweater only)	
-----	-------------------------------	--

4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
-----	--	----




4.8	Sharp edges check	OK
-----	-------------------	----



4.9	摔箱测试	OK
-----	------	----



4.10	珠片脱落测试	OK
------	--------	----




5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
-----	---	----






Confirmation sample provided by the factory



Barcode Lookup Table



5.2	Export carton (shipping mark, barcode)	OK
-----	--	----

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	60
W	-	-	36
H	-	-	35
Gross Weight	-	-	7





COMMENTS

QC-JOJO Chen Inspector's conclusion Sep 23, 2026 06:52

Reasons for rejection in bulk orders:

1. Excessive dirt on the lining, covering approximately 20%-30% of the bag; stitched-in care labels; needle holes; glue residue on care labels.
2. Uneven width of the 4.5cm height strip; uneven width of exposed zippers and webbing; serious issues will result in rejection.
3. Loose threads and debris inside the bag must be cleaned.
4. Bags with exposed sequins will not be accepted.

All of the above issues require rework; each bag must be carefully inspected.
