



Inspection report, Final: PO003459

KS106366-NAVY BLAZER: ALL I WISH FOR - JEWELRY



[Online report](#)

1st inspection

Inspector	Sunny Chen	Inspection Date	Jun 12, 2026
Sample Qty	80	Order Qty	804
Location	29° 21' 13" N x 120° 3' 48" E	Checklist Name	Final
Planned Date	Jun 12, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Rejected	The bulk order failed final inspection. The following issues require revision: 1. The protective film on the lens is not applied evenly. Whether the film needs a warning label must be confirmed with the customer. 2. The mirror's edges are protruding and sharp, easily scratching fingers. The mirror should be completely recessed. 3. Excessive glue penetration and glue residue around the mirror inside the jewelry box are unacceptable. 4. The Batch No. 062026 on the cardboard box is correct, but the Batch No. 012026 on the barcode sticker is incorrect. Please confirm with the customer. (Automatic translation)
----------------------	-----------------	---

SUMMARY

	PO003459:KS106366-NAVY BLAZER
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	1
4 On-site Test	
5 Pack and Packaging	
5.2 Export carton (shipping mark, barcode)	2

- The protective film on the lenses is not applied evenly;

whether the film needs a warning label needs to be confirmed with the customer.

Uneven film on mirrors is a common phenomenon.
- The Batch No. 062026 on the carton is correct. The Batch No. 012026 on the barcode sticker is incorrect. Please confirm with the customer.

Outer box shape

Front box label

Side box markings


The Batch No. on the barcode sticker is incorrect. Please confirm with the customer.

	CRITICAL	MAJOR	MINOR
F1 Soiling/stains.	-	7	-


WX Other.	-	7	-
WX Other.	-	2	-
P7 Incorrect packaging.	-	-	General Defect
W1 Threads, untrimmed.	-	-	1
TOTAL	0	16	1
AQL MAX	0	5	7

DEFECTS: 17


1	F1 Soiling/stains. There was a lot of glue residue around the mirror inside the jewelry box. (Automatic translation)	MAJOR Items affected: 7
---	---	---



2	WX Other. The sharp edges of the mirror can easily scratch your fingers. (Automatic translation)	MAJOR Items affected: 7
---	---	---




3	WX Other. glue (Automatic translation)	MAJOR Items affected: 2
---	---	---



4	P7 Incorrect packaging. Uneven mirror film (Automatic translation)	MINOR General Defect
---	---	--



5	W1 Threads, untrimmed. -	MINOR Items affected: 1
---	--------------------------	---



CHECKPOINTS: 24

1	Factory details	
1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:

义乌市萌萱贸易有限公司

Factory Address:

浙江省 义乌市 柳青路1565号



workshop



workshop

2	Quantity Check	
---	----------------	-------------

2.1	Warehouse / carton piled view	OK
	Factory box yield rate: 85% (Automatic translation)	



Stacked container photos



Stacked container photos




Box Photo

2.2	Production quantity match PO	OK
	Number of orders: 804 pieces Packing list: 806 pieces Overstock: 2 pieces (Automatic translation)	



Order



Packing list

3	Product	
---	---------	--

3.1	Product compare against approved sample / color swatch/TECH file	OK
	The bulk order is OK compared with the confirmed sample provided by the factory. (Automatic translation)	





3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----

OS: (804)

Barcode can be scanned	OK
Scanned barcode	5715681362075
Barcode from order data	5715681362075
Scanned format	EAN_13

Size: KSOS

Barcode can be scanned	OK
Scanned barcode	5715681362082
Barcode from order data	
Scanned format	EAN_13



front of the cardboard box



Back of the cardboard box



Front of the cardboard box




Back of the cardboard box



Left side of the cardboard box



Right side of the cardboard box



Instruction Manual 1



Instruction Manual 2



Main title, position: lower-middle of the back center



The KS logo is located 1 cm directly below the mirror inside the jewelry box lid.

3.3	Embroidery / Printing check
-----	-----------------------------

3.4	Lace / Trimming / Accessories check
-----	-------------------------------------

3.5	Workmanship	Not OK
-----	-------------	--------



The protective film on the lenses is not applied evenly;

whether the film needs a warning label needs to be confirmed with the customer.



Uneven film on mirrors is a common phenomenon.



3.6	Measurement	OK
	Necklace: 39cm Bracelet: 14cm Ring inner diameter: 1.5cm (Automatic translation)	

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
	Large cargo tensile strength test OK (Automatic translation)	




4.3	Smell check	OK
	The artificial olfactory odor test was OK; there was no pungent odor, which is acceptable. (Automatic translation)	



4.4	Humidity check
-----	----------------

4.5	Garment weight (sweater only)
-----	-------------------------------

4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK
	Correctly packaged cardboard boxes (Automatic translation)	



Outer box shape



5	Pack and Packaging	
---	--------------------	---


5.1	Approved sample/QA file available during inspection	OK
	There are confirmation samples, orders, and packing lists provided by the factory. (Automatic translation)	



Confirmation sample provided by the factory




Confirmation sample provided by the factory



Barcode data



Order



Packing list

5.2	Export carton (shipping mark, barcode)	Pending
	The Batch No. 062026 on the carton is correct. The Batch No. 012026 on the barcode sticker is incorrect. Please confirm with the customer. (Automatic translation)	


Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



Outer box shape



Front box label



Side box markings



The Batch No. on the barcode sticker is incorrect. Please confirm with the customer.

5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----


	Specification	Tolerance	Actual
L	-	-	44.5
W	-	-	40
H	-	-	39.5
Gross Weight	-	-	12.6



Carton length



width




high



Gross weight

5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK
	The quantity per carton is based on the packing list provided by the factory; each carton contains 36 pieces (6 Colli boxes * 6). (Automatic translation)	



Packing list



Outer box shape



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
	Whether a warning label is required on the mirrored transparent film of the jewelry box needs to be confirmed with the customer. (Automatic translation)	




Colli packaging box front



Colli inner packaging 6 pieces



Single-piece cardboard box packaging



Back of the cardboard box



The jewelry box contains an instruction manual, a necklace, a bracelet, and two sets of rings (one blue and one red).



Jewelry box set



Back of foam



The mirror surface has a thin film.

5.6	Hanger (quality, size etc)
-----	----------------------------

5.7	Header card
-----	-------------

5.8	Products are in polybags
	No plastic bag packaging (Automatic translation)



Single-piece cardboard box packaging



The jewelry box contains an instruction manual, a necklace, a bracelet, and two sets of rings (one blue and one red).

COMMENTS

Sunny Chen Jun 14, 2026 12:57

Re-inspection scheduled

Sunny Chen Inspector's conclusion Jun 12, 2026 10:06

The bulk order failed final inspection. The following issues require revision:

- 1. The protective film on the lens is not applied evenly.
Whether the film needs a warning label must be confirmed with the customer.
- 2. The mirror's edges are protruding and sharp, easily scratching fingers. The mirror should be completely recessed.
- 3. Excessive glue penetration and glue residue around the mirror inside the jewelry box are unacceptable.
- 4. The Batch No. 062026 on the cardboard box is correct, but the Batch No. 012026 on the barcode sticker is incorrect. Please confirm with the customer.