



Inspection report, Final: PO003459

KS105936-CERISE GLITTER PINK: CAT WALLET



[Online report](#)

Inspector	Nya Ni	Inspection Date	Jun 30, 2026
Sample Qty	80	Order Qty	1068
Location	29° 16' 6" N x 120° 11' 36" E	Checklist Name	Final
Planned Date	Jun 29, 2026	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved
----------------------	----------

SUMMARY

	PO003459:KS105936-CERISE GLITTER PINK
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
W7 Seam slippage.	-	1	-
W1 Threads, untrimmed.	-	-	4
TOTAL	0	1	4
AQL MAX	0	5	7

DEFECTS: 5

1	W7 Seam slippage. -	MAJOR Items affected: 1
---	---------------------	----------------------------



2	W1 Threads, untrimmed. -	MINOR Items affected: 4
---	--------------------------	----------------------------



CHECKPOINTS: 25



1	Factory details
---	-----------------

1.1	Factory name at the location for QC (not supplier name)
-----	---

Factory Name:

浙江东阳创希皮具有限公司

Factory Address:



2	Quantity Check	
---	----------------	-------------

2.1	Warehouse / carton piled view	OK
-----	-------------------------------	----



2.2	Production quantity match PO	OK
-----	------------------------------	----



The factory provides order details: 168 pieces.

3	Product	
---	---------	-------------

3.1	Product compare against approved sample / color swatch/TECH file	OK
-----	--	----



3.2	Labelling (hangtag, main label, size label, care label, tracking label)	OK
-----	---	----

OS: (1068)

Barcode can be scanned	OK
Scanned barcode	5715681359723
Barcode from order data	5715681359723
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681359730
Barcode from order data	
Scanned format	EAN_13




Flag inspection





3.3	Embroidery / Printing check	OK
-----	-----------------------------	----



3.4	Lace / Trimming / Accessories check	OK
-----	-------------------------------------	----



3.5	Workmanship	
-----	-------------	--

3.6	Measurement	OK
-----	-------------	----

	Specification	Tolerance	Actual
	-	-	



Length 11cm



Width 8cm




High 2.5cm

4	On-site Test	
---	--------------	------------------------

4.1	Metal detection
-----	-----------------

4.2	Pull test	OK
-----	-----------	----




4.3	Smell check
-----	-------------



4.4	Humidity check
-----	----------------

4.5	Garment weight (sweater only)
-----	-------------------------------

4.6	Prove of color fastness test from supplier	OK
-----	--	----



4.7	Shrinkage test - prove from supplier	OK
-----	--------------------------------------	----



4.8	The product is packed in poly bag or carton. Supplier can't send products without packaging.	
-----	--	--



5	Pack and Packaging	
---	--------------------	------------------------

5.1	Approved sample/QA file available during inspection	OK
-----	---	----




The factory provides inspection samples.




5.2	Export carton (shipping mark, barcode)	OK
-----	--	----

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



5.3	Export carton (dimension, weight)	OK
-----	-----------------------------------	----

	Specification	Tolerance	Actual
L	-	-	30
W	-	-	27
H	-	-	20
Gross Weight	-	-	3.95



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	
-----	--	--



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK
-----	---	----



5.6	Hanger (quality, size etc)	
5.7	Header card	
5.8	Products are in polybags	OK

