Inspection report, Final: PO001943

KS103255-MULTI: DREAMY RING SET 14 PCS

Online report

2nd inspection

Inspector	QC-JOJO Chen	Inspection Date	Jul 04, 2025
Sample Qty	80	Order Qty	1002
Location	29° 21' 11" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Jul 04, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO001943:KS103255-MULTI
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
WX Other.	-	2	-
A18 Glue Marks.	-	-	2
P11 Cardboard.	-	-	1
A15 Unmatched checks / stripes.	-	-	1
TOTAL	**0**	**2**	**4**
AQL MAX	**0**	**5**	**7**

DEFECTS: 6

1	**WX Other. Drill Falling (Automatic translation)**	MAJOR Items affected: 2

2	A18 Glue Marks. The edge of the love box is warped (Automatic translation)	MINOR Items affected: 2

3	P11 Cardboard. The outer box has a hole and needs to be replaced (Automatic translation)	MINOR Items affected: 1

4	A15 Unmatched checks / stripes. The ring face does not match the base (Automatic translation)	MINOR Items affected: 1

CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name: 义乌萌萱贸易有限公司

Factory Address: 浙江省金华市义乌市柳青路 1565 号

2	**Quantity Check**	

2.1	**Warehouse / carton piled view**	**OK**

2.2	**Production quantity match PO**	**OK**
	Number of bulk orders: 1002 sets Number of bulk packings: 1002 sets (Automatic translation)	





3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**

3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

Barcode can be scanned	OK
Scanned barcode	5715681074572

Barcode from order data	
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681067321
Barcode from order data	
Scanned format	EAN_13







3.3	**Embriodery / Printing check**	**OK**

3.4	**Lace / Trimming / Accessories check**	**OK**

3.5	Workmanship

3.6	Measurement	OK

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK



4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK

4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

Confirmation sample provided by the factory

5.2	Export carton (shipping mark, barcode)	OK

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	



5.3	Export carton (dimension, weight)	OK

	Specification	Tolerance	Actual
L	-	-	51
W	-	-	50
H	-	-	44.5
Gross Weight	-	-	12.5

5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card