Inspection report, Final: PO002770

KS104716-GOLD: BUNNY BESTIE NECKLACE

Online report

Inspector	QC-JOJO Chen	Inspection Date	Sep 15, 2025
Sample Qty	125	Order Qty	2004
Location	29° 21' 13" N x 120° 3' 50" E	Checklist Name	Final
Planned Date	Sep 15, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO002770:KS104716-GOLD
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
F7 Damaged fabric.	-	1	-
F7 Damaged fabric.	-	-	2
F1 Soiling/stains.	-	-	2
TOTAL	**0**	**1**	**4**
AQL MAX	**0**	**7**	**10**

DEFECTS: 5

1	**F7 Damaged fabric. Cherry is not flat (Automatic translation)**	MAJOR Items affected: 1

2	F7 Damaged fabric. Uneven cherry surface (Automatic translation)	MINOR Items affected: 2

3	F1 Soiling/stains. -	MINOR Items affected: 2

CHECKPOINTS: 24

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌昊林饰品有限公司
Factory Address:	浙江省金华市义乌市柳青路 1569 号

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	**Production quantity match PO**	**OK**
	Bulk order quantity: 2004 sets Bulk packing quantity: 2004 sets (Automatic translation)	





3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**



3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

OS: (2004)

Barcode can be scanned	OK
Scanned barcode	5715681186824
Barcode from order data	5715681186824
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5715681186831

Barcode from order data	
Scanned format	EAN_13



3.3	Embriodery / Printing check	OK

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	OK

3.6	Measurement	OK

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK

4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

4.8	功能测试	OK



5	Pack and Packaging	

5.1	Approved sample/QA file available during inspection	OK

Confirmation sample provided by the factory

5.2	**Export carton (shipping mark, barcode)**	**OK**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	

5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	40
W	-	-	30
H	-	-	30
Gross Weight	-	-	12



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card	OK