Inspection report, Final: PO002818

KS102881-GOLD: 2 PACK CHERRY BESTIE BRACELETS

Online report

Inspector	QC-JOJO Chen	Inspection Date	Sep 15, 2025
Sample Qty	80	Order Qty	804
Location	29° 21' 13" N x 120° 3' 49" E	Checklist Name	Final
Planned Date	Sep 15, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved

SUMMARY

	PO002818:KS102881-GOLD
1 Factory details	
2 Quantity Check	
3 Product	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
F5 Coarse/thick Yarn.	-	-	2
F13 Scratch marks / cracks in surface.	-	-	1
TOTAL	**0**	**0**	**3**
AQL MAX	**0**	**5**	**7**

DEFECTS: 3

1	**F5 Coarse/thick Yarn. Rough edges (Automatic translation)**	MINOR Items affected: 2

2	F13 Scratch marks / cracks in surface. Scratches on the surface (Automatic translation)	MINOR Items affected: 1

CHECKPOINTS: 24

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌昊林饰品有限公司
Factory Address:	浙江省金华市义乌市柳青路 1569 号

2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	**Production quantity match PO**	**OK**
	Bulk order quantity: 804 cartons Bulk order quantity: 804 cartons (Automatic translation)	





3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**

3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

OS: (804)

Barcode can be scanned	OK

Scanned barcode	5715681042663
Barcode from order data	5715681042663
Scanned format	EAN_13

Barcode can be scanned	OK
Scanned barcode	5575681042670
Barcode from order data	
Scanned format	EAN_13

3.3	**Embriodery / Printing check**	**OK**

3.4	**Lace / Trimming / Accessories check**

3.5	**Workmanship**	**OK**

3.6	Measurement	OK

	Specification	Tolerance	Actual
	-	-	

The length of the bulk goods is the same as the confirmed sample

4	On-site Test	

4.1	Metal detection

4.2	Pull test	OK



4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK





4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK



4.8	功能测试	OK



5	**Pack and Packaging**	

5.1	**Approved sample/QA file available during inspection**	**OK**

Confirmation sample provided by the factory



5.2	**Export carton (shipping mark, barcode)**	**OK**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	

5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	40
W	-	-	30
H	-	-	30

Gross Weight	-	-	8.4



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK

5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK

5.6	Hanger (quality, size etc)

5.7	Header card	OK