Inspection report, Final: PO002770

KS104809-MULTI: FANS DISPLAY 30 PCS

Online report

Inspector	Wing Xu	Inspection Date	-
Sample Qty	125	Order Qty	2160
Location	29° 21' 12" N x 120° 3' 47" E	Checklist Name	Final
Planned Date	Oct 09, 2025	Sampling Method	AQL 2.5/4 Level II
Supplier Name	10 FASHION		

Inspector Conclusion	Approved	

Status: **Pending**

SUMMARY

	PO002770:KS104809-MULTI
1 Factory details	
2 Quantity Check	
3 Product	
3.5 Workmanship	
4 On-site Test	
5 Pack and Packaging	

	CRITICAL	MAJOR	MINOR
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
M5 Damaged fabric / material.	-	-	1
TOTAL	**0**	**0**	**3**
AQL MAX	**0**	**7**	**10**

DEFECTS: 3

1	**M5 Damaged fabric / material. exposed edge**	MINOR Items affected: 1



2	M5 Damaged fabric / material. exposed edge	MINOR Items affected: 1



3	M5 Damaged fabric / material. burrs	MINOR Items affected: 1



CHECKPOINTS: 23

1	Factory details	

1.1	Factory name at the location for QC (not supplier name)	OK

Factory Name:	义乌萌宣贸易有限公司
Factory Address:	浙江省金华市义乌市柳青路 1565 号



2	Quantity Check	

2.1	Warehouse / carton piled view	OK

2.2	**Production quantity match PO**	**OK**
	products finished 100%	

3	**Product**	

3.1	**Product compare against approved sample / color swatch/TECH file**	**OK**



3.2	**Labelling (hangtag, main label, size label, care label, tracking label)**	**OK**

OS: (2160)

Barcode can be scanned	OK
Scanned barcode	5715681194867
Barcode from order data	5715681194867
Scanned format	EAN_13

product

Barcode can be scanned	OK
Scanned barcode	5715681194874
Barcode from order data	
Scanned format	EAN_13



3.3	Embriodery / Printing check

3.4	Lace / Trimming / Accessories check

3.5	Workmanship	Not OK

DEFECT M5 Damaged fabric / material. exposed edge

MINOR
Items affected: 1



DEFECT M5 Damaged fabric / material. exposed edge

MINOR
Items affected: 1

DEFECT M5 Damaged fabric / material. burrs

MINOR
Items affected: 1



3.6	Measurement

	Specification	Tolerance	Actual
	-	-	

4	On-site Test	

4.1	Metal detection

4.2	Pull test

4.3	Smell check	OK

4.4	Humidity check

4.5	Garment weight (sweater only)

4.6	Prove of color fastness test from supplier	OK



4.7	The product is packed in poly bag or carton. Supplier can't send products without packaging.	OK

5	**Pack and Packaging**	

5.1	**Approved sample/QA file available during inspection**	**OK**

5.2	**Export carton (shipping mark, barcode)**	**OK**

Barcode can be scanned	
Scanned barcode	
Barcode from order data	
Scanned format	

5.3	**Export carton (dimension, weight)**	**OK**

	Specification	Tolerance	Actual
L	-	-	54
W	-	-	50
H	-	-	30
Gross Weight	-	-	9



5.4	Carton Packing (quantity, ratio etc), 3 ply carton	OK



5.5	Inner package (polybag, sticker, tissue paper, silica gel etc)	OK





5.6	**Hanger (quality, size etc)**

5.7	**Header card**