Fastener torque audit, Z01, 2024-02-07

Document number	INS-Z01-20240207-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Ines Sorrel
Approved by	-
Date	2024-02-07

Inspection type	Fastener torque audit
Zone	Z01
Date	2024-02-07
Inspector	Ines Sorrel
Number of findings	7

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Sealant gap	Deck 41, frame 302	Major	Clean and re-apply sealant; leak check.	2024-03-08
F-02	Damaged insulation	Deck 35, frame 192	Minor	Replace insulation segment.	2024-03-08
F-03	Incorrect torque	Deck 61, frame 140	Minor	Re-torque to drawing value.	2024-02-14
F-04	Corrosion spot	Deck 66, frame 22	Minor	Treat and re-coat the area.	2024-02-10
F-05	Incorrect torque	Deck 19, frame 272	Major	Re-torque to drawing value.	2024-03-08
F-06	Damaged insulation	Deck 82, frame 184	Major	Replace insulation segment.	2024-02-10
F-07	Incorrect torque	Deck 42, frame 291	Major	Re-torque to drawing value.	2024-02-14

Assessment

No critical findings. Release after the actions are closed.