# Fastener torque audit, Z01, 2024-09-25

| | |
|---|---|
| Document number | INS-Z01-20240925-1 |
| Revision | 1 |
| Status | APPROVED |
| Classification | CONFIDENTIAL |
| Author | Nadia Dravis |
| Approved by | - |
| Date | 2024-09-25 |

| | |
|---|---|
| Inspection type | Fastener torque audit |
| Zone | Z01 |
| Date | 2024-09-25 |
| Inspector | Nadia Dravis |
| Number of findings | 7 |

## Findings

| ID | Finding | Location | Severity | Action | Due |
|---|---|---|---|---|---|
| F-01 | Incorrect torque | Deck 80, frame 260 | Minor | Re-torque to drawing value. | 2024-10-09 |
| F-02 | Damaged insulation | Deck 11, frame 290 | Minor | Replace insulation segment. | 2024-10-25 |
| F-03 | Damaged insulation | Deck 42, frame 16 | Minor | Replace insulation segment. | 2024-09-28 |
| F-04 | Sealant gap | Deck 34, frame 56 | Major | Clean and re-apply sealant; leak check. | 2024-10-25 |
| F-05 | Plate misalignment at seam | Deck 83, frame 258 | Minor | Re-shim and re-torque the seam. | 2024-10-09 |
| F-06 | Damaged insulation | Deck 10, frame 221 | Minor | Replace insulation segment. | 2024-10-09 |
| F-07 | Sealant gap | Deck 40, frame 140 | Major | Clean and re-apply sealant; leak check. | 2024-10-09 |

## Assessment

No critical findings. Release after the actions are closed.