Conduit routing inspection, Z07, 2025-07-08

Document number	INS-Z07-20250708-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Hollis Fairholm
Approved by	-
Date	2025-07-08

Inspection type	Conduit routing inspection
Zone	Z07
Date	2025-07-08
Inspector	Hollis Fairholm
Number of findings	3

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Weld porosity	Deck 79, frame 298	Minor	Grind out and re-weld; repeat inspection.	2025-07-11
F-02	Damaged insulation	Deck 11, frame 283	Minor	Replace insulation segment.	2025-07-11
F-03	Sealant gap	Deck 18, frame 234	Major	Clean and re-apply sealant; leak check.	2025-07-11

Assessment

No critical findings. Release after the actions are closed.