Hull plating fit-up inspection, Z17, 2025-08-25

Document number	INS-Z17-20250825-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Leda Thorne
Approved by	-
Date	2025-08-25

Inspection type	Hull plating fit-up inspection
Zone	Z17
Date	2025-08-25
Inspector	Leda Thorne
Number of findings	6

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Damaged insulation	Deck 57, frame 72	Minor	Replace insulation segment.	2025-09-24
F-02	Missing fastener	Deck 19, frame 63	Minor	Install fastener per drawing and record torque.	2025-09-08
F-03	Incorrect torque	Deck 64, frame 206	Minor	Re-torque to drawing value.	2025-09-08
F-04	Missing fastener	Deck 83, frame 199	Minor	Install fastener per drawing and record torque.	2025-09-24
F-05	Sealant gap	Deck 6, frame 107	Major	Clean and re-apply sealant; leak check.	2025-09-01
F-06	Incorrect torque	Deck 60, frame 305	Minor	Re-torque to drawing value.	2025-09-01

Assessment

No critical findings. Release after the actions are closed.