Hull plating fit-up inspection, Z17, 2026-03-12

Document number	INS-Z17-20260312-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Rhett Bailin
Approved by	-
Date	2026-03-12

Inspection type	Hull plating fit-up inspection
Zone	Z17
Date	2026-03-12
Inspector	Rhett Bailin
Number of findings	5

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Plate misalignment at seam	Deck 81, frame 154	Minor	Re-shim and re-torque the seam.	2026-03-19
F-02	Damaged insulation	Deck 71, frame 176	Minor	Replace insulation segment.	2026-03-15
F-03	Conduit chafing	Deck 52, frame 328	Major	Add protective sleeve and re-route.	2026-03-19
F-04	Damaged insulation	Deck 63, frame 340	Minor	Replace insulation segment.	2026-03-19
F-05	Conduit chafing	Deck 39, frame 187	Minor	Add protective sleeve and re-route.	2026-03-26

Assessment

No critical findings. Release after the actions are closed.