Hull plating fit-up inspection, Z20, 2024-05-05

Document number	INS-Z20-20240505-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Leda Thorne
Approved by	-
Date	2024-05-05

Inspection type	Hull plating fit-up inspection
Zone	Z20
Date	2024-05-05
Inspector	Leda Thorne
Number of findings	7

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Incorrect torque	Deck 22, frame 229	Minor	Re-torque to drawing value.	2024-06-04
F-02	Plate misalignment at seam	Deck 6, frame 197	Major	Re-shim and re-torque the seam.	2024-05-08
F-03	Weld porosity	Deck 18, frame 114	Critical	Grind out and re-weld; repeat inspection.	2024-05-19
F-04	Weld porosity	Deck 34, frame 4	Major	Grind out and re-weld; repeat inspection.	2024-06-04
F-05	Plate misalignment at seam	Deck 48, frame 329	Minor	Re-shim and re-torque the seam.	2024-05-12
F-06	Weld porosity	Deck 5, frame 220	Major	Grind out and re-weld; repeat inspection.	2024-05-08
F-07	Weld porosity	Deck 35, frame 360	Minor	Grind out and re-weld; repeat inspection.	2024-05-12

Assessment

1 critical findings; non-conformance reports raised.