Hull plating fit-up inspection, Z20, 2025-03-12

Document number	INS-Z20-20250312-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Calla Embry
Approved by	-
Date	2025-03-12

Inspection type	Hull plating fit-up inspection
Zone	Z20
Date	2025-03-12
Inspector	Calla Embry
Number of findings	5

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Incorrect torque	Deck 1, frame 124	Minor	Re-torque to drawing value.	2025-03-19
F-02	Weld porosity	Deck 52, frame 350	Minor	Grind out and re-weld; repeat inspection.	2025-03-26
F-03	Missing fastener	Deck 7, frame 135	Major	Install fastener per drawing and record torque.	2025-03-26
F-04	Conduit chafing	Deck 36, frame 51	Major	Add protective sleeve and re-route.	2025-03-15
F-05	Damaged insulation	Deck 8, frame 216	Minor	Replace insulation segment.	2025-03-19

Assessment

No critical findings. Release after the actions are closed.