Hull plating fit-up inspection, Z20, 2025-08-28

Document number	INS-Z20-20250828-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Aven Avrane
Approved by	-
Date	2025-08-28

Inspection type	Hull plating fit-up inspection
Zone	Z20
Date	2025-08-28
Inspector	Aven Avrane
Number of findings	6

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Damaged insulation	Deck 83, frame 248	Minor	Replace insulation segment.	2025-09-27
F-02	Corrosion spot	Deck 54, frame 155	Minor	Treat and re-coat the area.	2025-09-11
F-03	Incorrect torque	Deck 76, frame 31	Minor	Re-torque to drawing value.	2025-08-31
F-04	Missing fastener	Deck 55, frame 199	Major	Install fastener per drawing and record torque.	2025-09-11
F-05	Missing fastener	Deck 71, frame 220	Minor	Install fastener per drawing and record torque.	2025-09-27
F-06	Weld porosity	Deck 37, frame 87	Minor	Grind out and re-weld; repeat inspection.	2025-09-04

Assessment

No critical findings. Release after the actions are closed.