Conduit routing inspection, Z20, 2026-06-30

Document number	INS-Z20-20260630-1
Revision	1
Status	APPROVED
Classification	INTERNAL
Author	Merrin Greaves
Approved by	-
Date	2026-06-30

Inspection type	Conduit routing inspection
Zone	Z20
Date	2026-06-30
Inspector	Merrin Greaves
Number of findings	5

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Damaged insulation	Deck 83, frame 6	Major	Replace insulation segment.	2026-07-14
F-02	Missing fastener	Deck 13, frame 175	Minor	Install fastener per drawing and record torque.	2026-07-07
F-03	Sealant gap	Deck 17, frame 18	Minor	Clean and re-apply sealant; leak check.	2026-07-14
F-04	Conduit chafing	Deck 17, frame 171	Minor	Add protective sleeve and re-route.	2026-07-07
F-05	Sealant gap	Deck 34, frame 186	Minor	Clean and re-apply sealant; leak check.	2026-07-03

Assessment

No critical findings. Release after the actions are closed.