Pressure seal inspection, Z22, 2026-07-08

Document number	INS-Z22-20260708-1
Revision	1
Status	APPROVED
Classification	CONFIDENTIAL
Author	Rhosa Ancel
Approved by	-
Date	2026-07-08

Inspection type	Pressure seal inspection
Zone	Z22
Date	2026-07-08
Inspector	Rhosa Ancel
Number of findings	8

Findings

ID	Finding	Location	Severity	Action	Due
F-01	Sealant gap	Deck 69, frame 190	Minor	Clean and re-apply sealant; leak check.	2026-08-07
F-02	Missing fastener	Deck 4, frame 246	Minor	Install fastener per drawing and record torque.	2026-07-15
F-03	Sealant gap	Deck 41, frame 30	Minor	Clean and re-apply sealant; leak check.	2026-07-11
F-04	Incorrect torque	Deck 5, frame 46	Minor	Re-torque to drawing value.	2026-07-15
F-05	Missing fastener	Deck 65, frame 264	Minor	Install fastener per drawing and record torque.	2026-08-07
F-06	Missing fastener	Deck 21, frame 246	Minor	Install fastener per drawing and record torque.	2026-07-22
F-07	Incorrect torque	Deck 56, frame 326	Major	Re-torque to drawing value.	2026-07-11
F-08	Damaged insulation	Deck 41, frame 337	Minor	Replace insulation segment.	2026-08-07

Assessment

No critical findings. Release after the actions are closed.